## **FINAL**

# Remedial Action Report CW-7 PCB Site

U. S. Army Garrison Fort Monmouth Fort Monmouth, New Jersey



**Directorate of Public Works** 



August 3, 2004



Contract No. DACA51-98-D-0006 Delivery Order No. 0019

## **United States Army**

Fort Monmouth, New Jersey

## **CW-7 PCB Site Remedial Action Report**

Fort Monmouth, New Jersey

#### PREPARED BY:



### 201 GIBRALTAR ROAD, SUITE 100 HORSHAM, PA 19044

August 3, 2004

VERSAR PROJECT NO. 4435.034



## **TABLE OF CONTENTS**

<b>EXECU</b>	TIVE SUMMARY	i
1.0.INT	RODUCTION	1-1
1.1	Objectives	1-1
1.2	Report Organization	1-1
2.0.SITE	E BACKGROUND AND ENVIRONMENTAL SETTING	
2.1	Site Location and Description.	
2.2	Site Background	
2.3		
	.3.1 Regional and Local Geology	
	.3.2 Hydrogeology	
	.3.3 Soils	
	.3.4 Topography and Surface Drainage	
	MEDIAL ACTION ACTIVITIES	
3.1	Delineation Sampling.	3-1
3	.1.1 Sampling Process	
	.1.2 Delineation Results	
3.2	Remedial Activities	
3.3	UST Closure Activities	3-5
3.4	Schedule of Site Activities	3-5
3.5	Compliance Averaging	
4.0.FINI	DINGS/REMEDIAL ACTIONS	
4.1	Remedial Action Effectiveness.	
4.2	Soil Disposal	
4.3	Recommendations	
5.0 REF	ERENCES	<i>5</i> 1



#### **TABLES**

Table 1 PCB Sampling Results – May 28 to 30, 1996
 Table 2 Post Excavation Soil Sampling – PCB Data Summary, November 19-25, 1997
 Table 3 Additional Soil Investigation – PCB Delineation, January 27, 1998
 Table 4 Post Excavation Soil Sampling – PCB Data Summary, February 9-10, 1998
 Table 5 Underground Storage Tank - Post Excavation Samples, TPHC Data Summary
 Table 6 Soil Stockpile - Waste Characterization

#### **FIGURES**

Figure 1	Site Location Map
Figure 2	Site Map
Figure 3	Geologic Map of New Jersey
Figure 4	Soils Map of Monmouth County
Figure 5	Estimated Extent of PCB Contamination, Building 2000 – Charles Wood Area
Figure 6 Figure 7	Post-Excavation Sample Locations and PCB Analytical Results Underground Storage Tank and Post-Excavation Sample Locations

#### **APPENDICES**

Appendix A	Fort Monmouth – DPW Decision Document CW-7 (Former PCB
	Class Transformer CW035) Site
Appendix B	PCB Transformer Section in the Weston (1995) Site
	Investigation Report
Appendix C	ENSYS, Inc. PCB RISc® Soil Test System User's Guide
Appendix D	PCB RISc® Soil Test Field Screening Data, May – June 1996
Appendix E	Analytical Laboratory Data – PCB Confirmation, June 1996
Appendix F	Backfill Material Receipts – Sand and Stone
Appendix G	Site Health and Safety Plan
Appendix H	Post-Excavation Soil Analytical Data Packages
Appendix I	UST Disposal Documentation
Appendix J	Soil Stockpile – Waste Characterization Analytical Data Package
Appendix K	Hazardous and Non-Hazardous Waste Manifests and Soil Disposal
	Certificates



#### **EXECUTIVE SUMMARY**

This Remedial Action Report (RAR) presents a compilation, prepared by VERSAR, Inc. (VERSAR), of the results of the remedial action conducted by the United States (U.S.) Army Garrison Fort Monmouth, New Jersey (Fort Monmouth) – Directorate of Public Works (DPW) at Site CW-7. Site CW-7 is the location of former polychlorinated biphenyl (PCB) Transformer CW035 that was associated with Building 2000, the Officer's Club in the Charles Wood Area of Fort Monmouth. The objective of the remedial action was to remove all PCB impacted soils to the established regulatory limit and perform confirmatory sampling. VERSAR has developed this RAR based on the activities performed and the results of the remedial action.

The former locations of PCB transformers at Fort Monmouth were inspected for evidence of spills during performance of the 1993 site investigation (SI) conducted by Roy F. Weston, Inc. (WESTON). Transformer CW035 had been formerly located on a concrete pad, near the northeast entrance of the Officers' Club building (Building 2000) and the concrete pad location, designated as Site CW-7, was one of the areas sampled. At the time of sampling for the SI, the concrete pad had been removed; therefore four soil samples were collected downgradient of the former concrete pad and transformer location. PCBs were detected above the State of New Jersey Department of Environmental Protection (NJDEP) Residential Direct Contact Soil Cleanup Criteria (RDCSCC) or 0.49 mg/Kg for PCBs in soil of 0.49 mg/Kg in each of the four samples. As a result of the findings of the SI, a Decision Document was prepared by the DPW and submitted to the NJDEP describing the selected remedial alternative for Site CW-7. The selected remedial alternative encompassed excavation and offsite disposal of an estimated 410 cubic yards of contaminated soil. Excavation was determined to be the most cost effective approach for eliminating the identified contaminant of concern (i.e., PCBs) at the site and to achieve the respective NJDEP RDCSCC for PCBs in soil (0.49 mg/Kg). The NJDEP reviewed and approved the Decision Document on 1 July 1997.

In May 1996, a remedial investigation (RI) was conducted by TECOM – Vinnell Services (TVS) to delineate the horizontal and vertical extent of PCBs in soil at Site CW-7 in support of the planned remedial action. The RI used a combination of field screening techniques and laboratory analyses. A total of 67 soil samples were collected and screened in the field for PCBs. Sample locations revealing PCB concentrations above 0.49 mg/Kg were further delineated. The results of field screening showed that PCB soil contamination was primarily distributed in the area surrounding the former transformer pad location near Building 2000 and along a drainage swale that skirts the north side of Building 2000. Eight of the 67 samples (>10%) were submitted for laboratory analysis to confirm the PCB concentrations detected by field screening. The field screening and laboratory analytical results indicated a surface area encompassing approximately 3,000 square ft (ft2) within which PCB concentrations exceeded 0.49 mg/Kg. Within this area of impacted soil, PCB contamination ranged to a maximum depth of approximately 6 ft below ground surface. Based on the estimated surface area and varying depths of PCB concentrations detected above the RDCSCC, the site was divided into five areas (Areas 1 to 5) for soil excavation and removal.



Soil excavation and post-excavation sampling activities were then conducted between November 19 and 25, 1997. In evaluating the analytical results from the post-excavation sampling, it was determined that further delineation/excavation of PCB contaminated soils was required at Areas 1 and 2. However, the post-excavation sample results at Areas 3 and 4 were deemed appropriate for further evaluation using compliance averaging. Therefore, further delineation/excavation was not proposed at Areas 3 and 4. No further excavation/evaluation was required at Area 5. Further delineation and excavation efforts at Areas 1 and 2 were conducted through February 1998 where initial post-excavation sampling did not achieve the NJDEP RDCSCC for PCBs in soils. Post-excavation samples were again collected and analytical results indicated all samples to be below the NJDEP RDCSCC for PCBs in soil. The results of compliance averaging performed at Areas 3 and 4 concluded that the exceedences were considered marginal or represented de minimus quantities given the sample depth and the excavation efforts conducted and no further action was recommended.

During the course of the excavation activities, a 2,000-gallon No.2 fuel oil underground storage tank (UST) was encountered. The UST was cleaned out, removed and transported off-site for recycling to the Mazza & Sons, Inc., facility located in Tinton Falls, New Jersey. Six post-excavation soil samples were collected and submitted for Total Petroleum Hydrocarbons (TPHC) analysis. The sample results were either below the method detection limit (MDL) or below the NJDEP criteria for Total Organic Contaminants and the NJDEP Cleanup Criteria for Total Organic Contaminants.

A total of approximately 44 cubic yards of soil containing PCBs greater than 50 mg/Kg and 250 cubic yards of non-hazardous soil were excavated during the remedial action. All waste characterization analysis and disposal was handled by the DPW. The PCB soil (greater than 50 mg/Kg PCBs) was managed as a Toxic Substances Control Act (TSCA) waste and transported to for disposal at the Chemical Waste Management Facility located in Model City, New York. The remaining non-hazardous soil was transported to a thermal treatment facility in New Castle, Delaware.

The analytical results of the post-excavation soil sampling confirmed either that PCB contaminated soils had been excavated to the established remediation standard of 0.49 mg/Kg or that further evaluation and the results of compliance averaging concluded that the exceedences were considered marginal or represented de minimus quantities and no that further action is recommended. In addition, confirmatory sampling at the former UST location was below the NJDEP criteria for Total Organic Contaminants and the NJDEP Cleanup Criteria Total Organic Contaminants.

No further action is recommended in regard to Site CW-7.



#### 1.0 INTRODUCTION

Versar, Inc. (Versar) has been contracted by the United States (U.S.) Army Garrison, Fort Monmouth (Fort Monmouth), Directorate of Public Works (DPW), Fort Monmouth, New Jersey to prepare a Remedial Action Report (RAR) for the remedial activities conducted at the CW-7 polychlorinated biphenyl site located in Fort Monmouth. This report addresses the remedial activities performed at this site as of January 2001.

#### 1.1 Objectives

The objective of this RAR is to present the site remedial action process performed at the CW-7 site. The purpose of the remedial action was to excavate and dispose of the shallow soils impacted by metals in the vicinity of the water tank area. A Decision Document was prepared and submitted by the Fort Monmouth DPW in April 1996, which contains a description of the site and a summary of the risks and remedial alternatives. This document is provided in **Appendix A**. The remedial actions were conducted in accordance with New Jersey Department of Environmental Protection (NJDEP) Technical Requirements for Site Remediation, N.J.A.C. 7:26E, et al.

The remedial action encompassed the following:

- Excavating "hot spot" areas identified through sampling conducted from May 1996 through November 1997.
- Closure of an underground Storage Tank
- Characterizing soils for off-site disposal.
- Comparing the results of the sampling program with the NJDEP Residential Direct Contact Soil Cleanup Criteria (RDCSCC).
- Disposal of contaminated soil (conducted by the DPW).

#### 1.2 Report Organization

This report is organized to minimize repetition. **Section 2.0** provides background information and a general description of the CW-7 site located at Fort Monmouth, Charles Wood Area. **Section 3.0** describes and summarizes the characterization and delineation of contaminants, sampling procedures, and remedial activities conducted at the site. **Section 4.0** provides a summary of the remedial action effectiveness, soil disposal and cost summary.



#### 2.0 SITE BACKGROUND AND ENVIRONMENTAL SETTING

The following sections describe the site background and environmental setting of the area surrounding Fort Monmouth and the CW-7 site. Included is a description of the site location, background, current conditions, and environmental setting.

#### 2.1 Site Location and Description

Fort Monmouth is located in the central-eastern portion of New Jersey in Monmouth County, approximately 45 miles south of New York City and 70 miles northeast of Philadelphia (**Figure 1**). In addition to the Main Post, the installation includes two subposts, the Charles Wood Area and the Evans Area. The Main Post encompasses approximately 630 acres and is generally bounded by State Highway 35, Parkers Creek, Lafetra Brook, the New Jersey Transit Railroad, and a residential area to the south. The post was established in 1918 during World War I (WW I) as an Army Signal Corps training center. The Main Post currently provides administrative, training, and housing support functions, as well as providing many of the community facilities for Fort Monmouth. The primary mission of Fort Monmouth is to provide command, administrative, and logistical support for Headquarters, U.S. Army Communications and Electronics Command (CECOM). CECOM is a major subordinate command of the U.S. Army Materiel Command (AMC) and is the host tenant at Fort Monmouth.

The Charles Wood Area is composed of approximately 511 acres and is located 1 mile west of the Main Post. The Charles Wood Area is bounded by Tinton Avenue to the north, residential development and Pine Brook Road to the south, and the Garden State Parkway to the west. The Charles Wood Area is used primarily for research and development (R&D), and testing, and provides the greatest number of housing units available on-post.

Site CW-7, associated with Building 2000, is located in the Charles Wood area of Fort Monmouth. Building 2000 consists of a two-story building used for the Officers' Club. The Officers' Club is located on the same grounds as the Charles Wood golf course. A former transformer unit, CW035, was associated with Building 2000 until 1990. In 1989, during a post-wide site investigation, transformer CW035 was sampled and tested for PCB content. The sample results revealed a PCB level of 223,091 parts per million (ppm). The PCB Transformer (i.e., CW035) was removed from service on 10 September 1990 and shipped for offsite disposal on 24 September 1990. The former transformer location was then evaluated as part of the Site Investigation (SI) of Fort Monmouth. A site map is provided in **Figure 2.** 

#### 2.2 Site Background

Suspected hazardous waste sites at Fort Monmouth were initially identified in a report prepared by the U.S Army Toxic and Hazardous Materials Agency (USATHAMA) entitled: "Installation Assessment of Fort Monmouth. Report 171", dated May 1980. This report identified 37 sites with known or suspected waste materials on the Main Post and



the two subposts (Charles Wood and Evans Areas). Roy F. Weston, Inc. (WESTON) then conducted a background investigation on these sites and on eight additional sites, identified by Fort Monmouth and the NJDEP. As part of the 1993 background investigation (WESTON, 1993), all former locations of PCB transformers at the site were inspected for evidence of spills. All PCB transformers (i.e., containing greater than 500 ppm PCBs) had been removed, but the former locations of the transformers had not been investigated for spilled PCBs. On December 1 and 2, 1994, three transformer areas at Charles Wood were sampled. The transformer area sampling consisted of collecting concrete chips and soil samples from areas potentially impacted by leaking transformers. Soil samples were collected under the former location of pole-mounted transformers and on each side of former pad-mounted transformers. Concrete chip samples were taken at stained areas on the concrete pads or vault floors. The former location of Transformer CW035, near the northeast entrance of the Officers' Club building (Building 2000) was one of the areas sampled. Dark stains had been observed on an old concrete pad, approximately 4 feet (ft) by 6 ft in size. At the time of sampling, the concrete pad had been removed and four (4) soil samples were collected downgradient of the former pad location and the area was designated as Site CW-7. PCBs were detected above the NJDEP Residential Direct Contact Soil Cleanup Criteria (RDCSCC) of 0.49 milligrams/kilogram (mg/Kg) in each of the four samples collected downgradient of the former concrete pad and transformer location. The results of these investigation activities were presented in the WESTON Report entitled: "Final, Site Investigation, Fort Monmouth, New Jersey, Main Post and Charles Wood Areas, Site Investigation Report", December 1995. The Section from the SI report which discusses the site investigation activities at CW-7 Site is provided in **Appendix B**.

The recommendations of the WESTON SI Report for Site CW-7 were that additional samples be taken to further delineate the extent of contamination; the contaminated soil be removed and disposed of in accordance with applicable regulations; and confirmatory sampling be performed.

#### 2.3 Environmental Setting

The following is a description of the geological/hydrogeological setting of the area surrounding the CW-7 site. Included is a description of the regional geology of the area surrounding Fort Monmouth, as well as descriptions of the local geology and hydrogeology of the Main Post area.

#### 2.3.1 Regional and Local Geology

Monmouth County lies within the New Jersey Section of the Atlantic Coastal Plain physiographic province. The CW-7 site is located in what may be referred to as the Outer Coastal Plain subprovince, or the Outer Lowlands. The geologic map of New Jersey is provided as **Figure 3**.

In general, New Jersey Coastal Plain formations consist of a seaward-dipping wedge of unconsolidated deposits of clay, silt, sand and gravel. These formations typically strike

2-2



northeast-southwest with a dip ranging from 10 to 60 ft (ft) per mile and were deposited on Precambrian and lower Paleozoic rocks (Zapecza, 1989). These sediments, predominantly derived from deltaic, shallow marine, and continental shelf environments, date from Cretaceous through the Quaternary Periods. The mineralogy ranges from quartz to glauconite.

The formations record several major transgressive/regressive cycles and contain units, which are generally thicker to the southeast and reflect a deeper water environment. More than 20 regional geologic units are present within the sediments of the Coastal Plain. Regressive, upward coarsening deposits are usually aquifers (e.g., Englishtown and Kirkwood Formations, and the Cohansey Sand), while the transgressive deposits act as confining units (e.g., the Merchantville, Marshalltown, and Navesink Formations). The individual thickness for these units varies greatly (i.e., from several ft to several hundred ft). The Coastal Plain deposits thicken to the southeast from the Fall Line (i.e., a boundary zone between older, resistant rocks and younger, softer plain sediments) to greater than 6,500 ft in Cape May County (Brown and Zapecza, 1990).

Based on the regional geologic map (Jablonski, 1968), the Cretaceous age Red Bank and Tinton Sands outcrop at the Main Post area. The Red Bank Sand conformably overlies the Navesink Formation and dips to the southeast at 35 ft per mile. The upper member (Shrewsbury) of the Red Bank Sand is a yellowish-gray to reddish brown clayey, medium-to-coarse-grained sand that contains abundant rock fragments, minor mica and glauconite (Jablonski). The lower member (Sandy Hook) is a dark gray to black, medium-to-fine grained sand with abundant clay, mica, and glauconite.

The Tinton Sand conformably overlies the Red Bank Sand and ranges from a clayey medium to very coarse-grained feldspathic-quartz and glauconite-sand to a glauconitic-coarse sand. The color varies from dark yellowish orange or light brown to moderate brown and from light olive to grayish olive. Glauconite may constitute 60 to 80 percent of the sand fraction in the upper part of the unit (Minard, 1969). The upper part of the Tinton is often highly oxidized and iron oxide encrusted (Minard, 1969). Groundwater occurs beneath the site at a depth of approximately 1 to 2 feet bgs.

The Kirkwood Formation (part of the Kirkwood-Cohansey system) crops out southeast of the Main Post and dips to the southeast at a slope of 20 ft per mile (Jablonski, 1968). The Kirkwood Formation consists of alternating layers of sand and clay. The upper unit is a light gray to yellowish-brown, fine-grained quartz sand with quartz nodules and small pebbles. The lower unit is a brown silt in Monmouth County (Jablonski, 1968).

#### 2.3.2 Hydrogeology

Fort Monmouth lies in the Atlantic and Eastern Gulf Coastal Plain groundwater region (Meisler et al., 1988). This groundwater region is underlain by undeformed, unconsolidated to semi-consolidated sedimentary deposits. The chemistry of the water near the surface is variable with low dissolved solids and high iron concentrations. The water chemistry in areas underlain by glauconitic sediments (such as Red Bank and



Tinton Sands) is dominated by calcium, magnesium, and iron. The sediments in the area of Fort Monmouth were deposited in fluvia-deltaic to nearshore environments.

The water table aquifer in the Main Post area is identified as part of the "composite confining units," or minor aquifers. The minor aquifers include the Navesink formation, Red Bank Sand, Tinton Sand, Hornerstown Sand, Vincentown Formation, Manasquan Formation, Shark River Formation, Piney Point Formation, and the basal clay of the Kirkwood Formation.

Well records indicate that wells installed in the Red Bank and Tinton Sands produce 2 to 25 gallons per minute (gpm). Water in these upper hydrogeologic units is typically encountered at shallow depths below ground surface (2 to 9 ft bgs). However, domestic wells are generally screened deeper in these upper hydrogeologic units. The shallow water table conditions in the Tinton and Red Bank Sands, and the similar composition of these sands within the Kirkwood Formation, suggest that the Tinton-Red Bank-Kirkwood sequence forms a single, laterally continuous aquifer. Water in this water table aquifer will flow east toward the Atlantic Ocean. Local topography will tend to deflect the flow toward local depressions.

As stated in the SI Report (Weston, 1995), N.J.A.C. 7:9-6, *Groundwater Quality Standards*, establishes groundwater criteria for different classes of groundwater. Class II-A, which is defined as all groundwater that is not classified as one of the other special classes, is the class for groundwater at Fort Monmouth. The primary designated use for Class II-A ground water is potable water; secondary uses include agricultural and industrial water.

Shallow groundwater is locally influenced within the Main Post area by the following factors:

- Tidal influence (based on proximity to the Atlantic Ocean, rivers, and tributaries)
- Topography
- Nature of the fill material within the Main Post area
- Presence of clay and silt lenses in the natural overburden deposits
- Local groundwater recharge areas (i.e., streams, lakes)

Due to the fluvial nature of the overburden deposits (i.e., sand and clay lenses), shallow groundwater flow direction is best determined on a case-by-case basis. The groundwater flow in the vicinity of the CW-7 site has been determined to be south towards Wampum Brook.

#### **2.3.3 Soils**

According to the U.S. Department of Agriculture (USDA), Soil Conservation Service, Monmouth County Soil Survey, (**Figure 4**) the following nine soil types are found in the Charles Wood area.



At Atsion Sand

EvB Evesboro Sand, 2 to 5% slopes

FrB Freehold Sandy Loam, 2 to 5% slopes

FUB Freehold Sandy Loam – urban land complex, 0 to 10% slopes

HnA Holmdel Sandy Loam, 0 to 2% slopes

HUA Holmdel Sandy Loam – urban land complex, 0 to 5% slopes

PT Pits, Sands and Gravel Sn Shrewsbury Sandy Loam

UD Udorthents – urban land complex, 0 to 3% slopes

A brief description of each of the identified soils types is provided below.

The Atsion sand is a nearly level, poorly drained, soil found in depressional areas and on broad flats. The uppermost two inches are matted, partly decomposed organic material and roots with six inches of black sand below. The subsurface layer is a 14-inch thick grayish brown sand. The subsoil is a dark reddish brown loamy sand, 18-inches thick, with approximately 10 inches of mottled brown sand in the lower layer. The substratum is mottled yellowish-brown fine sand to a depth of at least 60 inches. Permeability is moderately rapid or rapid in the subsoil and in the substratum. The available water capacity is low. Between November and June the seasonal high water table ranges from the surface to 1 foot (Jablonski and Baumley, 1989).

Evesboro soils are excessively drained soils that developed in acid, sandy, coastal plain sediments located on the uplands. These soils have a 4-inch surface layer where the upper 2 inches are matted decomposed organic matter with 2 inches of grayish-brown sand in the lower layer. The subsurface layer is 5 inches of yellowish-brown sand. The subsoil and substratum are yellowish-brown sand. Permeability is rapid in the subsoil and substratum. The available water capacity is low. The seasonal high water table is at a depth of more than 6 ft. Runoff is slow. At Charles Wood, the Evesboro soils are represented by the Evesboro sand, with 2 to 5% slopes (EvB) (Jablonski and Baumley, 1989).

Freehold soils are well-drained soils that formed in acid loamy coastal plain sediments that by volume are 1 to 10% glauconite and are found on uplands. The surface layer is 9-inches thick, dark yellowish brown sandy loam. The subsoil is 26 inches thick. The upper 16 inches of the subsoil are dark brown sandy loam and sandy clay loam with some glauconite. The lower 10 inches are brown sandy loam with glauconite. The substratum is yellowish brown loamy sand with much glauconite to a depth of 70 inches. Permeability is moderate in the subsoil and moderate to moderately rapid in the substratum. Surface runoff is medium. The available water capacity is high. Freehold soils are classified as nonhydric (Jablonski and Baumley, 1989).

Holmdel soils are level, moderately well drained to somewhat poorly drained soils found in depressions and on low divides. The surface layer is a 12-inch thick dark grayish brown sandy loam. The subsoil has two layers: the upper is a yellowish brown sandy loam, 12-inches thick, and the lower layer is mottled yellowish brown sandy clay loam to



a depth of 38 inches. The substratum is mottled, yellowish brown and light olive brown sand and sandy loam to a depth of at least 60 inches. Permeability is moderate in the subsoil and substratum, and the available water capacity is high. The seasonal high water table ranges from 1.5 to 4 ft between December and May. Runoff is slow. Two Holmdel soils are found at the Charles Wood area: the Holmdel sandy loam, 0 to 2% slopes and the Holmdel sandy loam – urban land complex, with 0 to 5% slopes (HUA) (Jablonski and Baumley, 1989).

Soils classified as the Pits, Sand, and Gravel have been excavated for sand and graves. These areas are sand with varying amounts of gravel. The properties of these soils vary from place to place (Jablonski and Baumley, 1989).

The Shrewsbury sandy loam is a level poorly drained soil found in depressions along drainage ways and on broad flats. The first inch is a dark reddish-brown, matted, partly decomposed organic material and roots with 8 inches of black sandy loam below. The subsurface layer is a 4-inch thick dark gray sandy loam. The subsoil has a 9-inch thick mottled grayish brown sandy clay loam and 9 inches of mottled olive gray sandy clay loam. The substratum is a mottled dark greenish gray loamy sand. Permeability is moderate in the subsoil and moderately rapid in the substratum. The available water capacity is high. The seasonal high water table is between the surface and a depth of 1 foot from October to June. Runoff is slow and water ponds on the surface (Jablonski and Baumley, 1989).

Udorthent soils have been altered by excavating or filling (Jablonski and Baumley, 1989). In filled areas, these soils consist of loamy material that is more than 20 inches thick. Filled areas include flood plains, tidal marshes, and areas with moderately well-drained to very poorly-drained soils. Some Udorthent soils contain concrete, asphalt, metal, or glass.

The soils in the vicinity of the CW-7 site are classified as Shrewsbury Sandy Loam (Sn).

#### 2.3.4 Topography and Surface Drainage

Over the last 80 years, the natural topography of Fort Monmouth has been altered by excavation and filling activities by the military. The land surface at the Main Post is relatively flat and ranges in elevation from 4 ft above mean sea level (msl) in the east at Oceanport Creek to 32 ft msl at the western end of the post, near Highway 35. The eastern half of the post is generally 10 ft msl in elevation.

At Charles Wood the land surface slopes from 72 ft msl in the southwest, to 20 ft. msl at the eastern end of the golf course. In general, the southwestern corner of Charles Wood is gently rolling and has the greatest relief.

The Charles Wood area is drained principally by two unnamed tributaries of Wampum Brook; one tributary flows eastward through the center of the camp, and the other flows along the southern boundary. East of Charles Wood, Wampum Brook is joined by



several other unnamed tributaries before it becomes Wampum Lake. Wampum Lake discharges into Mill Creek, which flows through the Main Post. Some runoff from the northwest part of the golf course flows into Lafetra Creek, which is located north of Tinton Avenue.

At Charles Wood, several wetland areas were identified on the FWS National Wetland Inventory Long Branch quadrangle map. The lake on the golf course is classified as palustrine open water/unknown bottom. Several areas along the unnamed tributaries to Wampum Brook are classified palustrine forested wetland, broad-leaved deciduous.

The CW-7 site is located up-gradient of Wampum Brook. The USGS topographic map (**Figure 1**) shows that the land surface of the site is relatively flat at an elevation of approximately 40 ft above mean sea level (msl). Surface water runoff from the CW-7 site is likely to flow southward towards Wampum Brook.



#### 3.0 REMEDIAL ACTION ACTIVITIES

The details and results of remedial activities including the soil delineation sampling, soil excavation, and contaminated soil through disposal that occurred at the CW-7 site are described in the following sections.

#### 3.1 Delineation Sampling

As a result of the findings of the SI Report, a Decision Document (**Appendix A**) was prepared by DPW and submitted to NJDEP describing the selected remedial alternative for Site CW-7. The selected remedial alternative encompassed excavation and offsite disposal of an estimated 410 cubic yards of contaminated soil. Excavation was determined to be the most cost effective approach for eliminating the identified contaminant of concern (i.e., PCBs) at the site and to achieve the respective NJDEP RDCSCC for PCBs (0.49 mg/Kg) in soil. Following completion of the excavation, confirmatory soil sampling was to be performed. The Decision Document was reviewed and approved by the NJDEP on 1 July 1997. TVS was then retained by the DPW to implement the selected remedial alternative in accordance with the Decision Document.

At Site CW-7, PCBs are the contaminants of concern and soil is the media of concern. The applicable remediation standard is the NJDEP RDCSCC for total PCBs in soil: 0.49 mg/Kg. The Decision Document (Appendix A) submitted by Fort Monmouth to NJDEP and approved on 1 July 1997 identified the applicable remediation standard of 0.49 mg/Kg for PCBs in soils for the proposed remedial action at Site CW-7.

#### 3.1.1 Sampling Process

In May 1996, a remedial investigation (RI) was conducted at Site CW-7 to delineate the horizontal and vertical extent of PCBs in soil and to support the planned remedial action. The RI used a combination of field screening techniques and laboratory analyses. Collected soil samples were first evaluated in the field using the PCB Rapid Immunoassay Screen (RIS<sup>c</sup>)® Soil Test System manufactured by ENSYS Inc. (A copy of the User's Guide for the ENSYS RIS<sup>c</sup> ® Soil Test System is provided in **Appendix** C). The ENSYS RIS<sup>c</sup> ® Soil Test System is a colorimetric test and three (3) PCB concentration categories were reported in the field screening: less than (<)0.5 mg/Kg, greater than (>)0.5 mg/Kg, and >50.0 mg/Kg. The initial soil samples at each location were collected from a sample depth of 0 to 1 foot. In locations where results of field screening showed that PCB concentrations were above the RDCSCC (i.e., >0.5 mg/Kg), another sample was collected one foot deeper at that location. This process continued until field screening concentrations less than 0.5 mg/Kg were observed.

A total of 67 soil samples were screened for PCBs from approximately 40 sample locations. **Figure 5** shows the sample locations and results of the field screening. Copies of the field screening data are provided in **Appendix D**. The results of field screening showed that PCB soil contamination was primarily distributed in the area surrounding the former transformer pad location near Building 2000. Surface soil samples indicated PCB



concentrations greater than 50 mg/Kg at six locations (Location Nos. 51, 52, 53, 61, 62, and 72). PCB concentrations were observed at distances up to 30 ft north of Building 2000, at which point surface soil PCB concentrations were found to be less than 0.5 mg/Kg. Subsurface concentrations were distributed in a similar pattern as the surface samples. Subsurface PCB concentrations were found to be less than the surface samples, yet still exceeded 0.5 mg/Kg to a depth of 4 to 5 ft bgs at several locations (Location Nos. 51, 53, and 61).

The PCB contamination decreased further north of the former transformer location. The PCB contamination was also observed to follow a drainage swale, which skirts the north side of Building 2000. Samples collected along the swale, 50 ft from the former transformer location and as deep as 4 ft bgs, were found to contain PCB concentrations above 0.5 mg/Kg.

Eight of the 67 samples (>10%) were submitted for laboratory analysis to confirm the PCB concentrations detected by field screening. **Table 1** provides a comparison of the field screening and laboratory analysis results. The laboratory results confirmed the observed range of PCBs in each of the 8 field screening samples. A copy of the confirmatory laboratory analytical results is provided in **Appendix E**.

Table 1
PCB Sampling Results – May 28 to 30, 1996

Location		Field Sci	Laboratory Analysis Total PCB		
(Building No.)	Sample ID	0 to 0.5	0.5 to 50	>50	Results (mg/Kg)
2000	CW07-TR04		X		1.6*
2000	CW07-TR12	X			0.52*
2000	CW07-TR13	X			(U)
2000	CW07-TR32	X			0.32
2000	CW07-TR33	X			0.46
2000	CW07-TR53		X		1.6*
2000	CW07-TR61 (0-1')			X	72*
2000	CW07-TR61 (4-5')		X		6.8*

<sup>\*</sup>Exceeds the NJDEP RDCSCC of 0.49 mg/kg.

(U) – Compound was not detected at or above the reporting limit.

3-2



#### 3.1.2 Delineation Results

The field screening and laboratory analytical results indicated a surface area encompassing approximately 3,000 square ft (ft²) within which PCB concentrations exceeded 0.49 mg/Kg. Within this area of impacted soil, PCB contamination was found in certain locations to a maximum depth of approximately 6 ft. Based on the estimated surface area and varying depth of the PCB concentrations, the site was divided into five areas (Areas 1 to 5) for soil excavation and removal. (Note: Areas 1 and 2 include the same surface area but separate depths; Area 1 encompasses the identified area from 0 to 2 ft, and Area 2 from 2 to 6 ft.)

#### 3.2 Remedial Activities

Based on the results of the RI and as presented in the Decision Document, excavation and removal of the delineated PCB contaminated soils was selected as the most cost effective remedial alternative for eliminating the identified contaminant of concern at Site CW-7. It was estimated that approximately 410 cubic yards of contaminated soil would be excavated and disposed offsite at an appropriate disposal facility. DPW then contracted TVS to implement the selected remedial alternative and then perform post-excavation soil sampling.

During all site investigation/remedial activities, hazards at the work site, which may have posed a threat to the Health and Safety of personnel, were minimized. A qualified individual utilizing air-monitoring devices monitored all areas that posed, or may have been suspected to pose, a vapor hazard. A copy of the Site Health and Safety Plan for the remedial activities performed at Site CW-7 is provided in **Appendix F**.

All sampling was performed in accordance with the methods described in the NJDEP *Field Sampling Procedures Manual*. Sampling frequency and parameters analyzed complied with the NJDEP *Technical Requirements for Site Remediation* (N.J.A.C. 7:26E). Analysis of the soil samples collected at Site CW-7 by TVS, was performed at the Fort Monmouth Environmental Laboratory, a New Jersey certified laboratory (Certification No. 13461).

Review of the analytical data report packages provided by the laboratory indicated that the analytical data is of good quality and is reliable. The data reports indicate that the appropriate analytical methods were used, holding times were met and duplicate and blank analyses showed good reproducibility. The method detection limits achieved by the laboratory, for the various analytes were below the established regulatory limits. The analytical data package is provided in **Appendix H.** The full data package, including quality control data, is on file at U.S. Army Fort Monmouth, Fort Monmouth, New Jersey.

Soil excavation and post-excavation sampling activities at the 5 delineated areas were initially conducted between November 19 and 25, 1997. Sample locations and analytical results from the post-excavation sampling are depicted on **Figure 6**. The analytical



results are separately colored by sample depth and each analytical result that <u>exceeded</u> the RDCSCC has been "<u>boxed</u>" in "red". All of the results are expressed in milligrams/Kilogram (mg/Kg). A summary of the post-excavation sample results is provided in **Table 2**. A summary of the excavation activities conducted at each of the five delineated areas is provided below.

#### Areas 1 and 2

On November 19, 1997, TVS initiated soil excavation activities in Areas 1 and 2 (see **Figure 5**). Soils were initially excavated to depths ranging from 0 to 2 ft bgs (Area 1) to approximately 2 to 6 to 8 ft bgs (Area 2). Following the excavation activities, 12 post-excavation samples were collected from depth intervals of 0 to 6 inches, 72 to 78 inches bgs, and 96 to 102 inches bgs. Analytical results indicated two samples with PCB concentrations exceeding the NJDEP RDCSCC at the following depths: Sample A1 at 24.9 mg/Kg, collected at 0 to 6 inches bgs, and Sample G at 47.5 mg/Kg, collected at 72 to 78 inches bgs.

#### Area 3

On November 21, 1997, excavation activities were initiated in Area 3. Soils were excavated to a depth of approximately 4 ft bgs. A total of 12 post-excavation samples were collected from the 48 to 54 inch depth interval. Analytical results indicated three samples with PCB concentrations exceeding the NJDEP RDCSCC: Samples M, O, and P at concentrations of 3.86 mg/Kg, 0.81 mg/Kg, and 0.76 mg/Kg, respectively.

#### Areas 4 and 5

On November 23, 1997, TVS conducted the excavation of Areas 4 and 5. Soils were excavated to a depth of approximately 2 ft bgs. A total of 19 post-excavation samples were collected from the 0 to 6 inch and 24 to 30 inch depth intervals. Analytical results indicated two samples within Area 4 at a sample depth of 24 to 30 inches with PCB concentrations exceeding the NJDEP RDCSCC: Sample X (0.86 mg/Kg) and Sample DD (0.61 mg/Kg). PCBs were not detected in the 3 post-excavation samples collected in Area 5 at a sample depth of 24 to 30.

In addition, 4 confirmatory samples (Samples II, JJ, KK, and LL) were collected further downgradient of the delineated excavation areas at a sample depth of 0 to 6 inches. In these samples, PCBs were not detected.

Based on the analytical results from the post-excavation sampling, it was determined that further delineation/excavation of PCB contaminated soils was required at Areas 1 and 2. Additional soil investigation in Areas 1 and 2 was then conducted by TVS to expand upon the initial post-excavation sampling and further delineate the extent of PCB impacted soil. On January 27, 1998, seven exploratory soil borings (depicted as A through G) were installed. Four soil samples were collected from each of the seven boring locations at the following sample depths: 0 to 6 inches, 12 to 18 inches, 24 to 30 inches, and 36 to 42 inches, totaling 28 samples. Analytical results for all the collected samples (see **Table 3**) were below the MDL.

3-4



The post-excavation sample results at Areas 3 and 4 were deemed appropriate for further evaluation using compliance averaging. Therefore, further delineation/excavation was not proposed at Areas 3 and 4. The results of compliance averaging for Areas 3 and 4 are presented in Section 3.5 of this RAR.

On February 9 and 10, 1998, based on the additional soil investigation, TVS excavated additional soils in Areas 1 and 2 at initial post-excavation sample locations A, B, G and H. Soils around locations G and H were excavated to a depth of 12 ft bgs, and soils around locations A and B were excavated to a depth of 0.5 ft bgs. Four post-excavation samples were collected (A3 and B3 at a depth of 0 to 6 inches bgs and H2 and G2 at a depth of 144 to 150 inches bgs). Analytical results indicated all samples to be below the MDL (see **Table 4**). Approximate limits of the excavation areas are depicted on **Figure 7**.

Upon receiving analytical results and confirming the effectiveness of the remedial activities completed at the site, the excavated areas were backfilled to grade with certified clean crushed stone and sand. Copies of the backfill receipts for sand and crushed stone used during the backfilling and site restoration efforts are provided in **Appendix G.** 

#### 3.3 UST Closure Activities

On November 19, 1997 during the excavation of Area 1, TVS encountered an unregulated 2,000-gallon No. 2 fuel oil underground storage tank (UST). The UST was immediately pumped out and cleaned. Approximately 380 gallons of residual sludge/water was pumped out of the UST and drummed for disposal. Following the UST removal, the tank was inspected for corrosion and leakage. The tank appeared to be in good condition, and there was no evidence that the tank or piping had leaked. In addition, TVS did not find the associated feed and return lines or the fill port. The UST was cleaned and transported off-site for recycling at the Mazza & Sons, Inc. facility, located in Tinton Falls, New Jersey. Disposal documentation for the UST is provided in **Appendix I.** Six post-excavation soil samples (Sample Numbers A through F) were collected on 26 February 1998 from the excavation at 96 to 102 inches in depth and submitted for Total Petroleum Hydrocarbons (TPHC) analysis. Figure 7 shows the approximate location of the former UST and the post-excavation sample locations. Five of the six samples were found to be below the MDL. The sixth sample (Sample Location - F) was found to contain TPHC at a concentration of 238 mg/Kg which is below the NJDEP criteria for Total Volatile Organic Contaminants (1,000 mg/kg) and the NJDEP Cleanup Criteria for Total Organic Contaminants (10,000 mg/kg) and therefore, no further action was warranted. Additionally, no groundwater was encountered in the UST excavation; therefore no groundwater sample was collected. Table 5 summarizes the analytical data results from the UST post-excavation sampling.

#### 3.4 Schedule of Site Activities

A schedule of site activities regarding the SI, remedial investigations, and remedial action activities at Site CW-7 is provided below.



1 & 2 December 1994	WESTON Site Investigation activities.						
May - June 1996	Remedial Investigation activities for soils						
-	conducted by DPW						
1 July 1997	Decision Document approved by NJDEP.						
November 1997	Soil excavation performed and post-excavation						
	sampling conducted, UST removal/disposal						
	completed, PCB contaminated soils transported						
	to CWM Chemical Services, Inc. Model City,						
	NY.						
27 January 1998	Additional soil investigation activities initiated						
	in Areas 1 and 2.						
9-10 February 1998	Additional soil excavation in Areas 1 & 2						
	performed and post-excavation sampling						
	conducted, backfilling activities and site						
	restoration completed.						
26 February 1998	UST post-excavation soil sampling and waste						
	characterization sampling of stockpiled soil						
	performed.						
June 1998	Certificate of Destruction and Recycling for						
	the thermally treated soil.						

#### 3.5 Compliance Averaging

In evaluating the analytical results of the post-excavation sampling at Areas 3 and 4 in comparison to the applicable remediation standards as required by N.J.A.C. 7:26E-4.8(c)3i, it was deemed appropriate that "compliance averaging" be used to determine compliance with the respective NJDEP RDCSCC for PCBs in soil (i.e., 0.49mg/Kg),. Compliance averaging uses the average contaminant concentration in an area of concern rather than the contaminant concentration of individual samples for comparison to applicable remediation standards or Soil Cleanup Criteria. To support this evaluation, the guidance and NJDEP policy presented in an article entitled "Compliance Averaging" from the NJDEP Spring 1995 issue of *Site Remediation News* (Volume 7, No. 2, Article 08) was utilized.

Typically, in performing compliance averaging, once a sample location exceeding the RDCSCC had been identified, the first step would be a comparison to site background concentrations. However, given that comparison to background concentrations would not be applicable for PCBs, an exceedence was first evaluated for consideration as "marginal" (i.e., 1 to 2 mg/Kg above the RDCSCC). If this was the case, the exceedence was then compared to the immediate surrounding sample locations. If the surrounding sample locations did not have any exceedences of the RDCSCC, no further action was recommended for that particular exceedence.

If the aforementioned exceedence could not be considered marginal, the exceedence was evaluated by averaging the exceedence value with the values for the immediate



surrounding sample locations at the same sample depth that did not have an exceedence of the RDCSCC. Where the surrounding sample locations had values of non-detect, one-half the respective MDL was used. After averaging the values, if the compliance averaged result was below the RDCSCC, it was recommended for no further action. If the compliance averaged result was marginally above the RDCSCC and the exceedence was isolated, no further action was also recommended. If the compliance averaged result was more than marginally above the RDCSCC, it was evaluated for a small quantity, de minimus exceedence or for further action. The results of further evaluation and compliance averaging for the exceedences in Areas 3 and 4 are provided below.

#### Area 3

Area 3 had three (3) exceedences of the RDCSCC at Sample Locations M (3.86 mg/Kg), O (0.81 mg/Kg), and P (0.76 mg/Kg). In each instance the detection was for PCB Arochlor 1260. No other PCBs were detected. The exceedences at Sample Locations P and O were considered to be marginal exceedences when compared to the RDCSCC of 0.49 mg/Kg or de minimus quantities given the sample depth and the excavation efforts conducted and no further action is recommended. The exceedence at Sample Location M has been evaluated utilizing compliance averaging. The table below lists the exceedence and the samples used from the sample depth of 48 to 54 inches to compliance average for Arochlor 1260.

Sample Location	Arochlor 1260				
	Concentration				
	(mg/Kg)				
M	3.86				
N	0.29				
K	0.025*				
L	0.025*				
J	0.025*				
Average of 5 samples	0.85				
Arochlor 1260 NJDEP RDCSCC – 0.49 mg/Kg					

**Note: Exceedence indicated by bold script** 

The result of compliance averaging for Sample Location M is 0.85 mg/Kg, which can be considered marginal when compared to the RDCSCC of 0.49 mg/Kg and given the sample depth and the excavation efforts conducted and no further action is recommended.

#### Area 4

Area 4 had two (2) exceedences of the RDCSCC at Sample Location DD (0.61 mg/Kg) and Sample Location X (0.86 mg/Kg) taken at a sample depth of 24 to 30 inches. In each instance the detection was for PCB Arochlor 1260. No other PCBs were detected. Both of these sample results were considered to be marginal exceedences when compared to

3-7

<sup>\*</sup>  $\frac{1}{2}$  MDL (0.05 mg/Kg)



the RDCSCC of 0.49 mg/Kg or de minimus quantities given the sample depth and the excavation efforts conducted and no further action is recommended.



#### 4.0 FINDINGS/REMEDIAL ACTIONS

The findings of the remedial activities, as well as the details of the waste disposal activities performed at the CW-7 site, are summarized in the following sections.

#### 4.1 Remedial Action Effectiveness

The RI used a combination of field screening techniques and laboratory analyses. A total of 67 soil samples were screened for PCBs from approximately 40 sample locations. The field screening and laboratory analytical results indicated a surface area encompassing approximately 3,000 ft² within which PCB concentrations exceeded 0.49 mg/Kg, the respective NJDEP RDCSCC for PCBs in soil. Within this area of impacted soil, PCB contamination was found at varying depths to a maximum depth of approximately 6 ft. Based on the estimated surface area and varying depths of PCB concentrations exceeding the established remediation standard, the site was divided into five areas (Areas 1 through 5) for soil excavation and removal.

Soil excavation activities were initiated by TVS at Site CW-7 on November 19 1997. Post-excavation soil samples were then collected from the five excavation areas (Areas 1, 2, 3, 4 and 5) and analytical results in Areas 1, 2, 3, and 4 indicated PCB levels that exceeded the NJDEP RDCSCC for PCBs in soils. In evaluating the analytical results from the post-excavation sampling, it was determined that further delineation/excavation of PCB contaminated soils was required at Areas 1 and 2. However, the post-excavation sample results at Areas 3 and 4 were deemed appropriate for further evaluation using compliance averaging. Therefore, further delineation/excavation was not proposed at Areas 3 and 4. The post-excavation results at Area 5 indicated no further action was required.

On January 27, 1998, TVS conducted an additional round of soil sampling activities to better delineate the extent of PCB contamination within Areas 1 and 2. A total of 28 samples were collected and submitted for PCB analysis and revised excavation areas established. TVS then performed additional excavation at sample locations A, B, G and H. The post-excavation samples collected subsequent to the additional excavation indicated no PCB concentrations above the MDL. Four confirmatory samples were also collected further downgradient of the delineated excavation areas at a sample depth of 0 to 6 inches. These samples also did not detect PCBs above the MDL.

Compliance averaging conducted at Areas 3 and 4 indicated average concentrations that were considered marginal exceedances. This included an average concentration of 0.85 mg/Kg at Area 3 and two marginal exceedances at Area 4 of 0.61 mg/Kg and 0.86 mg/Kg.

In addition, during the excavation of Area 1, TVS encountered an unregulated 2,000-gallon No. 2 fuel oil UST. Residual waste from the UST was removed, the UST was cleaned and removed and transported offsite for proper disposition. Six post-excavation soil samples were collected from the excavation at 96 to 102 inches in depth and



submitted TPHC analysis. Five of the six samples were found to be below the MDL and the sixth sample was found to contain TPHC at a concentration of 238 mg/Kg, which is below the NJDEP criteria for Total Volatile Organic Contaminants (1,000 mg/kg) and the NJDEP Cleanup Criteria for Total Organic Contaminants (10,000 mg/kg). Additionally, no groundwater was encountered in the UST excavation; therefore no groundwater sample was collected.

#### 4.2 Soil Disposal

A total of approximately 294 cubic yards of soil was excavated and placed in thirteen (13) stockpiles during the remedial activities. Excavated soils determined to contain PCB concentrations exceeding 50 mg/Kg were separately stockpiled and managed as a Toxic Substances Control Act (TSCA) waste. The stockpiled contaminated soil was both placed upon and covered with tarps. All excavated soil characterization and disposal was handled directly by the DPW. Composite samples from the 13 soil stockpiles were collected and submitted for waste characterization analysis for off-site disposal for: TPHC; PCBs; benzene, toluene, ethylbenzene, and xylenes (BTEX), and hazardous waste characteristics, including performance of Toxicity Characteristic Leaching Procedure (TCLP) analysis. A summary of the analytical results from the waste characterization sampling is provided in **Table 6**. The analytical data package is provided in **Appendix J**.

Approximately 44 cubic yards of soil determined to contain PCB concentrations greater than 50 mg/Kg (and thereby a TSCA regulated waste) were stockpiled separately. DPW transported the 44 cubic yards of PCB soils to CWM Chemical Services Inc., a permitted TSCA facility, located in Model City, New York. The soils were transported under State of New York hazardous waste manifests. The remaining 250 cubic yards of stockpiled soil were transported to a thermal treatment facility, located in New Castle, Delaware, under standard non-hazardous waste manifests. Copies of the hazardous and non-hazardous waste manifests and the Certificates of Disposal for the thermally treated soil are provided in **Appendix K**.

#### 4.3 Recommendations

Fort Monmouth is a Federal facility and as such, no deed exists. No further action is proposed in regard to Site CW-7 and the Master Plan for Fort Monmouth will be modified to identify CW-7 Site and the remedial actions conducted. No restrictions are proposed regarding future use of this site.



#### **5.0 REFERENCES**

Brown, G.A. and O.S. Zapecza. 1990. Results of Test Drilling in Howell Township, Monmouth County, New Jersey. USGS, West Trenton, New Jersey.

Jablonski, L.A. 1968. *Groundwater Resources of Monmouth County, New Jersey.* USGS Special Report 23. USGS, Washington, DC.

Jablonski, C.F. and R.J. Baumley. 1989. *Soil Survey of Monmouth County, New Jersey*. U.S. Department of Agriculture, Soil Conservation Service.

Minard, J.P. 1969. Geology of Sandy Hook Quadrangle in Monmouth County, New Jersey. U.S. Government Printing Office, Washington, DC.

New Jersey Geological Survey Map, 1994

Soil Survey of Monmouth County, New Jersey, USDA Soil Conservation Service, 1989.

USGS (U.S. Geological Survey). 1981. Long Branch Quadrangle Map.

WESTON (Roy F. Weston, Inc.). 1993. *Investigation of Suspected Waste Sites at Fort Monmouth, New Jersey*.

WESTON (Roy F. Weston, Inc.). December 1995. Site Investigation Report - Main Post and Charles Wood Areas, Fort Monmouth, New Jersey.

Zapecza, O. 1989. *Hydrogeologic Framework of the New Jersey Coastal Plain*. USGS Professional Paper 1404-B. U.S. Government Printing Office, Washington, DC.



## **TABLES**

#### TABLE 2 POST EXCAVATION SOIL SAMPLING - PCB DATA SUMMARY November 19-25, 1997

#### Site CW-7

#### Fort Monmouth, New Jersey

Laboratory Sample ID#	Field Sample Location	Excavation Area(s)	Depth (bgs)	Date of Collection	Result (mg/kg)	MDL
3165.01	A2	1/2	96-102"	11/19/97	ND	0.35
3165.02	B2	1/2	96-102"	11/19/97	ND	0.35
3165.03	C	1/2	96-102"	11/19/97	ND	0.35
3165.04	D	1/2	96-102"	11/19/97	ND	0.35
3165.05	E	1/2	96-102"	11/19/97	ND	0.35
3165.06	F	1/2	96-102"	11/19/97	ND	0.35
3168.01	A1	1/2	0-6"	11/20/97	24.9	0.35
3168.02	B1	1/2	0-6"	11/20/97	ND	0.35
3168.03	C1	1/2	0-6"	11/20/97	ND	0.35
3168.04	G	1/2	72-78"	11/20/97	47.5	0.35
3168.05	Н	1/2	72-78"	11/20/97	ND	0.35
3168.06	I	1/2	72-78"	11/20/97	ND	0.35
3178.01	J	3	48-54"	11/21/97	ND	0.35
3178.02	K	3	48-54"	11/21/97	ND	0.35
3178.03	L	3	48-54"	11/21/97	ND	0.35
3178.04	M	3	48-54"	11/21/97	3.86	0.35
3178.05	N	3	48-54"	11/21/97	0.29	0.35
3178.06	0	3	48-54"	11/21/97	0.81	0.35
3179.01	P	3	48-54"	11/23/97	0.76	0.35
3179.02	Q	3	48-54"	11/23/97	0.22	0.35
3179.03	R	3	48-54"	11/23/97	ND	0.35
3179.04	S	3	48-54"	11/23/97	ND	0.35
3179.05	T	3	48-54"	11/23/97	0.11	0.35
3179.06	U	3	48-54"	11/23/97	ND	0.35
3179.07	V1	4	0-6"	11/23/97	0.06	0.35
3179.08	V2	4	48-54"	11/23/97	ND	0.35
3182.01	W	4	24-30"	11/25/97	ND	0.35
3182.02	X	4	24-30"	11/25/97	0.86	0.35
3182.03	Y	4	24-30"	11/25/97	ND	0.35
3182.04	Z	4	24-30"	11/25/97	0.11	0.35
3182.05	AA	4	24-30"	11/25/97	0.28	0.35
3182.06	BB	4	24-30"	11/25/97	ND	0.35
3182.07	CC	4	24-30"	11/25/97	ND	0.35
3182.08	DD	4	24-30"	11/25/1997	0.61	0.35
3182.09	EE1	4	0-6"	11/25/1997	0.43	0.35
3182.10	EE2	4	24-30"	11/25/1997	ND	0.35
3182.11	FF	5	24-30"	11/25/1997	ND	0.35
3182.12	GG	5	24-30"	11/25/1997	ND	0.35
3182.13	HH	5	24-30"	11/25/1997	ND	0.35
3182.14	II	-	0-6"	11/25/1997	ND	0.35
3182.15	JJ	-	0-6"	11/25/1997	ND	0.35
3182.16	KK	-	0-6"	11/25/1997	ND	0.35
3182.17	LL	-	0-6"	11/25/1997	ND	0.35

Notes:

mg/Kg = milligrams per Kilogram ND = Not Detected

MDL = Method Detection Limit

Shaded areas = PCB exceedances (>0.49 mg/Kg)

bgs = below ground surface

## TABLE 3 ADDITIONAL SOIL INVESTIGATION - PCB DELINEATION January 27, 1998 Site CW-7

## Fort Monmouth, New Jersey

Laboratory Sample ID#	Field Sample Location	Depth (bgs)	Date of Collection	Result (mg/kg)	MDL
3299.01	A1	0-6"	01/27/98	ND	0.35
3299.02	A2	12-18"	01/27/98	ND	0.35
3299.03	A3	24-30"	01/27/98	ND	0.35
3299.04	A4	36-42"	01/27/98	ND	0.35
3299.05	B1	0-6"	01/27/98	ND	0.35
3299.06	B2	12-18"	01/27/98	ND	0.35
3299.07	В3	24-30"	01/27/98	ND	0.35
3299.08	B4	36-42"	01/27/98	ND	0.35
3299.09	C1	0-6"	01/27/98	ND	0.35
3299.10	C2	12-18"	01/27/98	ND	0.35
3299.11	C3	24-30"	01/27/98	ND	0.35
3299.12	C4	36-42"	01/27/98	ND	0.35
3299.13	D1	0-6"	01/27/98	ND	0.35
3299.14	D2	12-18"	01/27/98	ND	0.35
3299.15	D3	24-30"	01/27/98	ND	0.35
3299.16	D4	36-42"	01/27/98	ND	0.35
3299.17	E1	0-6"	01/27/98	ND	0.35
3299.18	E2	12-18"	01/27/98	ND	0.35
3299.19	E3	24-30"	01/27/98	ND	0.35
3299.20	E4	36-42"	01/27/98	ND	0.35
3299.21	F1	0-6"	01/27/98	ND	0.35
3299.22	F2	12-18"	01/27/98	ND	0.35
3299.23	F3	24-30"	01/27/98	ND	0.35
3299.24	F4	36-42"	01/27/98	ND	0.35
3299.25	G1	0-6"	01/27/98	ND	0.35
3299.26	G2	12-18"	01/27/98	ND	0.35
3299.27	G3	24-30"	01/27/98	ND	0.35
3299.28	G4	36-42"	01/27/98	ND	0.35
3299.29	DUP	-	01/27/98	ND	0.35
3299.30	Field Blank	-	01/27/98	ND	=

#### Notes:

ND = Not Detected

MDL = Method Detection Limit

mg/kg = milligrams per kilograms

bgs = below ground surface

## TABLE 4 POST EXCAVATION SOIL SAMPLING - PCB DATA SUMMARY February 9-10, 1998 Site CW-7

## Fort Monmouth, New Jersey

Laboratory Sample ID#	Field Sample Location	Depth (bgs)	Date of Collection	Result (mg/kg)	MDL
3326.01	G2	144-150"	2/9/1998	ND	0.35
3326.02	H2	144-150"	2/9/1998	ND	0.35
3330.01	A3	0-6"	2/10/1998	ND	0.35
3330.02	В3	0-6"	2/10/1998	ND	0.35

Notes:

ND = Not Detected

MDL = Method Detection Limit mg/kg = milligram per kilogram

bgs = below ground surface

## TABLE 5 UNDERGROUND STORAGE TANK - POST EXCAVATION SAMPLES

### TPHC - Data Summary Site CW-7

## Fort Monmouth, New Jersey

SAMPLE	FIELD ID	SAMPLE DATE	DILUTION FACTOR	MDL	TPHC Result
				(mg/Kg)	(mg/Kg)
3166.01	2000-A2 (96-102")	2/26/1998	1.00	184	ND
3166.02	2000-B2 (96-102")	2/26/1998	1.00	186	ND
3166.03	2000-C2 (96-102")	2/26/1998	1.00	192	ND
3166.04	2000-D2 (96-102")	2/26/1998	1.00	197	ND
3166.05	2000-E2 (96-102")	2/26/1998	1.00	212	ND
3166.06	2000-F2 (96-102")	2/26/1998	1.00	173	237.92

ND - Indicates that the compound was not detected at or below the quantification limits

MDL - Method Detection Limit

mg/Kg - milligrams per Kilogram

## TABLE 6 SOIL STOCKPILE - WASTE CHARACTERIZATION Total Petroleum Hydrocarbon (TPHC) Analysis Site CW-7

## Fort Monmouth, New Jersey

SAMPLE	FIELD ID	SAMPLE	DILUTION	MDL	TPHC Result
		DATE	FACTOR		
				(mg/kg)	(mg/kg)
3367.01	SP-1	2/26/1998	1.00	200	ND
3367.02	SP-2	2/26/1998	1.00	203	241.53
3367.03	SP-3	2/26/1998	1.00	179	ND
3367.04	SP-4	2/26/1998	1.00	187	ND
3367.05	SP-5	2/26/1998	1.00	188	ND
3367.06	SP-6	2/26/1998	1.00	189	ND
3367.07	SP-7	2/26/1998	1.00	192	ND
3367.08	SP-8	2/26/1998	1.00	188	ND
3367.09	SP-9	2/26/1998	1.00	195	ND
3367.10	SP-10	2/26/1998	1.00	203	359.78
3367.11	SP-11	2/26/1998	1.00	191	ND
3367.12	SP-12	2/26/1998	1.00	177	353.95
3367.13	SP-13	2/26/1998	1.00	195	237.07
3367.14	FIELD DUP	2/26/1998	1.00	194	1319.12

ND - Indicates that the compound was not detected at or below the quantification limits

MDL - Method Detection Limit

mg/kg - milligrams per kilogram

## SOIL STOCKPILE - WASTE CHARACTERIZATION

#### Total Polychlorinated Biphenyls (PCBs) Analysis Site CW-7

## Fort Monmouth, New Jersey

SAMPLE	FIELD ID	SAMPLE DATE	MDL	Total PCBs Result	
				resure	
			(mg/kg)	(mg/kg)	
3367.01	SP-1	2/26/1998	0.35	0.12	
3367.02	SP-2	2/26/1998	0.35	1.92	
3367.03	SP-3	2/26/1998	0.35	0.15	
3367.04	SP-4	2/26/1998	0.35	1.76	
3367.05	SP-5	2/26/1998	0.35	14.20	
3367.06	SP-6	2/26/1998	0.35	4.10	
3367.07	SP-7	2/26/1998	0.35	2.11	
3367.08	SP-8	2/26/1998	0.35	0.47	
3367.09	SP-9	2/26/1998	0.35	3.85	
3367.10	SP-10	2/26/1998	0.35	1.18	
3367.11	SP-11	2/26/1998	0.35	0.22	
3367.12	SP-12	2/26/1998	0.35	1.27	
3367.13	SP-13	2/26/1998	0.35	1.50	
3367.14	FIELD DUP	2/26/1998	0.35	ND	

ND - Indicates that the compound was not detected at or below the quantification limits

MDL - Method Detection Limit

Results are reported on a Dry Wt. Basis

mg/kg - milligrams per kilogram

## COMPOSITE SOIL STOCKPILE - WASTE CHARACTERIZATION

### Benzene, Toluene, Ethylbenzene, Xylene (BTEX) - Analysis Site CW-7

## Fort Monmouth, New Jersey

SAMPLE ANALYTE	SAMPLE DATE	SP1-3	SP4-6	SP7-9	SP10-13	
ANALYIE	DATE	(ug/kg)	(ug/kg)	(ug/kg)	(ug/kg)	
Benzene	2/26/1998	1 U	1 U	1 U	1 U	
Toluene	2/26/1998	1 U	1 U	1 U	1 U	
Ethylbenzene	2/26/1998	3 U	2 U	2 U	2 U	
m+p-Xylenes	2/26/1998	4 U	4 U	4 U	3 U	
o-Xylene	2/26/1998	3 U	2 U	2 U	2 U	

U - Not detected above the method detection limit ug/kg - micrograms per kilogram

## COMPOSITE SOIL STOCKPILE - WASTE CHARACTERIZATION

#### TCLP Analysis - Volatiles Site CW-7

## Fort Monmouth, New Jersey

SAMPLE	SAMPLE	SP1-3	SP4-6	SP7-9	SP10-13	Regulatory	MDL
	DATE					Level	
		mg/L	mg/L	mg/L	mg/L	mg/L	mg/L
Vinyl Chloride	2/26/1998	ND	ND	ND	ND	0.2	0.0026
1,1-Dichloroethene	2/26/1998	ND	ND	ND	ND	0.7	0.0007
2-Butanone	2/26/1998	ND	ND	ND	ND	200	0.0021
Chloroform	2/26/1998	ND	ND	ND	ND	6	0.0004
Carbon Tetrachloride	2/26/1998	ND	ND	ND	ND	0.5	0.0012
Benzene	2/26/1998	ND	ND	ND	ND	0.5	0.0005
1,2-Dichloroethane	2/26/1998	ND	ND	ND	ND	0.5	0.0013
Trichloroethene	2/26/1998	ND	ND	ND	ND	0.5	0.0009
Tetrachloroethene	2/26/1998	ND	ND	ND	ND	0.7	0.0009
Chlorobenzene	2/26/1998	ND	ND	ND	ND	100	0.0007

ND - Indicates that the compound was not detected at or below the quantification limits

MDL = Method Detection Limit

mg/L - milligrams per liter

#### COMPOSITE SOIL STOCKPILE - WASTE CHARACTERIZATION

### TCLP Analysis - Semi-Volatiles Site CW-7

#### Fort Monmouth, New Jersey

SAMPLE	SAMPLE	SP1-3	SP4-6	SP7-9	SP10-13	Regulatory	MDL
	DATE					Level	
		ug/L	ug/L	ug/L	ug/L	mg/L	ug/L
Pyridine	2/26/1998	ND	ND	ND	ND	5.00	5.00
1,4-Dichlorobenzene	2/26/1998	ND	ND	ND	ND	7.50	0.23
2-Methylphenol (o-cresol)	2/26/1998	ND	ND	ND	ND	200.00	0.14
4-Methylphenol (m,p-cresol)	2/26/1998	ND	ND	ND	ND	200.00	0.14
Hexachloroethane	2/26/1998	ND	ND	ND	ND	3.00	0.33
Nitrobenzene	2/26/1998	ND	ND	ND	ND	2.00	0.46
Hexachlorobutadiene	2/26/1998	ND	ND	ND	ND	0.50	0.38
2,4,6-Trichlorophenol	2/26/1998	ND	ND	ND	ND	2.00	0.42
2,4,5-Trichlorophenol	2/26/1998	ND	ND	ND	ND	400.00	0.31
2,4-Dinitrotoluene	2/26/1998	ND	ND	ND	ND	0.13	0.36
Hexachlorobenzene	2/26/1998	ND	ND	ND	ND	0.13	0.82
Pentachlorophenol	2/26/1998	ND	ND	ND	ND	100.00	1.08

ND - Indicates that the compound was not detected at or below the quantification limits

MDL = method Detection Limit

mg/L - milligrams per liter

ug/L - micrograms per liter

#### COMPOSITE SOIL STOCKPILE - WASTE CHARACTERIZATION

#### TCLP Analysis - Pesticides Site CW-7

#### Fort Monmouth, New Jersey

SAMPLE ANALYTE	SAMPLE DATE	SP1-3	SP4-6	SP7-9	SP10-13	Regulatory Level	MDL
		mg/L	mg/L	mg/L	mg/L	mg/L	mg/L
Chlordane	2/26/1998	ND	ND	ND	ND	0.03	0.00014
Endrin	2/26/1998	ND	ND	ND	ND	0.02	0.00003
Heptachlor	2/26/1998	ND	ND	ND	ND	0.01	0.00003
Heptachlor Epoxide	2/26/1998	ND	ND	ND	ND	0.01	0.00002
Lindane	2/26/1998	ND	ND	ND	ND	0.40	0.00003
Methoxychlor	2/26/1998	ND	ND	ND	ND	10.00	0.00010
Toxaphene	2/26/1998	ND	ND	ND	ND	0.50	0.00020

ND - Indicates that the compound was not detected at or below the quantification limits

MDL = method Detection Limit

mg/L - milligrams per liter

# TABLE 6 (cont.) COMPOSITE SOIL STOCKPILE - WASTE CHARACTERIZATION

#### TCLP Analysis - Metals Site CW-7

#### Fort Monmouth, New Jersey

SAMPLE ANALYTE	SAMPLE DATE	SP1-3	SP4-6	SP7-9	SP10-13	Regulatory Level	MDL
		mg/L	mg/L	mg/L	mg/L	mg/L	mg/L
Arsenic	2/26/1998	ND	ND	ND	ND	5	0.004
Barium	2/26/1998	1.138	0.699	0.195	0.915	100	0.001
Cadmium	2/26/1998	0.001	ND	0.001	ND	1	0.001
Chromium	2/26/1998	ND	ND	ND	ND	5	0.001
Lead	2/26/1998	0.025	0.069	0.101	0.023	5	0.004
Mercury	2/26/1998	ND	ND	ND	ND	0.2	0.0002
Selenium	2/26/1998	0.009	0.007	0.008	0.008	1	0.006
Silver	2/26/1998	ND	ND	ND	0.03	5	0.006

All Results in mg/L

ND - Indicates that the compound was not detected at or below the quantification limits

MDL = Method Detection Limit

mg/L - milligrams per liter

#### COMPOSITE SOIL STOCKPILE - WASTE CHARACTERIZATION

#### Hazardous Waste Characterization - Ignitability Site CW-7

### Fort Monmouth, New Jersey

LABORATORY ID#	Sample Location/Identification	Flashpoint °F
3367.01-03	Composite	>140
3367.04-06	Composite	>140
3367.07-09	Composite	>140
3367.10-13	Composite	>140

#### COMPOSITE SOIL STOCKPILE - WASTE CHARACTERIZATION

#### Hazardous Waste Characterization - pH Site CW-7

#### Fort Monmouth, New Jersey

LABORATORY ID#	Sample Location/Identification	рН
3367.01-03	Composite	5.23
3367.04-06	Composite	5.39
3367.07-09	Composite	5.14
3367.10-13	Composite	5.40

#### COMPOSITE SOIL STOCKPILE - WASTE CHARACTERIZATION

# Hazardous Waste Characterization - Reactivity and TCLP Analyis - Herbicides Site CW-7

#### Fort Monmouth, New Jersey

SAMPLE	SAMPLE DATE	MDL	PQL	3367.01-	3367.04- 06	3367.07- 09	3367.10- 13
% Solids	2/26/1998			80	82	76	81
Reactive Cyanide (mg/kg)	2/26/1998	100	100	ND	ND	ND	ND
Reactive Sulfide (mg/kg)	2/26/1998	250	250	ND	ND	ND	ND
TCLP Herbicides (mg/L)							
2,4-D	2/26/1998	0.00046	0.002	U	U	U	U
Silvex	2/26/1998	0.00066	0.002	U	U	U	U
Total Organic Halide (mg/kg)	2/26/1998	25	25	ND	ND	ND	ND

MDL = Method Detection Limit

MDL used for 600 and 200 series methods. PQL used for SW846 methods.

ND = Not Detected above Method Detection Limit


U - Undetected

mg/kg - milligrams per kilogram

mg/L - milligrams per liter



#### **FIGURES**





LONG BRANCH, N. J. 40073-C8-TF-024

1954 PHOTOREVISED 1981 DMA 6164 I SE-SERIES V822




Mapped, edited and published by the Geological Survey


Figure 1 **Site Location Map CW-7 PCB Site** Fort Monmouth, New Jersey



201 Gibraltar Road, Suite 100



# Geologic Map of New Jersey




#### FIGURE 3

Geologic Map of New Jersey CW-7 PCB Site Fort Monmouth, New Jersey



201 Gibraltar Road, Suite 100 Horsham, PA 19044 (215) 957-0955







US Department of Agriculture Soil Conservation Service Soil Survey of Monmouth County, NJ April 1989

Figure 4 Soil Map of Monmouth County **CW-7 PCB Site** Fort Monmouth, New Jersey



201 Gibraltar Road, Suite 100









#### **APPENDICES**



#### APPENDIX A

Fort Monmouth – DPW Decision Document CW-7 (Former PCB Class Transformer CW035) Site

#### **DECISION DOCUMENT**

#### 1. PURPOSE OF REMEDIAL ACTION

This decision document describes the remedial alternative for the CW-7 (Former PCB Class Transformer CW035) Site located in the Charles Wood area of Fort Monmouth. The selected remedial alternative was chosen in accordance with the following regulatory requirements: CERCLA as amended by SARA, the NCP, RCRA, N.J.A.C. 7:26D (Cleanup Standards for Contaminated Sites), N.J.A.C. 7:26E (Technical Requirements for Site Remediation) and AR 200-1, as applicable.

Prior to its removal, the CW035 transformer was located near the front entrance of the Officers Club (Bldg. 2000). The Officers Club is located on the same grounds as the Charles Wood golf course. As part of a post wide PCB survey, the CW035 transformer was sampled and tested for PCB content during the months of October and November, 1989. The sample result for the CW035 transformer revealed a PCB level of 223,091 parts per million. The PCB Class Transformer was removed from service on 10 September 1990 and shipped for offsite disposal on 24 September 1990. As part of the overall Site Investigation phase which was implemented in November of 1994, four surface soil samples were collected to evaluate the potential impact the transformer had on site soils. PCBs were detected above New Jersey Department of Environmental Protection (NJDEP) Direct Contact Soil Cleanup Criteria in all four samples. The sample with the highest PCB concentration was 204 times greater than the applicable standard. The NJDEP cleanup action level for PCBs in soil is 0.49 mg/kg. In May of 1996, a remedial investigation was implemented to completely delineate PCB levels both horizontally and vertically within the soil column. The remedial investigation was a combination of field screening techniques and sample collection for laboratory analysis. Field screening data and laboratory analysis has identified a 3,000 square foot area with PCB levels above NJDEP Direct Contact Soil Cleanup Criteria. Within the zone of contamination, PCBs have migrated vertically to a depth of six feet in some areas.

This decision document was developed by the Directorate of Public Works Environmental Office, Fort Monmouth. All documentation has been submitted and approved by the NJDEP.

#### 2. SUMMARY OF SITE RISK

PCBs are a confirmed carcinogen with carcinogenic and tumorigentic data for studies involving laboratory animals. PCBs are a suspected human carcinogen. A frequently cited health warning pertaining to PCBs is to keep the contaminant away from all food stuffs. The area of contamination is located directly next to the Officers Club Dining Facility. PCBs are also known to persist in the environment for long periods of time.

The chemical makeup of PCBs make them highly resistant to natural degradation processes. It has also been documented that PCBs bioaccumulate within living organisms as the contaminant moves up the food chain.

#### 3. SUMMARY OF REMEDIAL ALTERNATIVES

Approximately 410 cubic yards (615 tons) of contaminated soil shall be excavated and disposed of offsite. Excavation has been determined to be the most cost effective approach for eliminating the contaminant of concern at the site. The NJDEP Direct Contact Soil Cleanup Criteria for PCBs is 0.49 mg/kg. Following soil removal, the site shall be resampled and the data submitted to NJDEP. A no further action letter from the NJDEP shall be requested for the site.

#### 4. PUBLIC/COMMUNITY INVOLVEMENT

At the present time, the Directorate of Public Works Environmental Office is working with the NJDEP and the U.S. Environmental Protection Agency Region II. Information relating to the site investigation and the planned remedial action has not been released to the general public.

#### 5. DECLARATION

Because this remedy will not result in hazardous substances remaining on-site above levels that allow for unlimited use and unrestricted exposure, the five-year review will not apply to this action.

William H. McFarland, Jr.

LTC, MI

Garrison Commander

This Decision Document has been reviewed and approved.

Ian Curtis
Case Manager
NJDEP, Bureau of

Federal Case Management

Name, Title

Signature



#### APPENDIX B

PCB Transformers Section in the Weston (1995) Site Investigation Report



#### 4.3.11 PCB Transformers

#### 4.3.11.1 Site Location

During the 1993 investigation (WESTON, 1993), all locations where PCB transformers had formerly been located were inspected for evidence of spills. Three sites were identified where a PCB transformer was either formerly located over soil and thus evidence of a spill could not be determined visually, or formerly located on concrete and there was discoloration in the concrete. These locations are listed in Table 3.5-1 and identified in Figure 4.3-17.

#### **4.3.11.2** Site History

All PCB transformers (contain greater than 500 ppm PCBs) have been removed from Fort Monmouth; however, the former locations of these transformers were not previously investigated for spilled PCBs. The concrete pad outside Building 2000 was removed between the time of the 1993 investigation and the current field effort.

#### 4.3.11.3 Sampling Effort

As discussed in Subsection 3.5, soil samples were taken from below pole-mounted transformers. Because the concrete pad near Building 2000 had been removed, four soil samples were taken downgradient of the former pad location, as indicated in Figure 4.3-18.

#### 4.3.11.4 PCB Sampling Results

The results of the PCB transformer sampling are presented in Table 4.3-16. One of the four transformer sites sampled at the Charles Wood area was found to have PCBs in soil or concrete above NJDEP SCC.

PCBs were detected in four discrete soil samples above NJDEP SCC. The soil samples were collected downslope of the former location of transformer CW035, which was an exterior pad transformer northeast of Building 2000. This pad had been removed prior to sampling.



Table 4.3-16
Results of Transformer Site Sampling on Charles Wood

Location (Building No.)	Sample ID	Method Detection Limt (mg/kg)	Medium	NJDEP Soil Criteria (mg/kg)	Total PCBs (mg/kg)
2000	CW07-TR01	23*	Soil	0.49	100
2000	CW07-TR02	4.4*	Soil	0.49	27
2000	CW07-TR03	4.4*	Soil	0.49	26
2000	CW07-TR04	.91*	Soil	0.49	6
2018	CW07-TR05	4.5*	Soil	0.49	ND
2018	CW07-TR06	0.47	Soil	0.49	ND
2276	CWAE-TR01	0.21	Soil	0.49	ND

Compounds exceeding NJDEP cleanup criteria are noted by bold numbers ND - Indicates that the compound was not detected at the quantification limit.

<sup>\* =</sup> Method Detection Limit exceeded NJDEP criteria.




All other transformers sampled in the Charles Wood area either had results below detection limits, or had detectable levels of PCBs below applicable cleanup criteria.

#### 4.3.11.5 Recommendations

PCBs were detected above the NJDEP criteria in each of the four soil samples collected downgradient of the former transformer location northeast of Building 2000 (transformer CW-035). PCBs were not detected above NJDEP criteria in samples collected from the other three sampling locations.

Additional samples will be taken to further delineate the extent of contamination and the contaminated soil will be removed and disposed of in accordance with applicable regulations. The depth of contamination is assumed to be 6 inches. Excavation will be performed in conjunction with confirmatory soil sampling to ensure that NJDEP SCC are achieved.



# Sampling Location Former Transformer Pad Soil Remediation Boundary


Fort Monmouth, Charles Wood

FIGURE 4.3-18
EXTENT OF REMEDIATION AT
TRANSFORMER SITE – BUILDING 2000



#### APPENDIX C

ENSYS, Inc. PCB RIS<sup>c</sup>® Soil Test System User's Guide, Part #30966, Revision 0, 8/25/95



# PCB RISC® SOIL TEST SYSTEM

RAPID IMMUNOASSAY SCREEN

# User's Guide

#### IMPORTANT NOTICE

This method correctly identifies 95% of samples that are PCB-free and those containing 1 ppm or greater of PCBs. A sample that develops less color than the standard is interpreted as positive. It contains PCBs. A sample that develops more color than the standard is interpreted as negative. It contains less than 1 ppm PCBs.

This test system should be used only under the supervision of a technically qualified individual who is capable of understanding any potential health and environmental risks of this product as identified in the product literature. The components must only be used for the analysis of soil samples for the presence of polychlorinated biphenyls. After use, the kits must be disposed of in accordance with applicable federal and local regulations.

# TROUBLESHOOTER GUIDE

#### READ ALL INSTRUCTIONS BEFORE PROCEEDING WITH THE TEST

#### **WASH STEP**

Lack of vigorous washing may result in false positives or negatives depending on whether the wash error was committed on standard or sample tubes. Solution: Make sure to wash four times vigorously, washing the whole set of 12 tubes at once.

#### PIPETTE CALIBRATION

An out-of-calibration pipette may result in false positives or negatives depending on whether the amount is greater or less than the specified transfer volume. Solution: Check the calibration at least daily and after any extreme mechanical shock (such as dropping). An indication that the pipette is out of calibration is if the gold barrell is loose and will turn. (When set on 30 µl there should be about a 1/4 of an inch between the white plunger and the end of the clear pipette tip.)

#### AIR BUBBLES IN THE PIPETTE

The presence of air bubbles in the pipette tip when transferring extracts may result in false positives or negatives depending on whether the error was committed on standard or sample tubes. Solution: Quickly examine the pipette tip each time an aliquot is withdrawn and go back to the source and take another aliquot to displace the bubble iof necessary.

#### MIXING

Lack of thorough mixing, when instructed, can cause inconsistent results. Solution: Observe the times in the instructions and mix with sufficient force to ensure that the liquid is homogenous.

#### TIMING

It is important to follow the timing steps in the instructions carefully. The incubation step in the antibody tubes can vary a bit without harm to the tests. The color development step timing is critical and should be no less than 2 minutes and no greater than 3 minutes.

#### WIPING THE TUBES

Wiping of the tubes should be done before they are read in the spectrophotometer because smudges and fingerprints on the tubes can give potentially false negative readings.

#### **MIXING LOT #'S**

Never mix lots! Each kit's components are matched for optimal performance and may give inaccurate results with the components from other kits with different lot #'s. Also, NEVER mix components from different types of kits (ex: Petro kit buffer can not be used with a PAH kit).

#### STORAGE AND OPERATING TEMPERATURES

Temperature requirements are very important and should be strictly adhered to. This test kit should be stored at less than 80°F/27°C and operated between 40°F/4°C and 90°F/32°C.

#### SHELF-LIFE

Each kit label contains the kit expiration date. To achieve accurate results, kits must be used prior to expiration.


# WORKSTATION SET-UP

READ ALL INSTRUCTIONS BEFORE PROCEEDING WITH THE TEST

#### **WORKSTATION SET-UP**

- Mechanical pipette tips
- Filter barrels & plungers
- Ampule cracker
- Glass PCB buffer tubes
- Substrate A
- Eppendorf pipette tips
- Bulb pipettes
- PCB standard
- Antibody coated tubes
- Substrate B

- Extraction jars
- 1 & 10 ppm dilution ampules
- Stop Solution



Workstation shows components for 3 samples tested at 2 levels


READ ALL INSTRUCTIONS BEFORE PROCEEDING WITH THE TEST

#### READ BEFORE PROCEEDING

- Do not attempt to run more than 12 tubes, two of which must be standards.
- Items that you will need that are not provided in the test kit include: a permanent marking pen, laboratory tissue (or paper towels), a liquid waste container, and disposable gloves.
- This User's Guide was written for analyzing soil samples for PCBs at 1 and 10 ppm. See table on page 12 for sensitivity to various aroclors.

#### **TEST PREPARATION**


- Label all Eppendorf repeater tips. Tips can be reused for future analyses. Label the first 5mL tip "A", the second 5mL tip "B" and the third 5mL tip "Stop".
- Label the 12.5 mL tip "Buffer".



Eppendorf Tip

#### STANDARD PREPARATION

- Open PCB Standard ampules by slipping ampule cracker over top, and then breaking tip at scored neck. Transfer solution to empty vial with Bulb Pipettes.
- Label vial with current date. Standard is usable for 2 weeks. Always cap tightly when finished using standard.
- A new PCB Standard should be opened for every 4 samples.




# • PHASE 1


### EXTRACTION & PREPARATION OF THE SAMPLE

#### READ: ALL INSTRUCTIONS: BEFORE PROCEEDING: WITH THE TEST

#### **WEIGH SAMPLE**



- **1a.** Place unused weigh boat on pan balance.
- **1b.** Press ON/MEMORY button on pan balance. Balance will beep and display 0.0.
- 1c. Weigh out 10 % 0.1 grams of soil.
- 1d. If balance turns off prior to completing weighing, use empty weigh boat to retare, then continue.



Weigh Boat





Wooden spatula

#### **EXTRACT PCBS**





- 2a. Uncap extraction jar and place on a flat surface. Without contacting solvent puncture foil seal with ampule cracker or sharp object. Peel the remainder of the seal off extraction jar.
- **2h.** Using wooden spatula, transfer 10 grams of soil from weigh boat into extraction jar.
- **2c.** Recap extraction jar tightly and shake vigorously for one minute.
- 2d. Allow to settle for one minute. Repeat steps 1a 2c for each sample to be tested.




Extraction jar

#### FILTER SAMPLE





- 3h. Insert bulb pipette into top (liquid) layer in extraction jar and draw up sample. Transfer at least ½ bulb capacity into filtration barrel. Do not use more than one full bulb.
- **3c.** Press plunger firmly into barrel until adequate filtered sample is available (place on table and press if necessary). Repeat steps **3a 3c** for each sample to be tested.



# READ TO AVOID COSTLY MISTAKES

### READ ALLINSTRUCTIONS BEFORE PROCEEDING WITH THE TEST


#### SAMPLE DILUTION PROGRAM

- 1. The sample dilution procedure on the next page is for standard detection levels. The following diagram represents the sample dilution procedure for all other detection levels.
- 2. Your kit may include extra dilution ampules to reach high detection levels.
- 3. EVERY AMPULE PROVIDED MUST BE USED!

If there are any questions concerning the dilution procedure please call Technical Services before running the samples to help avoid costly mistakes.

1-800-242-7472 or 919-941-5509 (option "4").

#### **EXAMPLE:**




NOTE: Your Kit may include additional ampules in order to achieve your test levels. Always transfer filtered sample to the dilution ampule labeled with the lowest PPM level and then transfer from this ampule to the next higher level dilution tube.

#### READ: ALL INSTRUCTIONS BEFORE PROCEEDING WITH THE TEST

#### READ BEFORE PROCEEDING

- Label the plastic antibody coated tubes with a permament marking pen.
- When using the mechanical pipette always withdraw and dispense below the liquid level.
- "Shake tubes" means to thoroughly mix the contents with special care not to spill or splash.


#### **DILUTE SAMPLES AND STANDARDS**




1 ppm




10 ppm






PCB Standard

- **4a.** Set the Eppendorf Repeater on 4, assemble the "Buffer" tip and fill with Buffer.
- **4h.** Dispense 1 mL of Buffer into each glass buffer tube.
- **4c.** Open 1 and 10 ppm dilution ampules by slipping ampule cracker over top, and then breaking top at scored neck.
- 4d. Withdraw 60 µL of filtered sample using mechanical pipette and dispense below the liquid level in "1 ppm" dilution ampule. Gently shake ampule from side to side for 5 seconds to mix thoroughly.
- **4e.** Withdraw 60 μL from the "1 ppm" dilution ampule using mechanical pipette and dispense below the liquid level in "10 ppm" dilution ampule. Gently shake ampule from side to side for 5 seconds to mix thoroughly.
- 4f. Transfer 60 µL from each dilution ampule into glass buffer tubes. Always wipe tip after dispensing into buffer tube.
- 4g. Change pipette tip and repeat 4d - 4f for each sample.
- **4h.** Assemble new pipette tip on mechanical pipette and transfer 60 µL from Standard vial into two glass buffer tubes. Immediately replace cap on PCB Standard vial.
- **4i.** Shake all glass buffer tubes for 5 seconds.





Glass buffer tubes

PCB Standard vial

# • PHASE 3

#### THEIMMUNOASSAY

READ ALL INSTRUCTIONS BEFORE PROCEEDING WITH THE TEST

### TRANSFER FROM DILUTION TUBE TO ANTIBODY COATED TUBE









- 5a. Set timer for 10 minutes.
- Working left to right in the workstation:
   Fit all antibody coated tubes firmly on top of all corresponding glass buffer tubes.
   Start timer and immediately invert all connected tube pairs so that the liquid is poured into the antibody coated tubes. Return the tube pairs to the appropriate workstation row making sure the larger

(antibody coated) tube is on the bottom.

- 5c. Invert all tube pairs several more times making sure the pair is returned to the workstation with the larger (antibody coated) tube on the bottom.
- 5d. Disconnect and discard the smaller (dilution) tubes. It is not important to worry about drops of liquid adhering to lips of tubes.
- **5e.** Place conjugate tubes behind antibody tubes in workstation. Remove grey caps and discard.

### TRANSFER OF CONJUGATE TO ANTIBODY COATED TUBES







#### AFTER 10 MINUTES, IMMEDIATELY:

- 6a. Set timer for 5 minutes.
- 6b. Working left to right in the workstation:

  Start timer and immediately:

  Dissolve the conjugate pellets by horizontally connecting the antibody coated tubes and conjugate tubes and tilt the liquid up to pour it onto the conjugate.
- 6c. Return the connected tubes to the appropriate workstation row making sure the larger (antibody coated) tube is on the bottom. It is important that this step is completed within one minute for all tubes.
- 6d. In order to adequately mix solution, invert all connected tube pairs several more times making sure that the pair is returned to the workstation with the larger (antibody coated) tube on the bottom.
- **Ge.** Disconnect and discard the conjugate tubes. It is not important to worry about the loss of liquid adhering to lip of tubes.

Page 8 of 15

# PHASE 4

#### INTERPRETATION:

READ:ALL INSTRUCTIONS: BEFORE PROCEEDING:WITH:THE TEST


## READ BEFORE PROCEEDING WASH PROCEDURE

- An accurate test requires a virgorous wash accomplished by directing a strong stream into the antibody coated tubes.
- The wash solution is a harmless, dilute solution of detergent.


#### WASH

12.3





- 7a. After the 5 minute incubation (a total of 15 minutes), empty antibody coated tubes into liquid waste container.
- **7b.** Wash antibody coated tubes by vigorously filling and emptying a total of 4 times.
- 7c. Tap antibody coated tubes upside down on paper towels to remove excess liquid. Residual foam in the tubes will not interfere with test results.
- Note: When running up to 12 antibody coated tubes, tubes can be washed in two groups one group immediately following the other group.




Wash bottle

# PHASE 3 THE IMMUNOASSAY

READ ALL INSTRUCTIONS BEFORE PROCEEDING WITH THE TEST

#### COLOR DEVELOPMENT

- 8a. Set the Eppendorf Repeater on 2, assemble the "A" tip and fill with Substrate A (TMB, yellow label).
- 8h. Dispense once (200 µL) into each antibody coated tube.
- 8c. Set timer for exactly 2 1/2 minutes.
- 8d. Assemble "B" tip, fill with Substrate B, start timer, and dispense once (200 µL H<sub>2</sub>O<sub>2</sub>, green label) into each antibody coated tube.
- **8e.** Shake all tubes for 5 seconds. Solution will turn blue in some or all antibody coated tubes.
- 8f. Assemble "Stop" tip, fill with Stop Solution (red label), and stop reaction at end of 2 1/2 minutes by dispensing once (200 µL) into each antibody coated tube.




#### **AROCLOR SENSITIVITY**

Aroclor	Lowest Detection Level
1248	1.0 ppm
1254	0.5 ppm
1260	0.5 ppm
1242	2.0 ppm
1232	4.0 ppm
1016	5.0 ppm

# O PHASE? ANALYSIS DE RESIDES.

READ: ALL INSTRUCTIONS: BEFORE PROCEEDING: WITH THE TEST

#### **SELECT STANDARD**






- **9h.** Place both Standard tubes in photometer.
- 9c. Switch tubes until the photometer reading is negative or zero. Record reading.

  If reading is greater than 0.3 in magnitude, results are outside QC limits. Retest the sample(s).
- **9d.** Remove and discard tube in right well. The tube in the left well is the darker standard.

#### **MEASURE SAMPLE**



- 10a: Place 1 ppm tube in right well of photometer and record reading. If photometer reading is negative or zero, PCBs are present. If photometer reading is positive, concentration of PCBs is less than 1 ppm.
- 10b. Place 10 ppm tube in right well of photometer and record reading.

  If photometer reading is negative or zero, PCBs are present.

  If photometer reading is positive, concentration of PCBs is less than 10 ppm.

# **QUALITY CONTROL**

# READ ALL INSTRUCTIONS BEFORE PROCEEDING WITH THE TEST

#### **System Description**

Each PCB RISc Soil 12 Test Case contains enough material to perform 12 test samples, each at two detection levels.

The PCB RISc Soil Test is divided into four phases. The instructions and notes should be reviewed before proceeding with each phase.

#### **Hotline Assistance**

If you need assistance or are missing necessary Test System materials, call toll free: 1-800-242-RISC (7472).

### **Validation and Warranty Information**

Product claims are based on validation studies carried out under controlled conditions. Data has been collected in accordance with valid statistical methods and the product has undergone quality control tests of each manufactured lot.

PCB-free soil and soil containing 1 ppm or greater of PCBs were tested with the EnSys PCB RISc analytical method. The method correctly identified 95% of these samples. A sample that has developed less color than the standard is interpreted as positive. It contains PCBs. A sample that has developed more color than the standard is interpreted as negative. It contains less than 1 ppm PCBs.

The company does not guarantee that the results with the PCB RISc Soil 24 Test Case will always agree with instrument-based analytical laboratory methods. All analytical methods, both field and laboratory, need to be subject to the appropriate quality control procedures.

EnSys, Inc. warrants that this product conforms to the descriptions contained herein. No other warranties, whether expressed or implied, including warranties of merchantability and of fitness for a particular purpose shall apply to this product.

EnSys. Inc. neither assumes nor authorizes any representative or other person to assume for it any obligation or liability other than such as is expressly set forth herein.

Under no circumstances shall EnSys, Inc. be liable for incidental or consequential damages resulting from the use or handling of this product.

#### **How It Works**

Standards, Samples, and color-change reagents are added to test tubes, coated with a chemical specific to PCBs. The concentration of PCBs in an unknown Sample is determined by comparing its color intensity with that of a Standard.

Note: PCB concentration is inversely proportional to color intensity; the lighter the color development of the sample, the higher the concentration of PCBs.

#### **Quality Control**

Standard precautions for maintaining quality control:

- Do not use reagents or test tubes from one Test System with reagents or test tubes from another Test System.
- Do not use the Test System after any portion has passed its expiration date.
- Do not attempt the test using more than 12 antibody coated tubes (two of which are Standards) at the same time.
- Do not exceed incubation periods prescribed by the specific steps.
- Always follow the procedure in this user's guide.
- Usé EPA Method 8080 or Code of Federal Regulations Title 40, Part 136, Appendix A, Method 680 to confirm results.

### Storage and Handling Precautions

- Wear protective gloves and eyewear.
- Store kit at room temperature and out of direct sunlight (less than 80°F).
- Keep aluminized pouch (containing unused antibody coated tubes) sealed when not in use.
- If Stop Solution or liquid from the extraction jar comes into contact with eyes, wash thoroughly with cold water and seek immediate medical attention.
- Standard Solution contains PCBs. Test samples may contain PCBs. Handle with care.

### EPPENDORF REPEATER & MECHANICAL PIPETTE

READ: ALL INSTRUCTIONS BEFORE PROCEEDING WITH THE TEST

### HOW TO OPERATE THE EPPENDORF REPEATER

#### To Set Or Adjust Volume

To determine the pipetting volume, the dial setting (1-5) is multiplied by the minimum pipetting volume of the tip.

#### **To Assemble Pipette Tip**

Slide filling lever down until it stops. Then raise the locking clamp and insert the tip until it clicks into position. Be sure the tip plunger is fully inserted into the barrel before lowering the locking clamp to affix the tip in place.

#### To Fill Tip

With tip mounted in position on pipette, immerse end of tip into solution. Slide filling lever upward slowly.

#### To Dispense Sample


Check the volume selection dial to ensure pipetting volume. Place tip inside test tube so that tip touches the inner wall of tube. Completely depress the pipetting lever.

#### To Eject Tip


Empty tip of any remaining solution into appropriate container. Raise locking clamp upward, and remove the tip.

For additional information regarding operation and use of repeater, please refer to your Eppendorf Repeater manual.

#### Mechanical Pipette



#### Eppendorf Repeater



### HOW TO OPERATE THE MECHANICAL PIPETTE

#### To Set Or Adjust Volume

Remove push-button cap and use it to loosen volume lock screw. Turn lower part of push-button to adjust volume up or down. Meter should read "060". Tighten volume lock screw and replace push-button cap.

#### To Assemble Pipette Tip

Slide larger mounting end of pipette tip onto end of pipette. Holding tip in place, press push-button until plunger rod enters pipette tip. Ensure no gap exists between piston and plunger rod.

#### **To Withdraw Sample**

With tip mounted in position on pipette, press push-button to first stop and hold it Place tip at bottom of liquid sample and slowly release push-button to withdraw measured sample. Ensure that no bubbles exist in liquid portion of sample. If bubbles exist, dispense sample and rewithdraw sample.

#### **To Dispense Sample**

Place tip into dispensing vessel (immersing end of the tip if vessel contains liquid) and slowly press pushbutton to first stop. (Do not push to second stop or tip will eject).

Remove tip from vessel and release pushbutton.

#### To Eject Tip

Press push-button to second stop. Tip is ejected.

For additional information regarding operation and use of pipette, please refe to your pipette manual.



# APPENDIX D

PCB RIS<sup>c</sup>® Soil Test Field Screening Data, May – June 1996

Data for PCB RISC® Soil Test	1. R. Semulo Date: 5/28/94 Location: FT Membersh Bess 2000	ID AOD	401 -0.04 -0.03 > 0.5	-0.40 > 0.5 -0.13	-401 -0.60 >0.5 -0.26 >50	1 7	401 -0,04 -0,31 ,0;3 0,20 S 0,20	401	40, V -0,53 >0,5	AUI -0,13 -0,39 >0,5 0,17	-A01 -0,-(2 >0,5 6,12	401 -0.39 >0.5 -0.02	-Act V -0.41 >0.5 0.02 <50	
	Operator: A:	Sample ID		7 7R52-1	1	1-4 TRG1-1	10 to 1 TR 6.3 - 401	7563-	3-4 1K64-		3-2 TR71-401	3-3 TR72-401	3-4 1273 =	1/20/95

- 7 - i

T I I

\_ #

in the second

Ē,Ē

±. .ā

		ECG Serve		Comments		-					-	-							
oil Test		Mondrewith		Interpretation		<50	<50		<50 <	< 50									
S @ <u>5</u> 5		Location: 7-7-		OD sample	S ppm	0.00	7/ /	0 2	0,32	0,32									
PCB RISC® Soil Test	_	Date: 5/28/92		Interpretation		\ \\\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\	V C /	0.51	<0.5	70.0									
Data for				OD sample	0.5 ppm	1 '		-0.40	0.12	-0 32			-						
Da		OPU		COV	Standards	7'' ''	0.5.7	+		>									
			Operator:		Sample 10			TR 75-AU1	TR76- A01	100 000	1503-401								

Part # 30965 Rev. 6

PCB RISC® Soil Test System User's Guide

1/20/95

· · · · · · · · · · · · · · · · · · ·		Da	Data for	PCB RISC® Soil Test	Sea Sc	oil Test		,
	Opporator:			Date: 5/29/94	Location: Z	Location: LT Montered BOX	De Lare	
<del>, -1,</del>	Operator							
ev. 6	Sample ID	ΦOV	OD sample	Interpretation	OD sample	Interpretation	Comments	
		Standards	<u>0.5</u> ppm		36 ppm			
/-/	1032-401	50.0-	1	>0.5	0,39	< 50	-	
	10227		<u> </u>	< 0,5	0.39	< 5.0		
, ,			1 `	40.5	0.50	< 50		•
5-1	1571 HOI	>		<0,5	0,36	150		
CB BISS	1 (CC)	7)~ -	i .	>0.5	75.0	2.50		-
)Page	1		2. 1	10.0	27.0	7 50		
4 of	TR42-		0.3C	70.07	CH.0	2.5C		
T4 Till the service of the service o	T724 3-401	<b> </b>	0.38	20.5	0.47	750		
	- F カラ							
	TRUS. 402	1,	0.34	7.0.5	0.42	450		
ر د	_		0,16	70.5	C.29	15C		
) ( ) (	TR53- AC2		-0.52	5.0<	0,35	757		
5-5 2-2	704-51-21T	1	Jh.0-	>0.5	0.41	757		
)								
1/20								
V95								• •

		Da	Data for	PCB RISC® Soil Test	S ® S	oil Test		
Pan # :								
30966	Operator:			Date: :2/29194	Location:	ET. LIGOLOGIA	Location: F1.1141717413 AVO AVO	
Rev. 1	Cl alone S	dov	OD sample	Interpretation	OD sample	Interpretation	Comments	
		Standards	0, 5 ppm		mdd 25			
7-17	TR12 - A01	<i>ئان.د-</i>	-0.32	>0.5	0.53	L 5C		
7-7	14		D.34	5.07	0,55	757		$\top$
7.5	T222-A02		0.45	70.5	(C)-47	750		
7-hpc	TE42-A02	\ <u>\</u>	20.0	70.5	0.53	7.50		
:B RISQ	ı							
Page Soil Tes		- 01	44.0	20.5	70.04	<50		
15 of 1	1.00		0.34	60.S	0.65	<50		
B V	12/4/		6.36	\$ 0 S	44.0	<50		
•	1540	>	70,01	>0.5	67.29	< 50		T
<del>-</del>	1K24-401							
•								
3/5/96								
6								

	Location: LT Mangarity October 2000	Comments															
oil Tes	T Mandarth	Interpretation		<50	450	<50	< 50	< 50		<i>u</i>	<50	450	< 50	< 50	<50	< 50	
S ® S	Location: <	OD sample	mdd <u>Oc</u>	0.68	0.55	0.43	0.56	0,43		0,46	0,38	0.39	0.33	0.59	0.60	0,52	
PCB RISC® Soil Test	 Date: 5/32/96	Interpretation		< 0,5	40.5	>0,5/	< 0.5	>0.5		10.5	20,5	40,5	>0,5	< 0.5 S.0.5	VO.5	70,5	
Data for	e	OD sample	0.5 ppm	0.45	0.01	-0.57	0.11	10.56		17.00	40.0	0.3%	0.8%	13 0	-1,03	-10,83	i k
Da	Tride	dov	Standards	10.01				>		7001			>	40 a			7
	Operator: 15.55	Ol alomes	Call Diding	1007-401	TR13-14	·	1 "	1	1241	TR15 - ACI	- h2.21		7853-	7000 100	12001	1507	1419
	·			/-/	7.7	1-3				15 of			7	7	7.0	0 x	) 7 3/5/96

PCB RISc® Soil Test		Date: 気/3c/1/k Location: Fort Michaelt 1	Interpretation OD sample Interpretation Comments	32 ppm	>05 -0.26 >50	>0.5 0.64 <50	>0.5 0.36 <50	>0.5 0.35 <50			>0.5 0.46 <50	>0.5 0.48 <50	<0.5 0.48 <50	>0.5 0.54 <50			
Data for			OD sample	mdd <u>2,0</u>	-1,02	0,57	20.7-	10.1-	-1.00	-	-1.00	-0,80	0.30	-0.76			
Da			VOD	Standards	-0.18				A		-0.19	_		<i>\_</i>			
		Operator:	Sample ID		TR 51 - AUZ	TES1-A03	TP 61 - 103	TREIN AUS.	T1272 - AC2		TROY - AOS	F	1231	TRX2 - A0.2			
	Part # 3	30966	Rev. 1		1.7	7.7	4-3	h-hpce	HISC S	Page 1	5 of 15 System U	'\ !Ser's Gu	iqe 心 い	5.4			3/5/96

Ē. 3

Data for PCB RISC® Soil Test	Date: 5/30/94 Location: FOR MOUNCKER, Birg. 2555	AOD OD sample Interpretation	Standards 0.5 ppm	AND -0 14 -0 98 # >0,5 0 40 450	70/-	7.5.7	77 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	A2 V -0,40 /0.5		7.40771 20.5 0.62 450	7	S.D. 90 0	-402 V 031	-AUS -0,57 70.5 0.51 250	A02   0.14	- NO3 V - 0.50 > 0.5 0.5 0.5 250		
	Operator:	Sample ID			) · · · · · · · · · · · · · · · · · · ·		10.3 TRUM NUS	TR.60 - A	I		.	1682-40	3 TR83-H	4.1 TR61-AUS	10 01	8-3 TIS-13-NO3	A Day	28/9

- - 9

	Location: LT Manetality Chick Co. 1800 C.	Commonte																	
oil Test	T Marralt	doitetoractal	nite protection		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	,	< 50	>50	2 4 >		<5C				·	-			
S @ <u>5</u> (	Location: 1		OD salliple	_>		/	12/20	. 0.00°	1701	7 7 7	//- 0								
PCB RISC® Soil Test	Date: 14/12/14.		Interpretation		> 0>	, ,	>0.5	> 0 <	V 9 /	0.72	< 0.5.								
Data for	70		OD sample	(7.5 ppm	3/7 (/		-0,66	69.0-		. 7/ '/7	× \		-						
Da	שמנו ז		ΔOΔ	Standards	<i>(</i> 11 (1 ) (1 )	2					>								
	Operator:		Sample ID	Diguelle 16:2535	١ _	出しいフィアン	7R53-40-40	,	<u> </u>	14 1.2 110/00	10 20 11.2	(50)							
	Ö			D.Z	1		Q 7.	37.	<u> </u>	1	1-15	\ \ \	15 of	15					

2.4



# APPENDIX E

Analytical Laboratory Data – PCB Confirmation WESTON Environmental Metrics, Inc. (Gulf Coast), June 1996

Weston Environmental Metrics. Inc. (Gulf Coast)

PCBs by GC

Report Date: 06/16/96 09:20 Work Order: 03886-076-037-0 Page: 1

DEN Ratch Nom	iber: 9606G503	Client: USA	CE-Ft. Monmout	<u>h Wor</u>	<u>k Onden: <b>03886</b></u>	<u>-076-037-0</u>	<u>Page: 1</u>
NIW DOLCH NUI		CW07 - TR04 - A0	CW07-TR12-A0	CW07-TR13-A0	CW07 - TR32 - A0	CW07 - TR33 - A0	CW07 - TR53 - A0 5
Sample Information	RFW#: Matrix: D.F.: Units:	4 001 SOIL 5.0 ug/Kg	<b>002</b> SOIL 5.0 ug/Kg	003 SOIL 50 ug/Kg	- <b>004</b> SOIL 5.0 ug/Kg	005 SOIL 10 ug/Kg	006 SOIL 5.0 ug/Kg
Surrogate:	Tetrachloro-m-xylene Decachlorobiphenyl	115 % 135 %	110 % 170 * %	D % D %	105 % 130 %	95 % 140 % ======fl	
Aroclor-1016 Aroclor-1221 Aroclor-1232 Aroclor-1242 Aroclor-1248 Aroclor-1254 Aroclor-1260	becaciffor obtification	440 U 440 U 440 U 440 U 440 U 440 U 890 U	430 U 430 U 430 U 430 U 430 U 430 U 860 U 520	4200 U 4200 U 4200 U 4200 U 4200 U 8400 U 8400 U	460 U 460 U 460 U 460 U 460 U 910 U 320	910 U 910 U 910 U 910 U 910 U 1800 U 460	480 U 480 U 480 U 480 U 480 U 970 U 1600
		ALIAS TO 21 AO		CW07-TR61-A0	CW07-TR61-A0	PBLKNY	PBLKNY BS
	cust iv.	CW07-TR61-A0	CW07-TR61-A0			FULKINI	PDLNN1 DO
Sample Information	RFW#: Matrix: D.F.: Units:	CWU/- IR61-AU 1 007 SOIL 250 ug/Kg	CW07-TR61-AU 1 007 MS SOIL 250 ug/Kg	1 007 MSD SOIL 250 ug/Kg	5 008 SOTU 50 ug/Kg	96GP0563-MB1 SOIL 0.50 ug/Kg	96GP0563-MB1 SOIL 0.50 ug/Kg
	RFW#: Matrix: D.F.:	1 007 SOIL 250 ug/Kg	1 007 MS SOIL. 250 ug/Kg	1 007 MSD SOIL 250	5 008 SOIL 50 ug/Kg	96GP0563-MB1 SOIL 0.50	96GP0563 - MB1 SOIL. 0.50

U= Analyzed, not detected. J= Present below detection limit. B= Present in blank. NR= Not requested. NS= Not spiked. %= Percent recovery. D= Diluted out. I= Interference. NA= Not Applicable. %= Outside of EPA CLP QC

Weston Environmental Metrics, Inc. (Gulf Coast)  $PCBs\ by\ GC$ 

Report Date: 06/16/96 09:20

RFW Batch Number: 9606G503

Client: USACE-Ft. Monmouth

Work Order: 03886-076-037-0

Page:

Cust ID: PBLKNY BSD

Sample Information

RFW#: 96GP0563-MB1 Matrix: SOIL

0.50 D.F.: Units: ug/Kg

Surrogate:	Tetrachloro-m-xylene Decachlorobiphenyl	85 110	% % f1	 f]====================================	`]=======f	]=====================================	`]======f]
Aroclor-122 Aroclor-123 Aroclor-124 Aroclor-124 Aroclor-125 Aroclor-126	1 2 2 2 8 4	40 40 40 40 40 40 97 80	U U U U U W			·	

U= Analyzed, not detected. J= Present below detection limit. B= Present in blank. NR= Not requested. NS= Not spiked. C= Percent recovery. D= Diluted out. I= Interference. NA= Not Applicable. C= Outside of EPA CLP QC



# APPENDIX F

Backfill Material Receipts – Sand and Stone John Guire Co., Long Branch, NJ – November 1997

JOHN GUIRE CO.  Cust. Phone  125197  Date  Cust. Phone  187 BRIGHTON AVE. LONG BRANCH, N	N.I. 07740	13698
omer's Name	6 Driver On	Off
BANKTUN FILL Price 5.83/40	Price 104 94	Other Produ
DATE TIME 18105 Gross Ib.	Tax	Always Avail ● Fuel Oil ● Hardware ● Lawn & Garden S
Tare lb. Net lb.	TOTAL 10491	● Mulch ● Top Soil & Fill ● Wall Stone
tellvered prices are for street curb delivery, except where the curb and sidewalk are entirely bridged tected and a suitable road provided to actual point of unloading inside of curb. We will assume no sibility for any damages where delivery is made inside of curb.	ap Day Jan	• Cobble Stor • Railroad Tie

. .

Mulch     Top Soil & Fill     Wall Stone     Cobble Stone     Asilroad Tit	Del. Сhg. 11 де)		nloading inside of curb. We v	ded to actual point of u	vered prices are for street curb or sability for any damages where a sibility for any damages where or
Tiblaya Yawila  iiO lau1 •  lio lau4 •  lio lau4 •  lio lau4 •	xeT lefoT du8	Gross lb.	Phol	ЭМІТ	DATE
Other Produ	Price 101 gel	p/1/28:5	MON MOUTP Per Ton	117 117	1 Jan S 10
Supplies Comments		222-0612 • FAX 908-222-8126	7 H	Citat Phone	eled embN 2 lemo
Date A	532-1678 Cust. Phone 187 BRIG	JOHN GUIRE CO.  JOHN GUIRE CO.  GHTON AVE. • LONG BRANCH  908-222-0612 • FAX 908-222-8	, N.J. 07740	Driver On	.3694 Off Supplies
DATE  DATE  Actions P.O.	Price Per TIME 18-10  Run F(1) Price Per TIME 18-10  Run F(1) Price Per Per Per Price Per Per Price Per Per Per Per Per Per Per Per Per Pe	Gross Ib. Tare Ib. Net Ib.  are entirely bridged We will assume no	Price	0494 0494	Other Products Always Availabl  • Fuel Oil  • Hardware  • Lawn & Garden Supposition  • Mulch  • Top Soil & Fill Dir  • Wall Stone  • Cobble Stone  • Railroad Ties
<u> </u>	K TEcom-1	Weigher JOHN GUIRE CO. HTON AVE. • LONG BRANCH, 108-222-0612 • FAX 908-222-812		<b>1</b> Driver On	.3695 Off
BANK TOU	Ff. Mon mou	on 5.83/40/	Price DL  Tax  Sub Total  Del. Chg	194 	Other Products Always Available • Fuel Oil • Hardware • Lawn & Garden Suppl • Mulch • Top Soil & Fill Dirt

DATE Ctions P. O	Ten EIII  TIME  7297-019	18403	Gross lb. Tare lb. Net lb.	Price	Other Produc Always Availal  Fuel Oil Hardware Lawn & Garden Su Mulch Top Soil & Fill C Wall Stone Cobble Stone
: ected and a suitable road	curb delivery, except where the cur provided to actual point of unloadin here delivery is made inside of curb	g inside of curb, We will as		(M. P. L. Cu)	far_ BILLING C
Date : et's Name	Officers Ff Mon	187 BRIGHTON AV 908-222-0 1 N N C I C I C D · Price	N GUIRE CO. /E. • LONG BRANCH, 612 • FAX 908-222-81		Supplies
DATE	TOUN FILL	1840s	Gross lb. Tare lb. Net lb.	Tax Sub Total	Other Products Always Availabl  Fuel Oil Hardware  Lawn & Garden Sup Mulch Top Soil & Fill Dir
> ited and a suitable road pr	to delivery, except where the curb a ovided to actual point of unloading in the delivery is made inside of curb.	and sidewalk are entirely b	  ridged Rec'd By ime no Weigher	Chy Day	Wall Stone     Cobble Stone     Railroad Ties  BILLING CO
s Name	Cum-VIMME FICENS CLU T. Manma	87 BRIGHTŐÑ ÀVÉ. 908-222-0612 して しな	GUIRE CO. • LONG BRANCH, N. 2 • FAX 908-222-8126		1.3674 Off Supplies
DATE	MMW FIII	Price 5 6	Gross lb.	Price	Other Products Always Available • Fuel Oil • Hardware • Lawn & Garden Supplie
' and a suitable road provid	elivery, except where the curb and ded to actual point of unloading insi elivery is made inside of curb			TOTAL 104 9th	Top Soil & Fill Dirt  Wall Stone Cobble Stone Railroad Ties  Bil LING COP

DATE ctions	TIME	Price Per Ton 5	Gross lb. Tare lb. Net lb.	Price 104 94  Tax  Sub Total  Del. Chg.  TOTAL	Other Products Always Availabl  Fuel Oil Hardware  Lawn & Garden Supp Mulch Top Soil & Fill Dir Wall Stone
21)-97 Pate	urb delivery, except where the curt provided to actual point of unloadin are delivery is made inside of curb ON 97-01798 Cust. Phone	g inside of curb. We will assur JOHN 187 BRIGHTON AVE 908-222-06			• Railroad Ties  BILLING CO  Off Off Supplies
DATE	FFICEN CLUB T. MORING PLUN FILL TIME	enth.	Gross lb. Tare lb. Net lb.	Price 104 94  Tax  Sub Total  Del. Chg.	Other Products Always Available  • Fuel Oil  • Hardware  • Lawn & Garden Supp  • Mulch  • Top Soil & Fill Dirt
e ad and a suitable road pro	b delivery, except where the curb ovided to actual point of unloading e delivery is made inside of curb.			Chellag Jan.	Wall Stone     Cobble Stone     Railroad Ties  BILLING COF
Date Branch Date er's Name	11.97-01/98 Scust Phone SCOM - MINN OFFICENS C FT. MOUNT	187 BRIGHTON AVI 908-222-06	N GUIRE CO. E. LONG BRANCH, 612 • FAX 908-222-81		13676 n Off Supplies

ng prices are for street curb delivery, except where the curb and sidewark are entirely bridged ted and a suitable road provided to actual point of unloading inside of curb. We will assume no ity for any damages where delivery is made inside of curb.

Weigher

BILLING CO

Day	Ю. Г.	Price 7	583/4d	Price 101	194	
13HW/	MIN FILL	Per Ton -	5 / 14	Price	7 -	Other Products
3		16		Tax		<i>Always Available</i> ● Fuel Oil
<sup>1</sup> DATE	TIME			14A		Hardware
J.		YAMOS	Gross lb.	Sub Total	<del></del> ,	• Lawn & Garden Supplies
1	•	•	Tare lb.	Dal Ohr	; ´	• Mulch
		<del></del>	_ Net lb.	Del. Chg.	1194	• Top Soil & Fill Dirt
∄.∕actions				TOTAL 10	7 2,	<ul><li>Wall Stone</li><li>Cobble Stone</li></ul>
1.			- •	$\alpha \cap \alpha$	$\wedge$	Railroad Ties
	•		_	( 12/1) Ca	La	
	elivery, except where the curb an led to actual point of unloading in:			<u> </u>	1)	
iny damages where de	elivery is made inside of curb.	1 %	Weigher	· `	<del></del>	BILLING COPY
97 1201	12.97-01793		I OUIDE OO		1	3889
101	<u> </u>	14,0	N GUIRE CO. E. • LONG BRANCH, N.	ر کے لیے 1 07740		
· Logi.			12 • FAX 908-222-8126	0. 0	Driver On _	Off
ame E	con- Vin	WELL				Supplies
	DEFICERS	Clnb.			<del></del>	• •
	FT. MOON					
F	11	Price	5.83 YAMP	1	OH OU	Othor Drodest
1		Per Ton		Price	04.94	Other Products Always Available
i		THE STATE	5-17	Tax		• Fuel Oil
³ 'ATE	TIME	JAK DE	•	19A		Hardware
J		10 1/3	Gross Ib.	Sub Total		• Lawn & Garden Supplies
		Aleksin	Tare lb.	Dal Oha		• Mulch
Pierra and an artist of the second	_		₋ Net Ib.	Del. Chg.	laucos	• Top Soil & Fill Dirt
Actions -JOE	126GER3	1100		TOTAL	104.94	<ul><li>◆ Wall Stone</li><li>◆ Cobble Stone</li></ul>
1.	532-	16 18	•	$\sim$ $\sim$ $\sim$	Δ·	Railroad Ties
3-	· · · · · · · · · · · · · · · · · · ·			1/2/1/01/10	Ch.	
ices are for street curb del	livery, except where the curb and ed to actual point of unloading ins	l sidewalk are entirely brid ide of curb. We will assum	dged Rec'd By ne no	- Cop O g	1	·
	livery is made inside of curb		Weigher	·		BILLING COPY
G7 17 F	31007 01060			ميعودين والمماكنات والمناقين والماكان	to the first of th	
10.	17-97-01798		IN GUIRE CO.	46 . / 6		13888
1000	Cust. Phone		VE. • LONG BRANCH, 1 0612 • FAX 908-222-812		Driver On	Off
	Econ · Ur	MEN				Supplies
, Name	OFFICERS	Chb.	· · · · · · · · · · · · · · · · · · ·	<del>-</del>		Oupplies
9	FT. MON.					
, F		Price	502		1011011	,
F1)	12	Per Ton	583 yrn	Price	104.94	Other Products
j.		_ ) ,	1			Always Available
, .	TILAT	TOU DEW	1	Tax		• Fuel Oil
DATE	TIME	His	Gross Ib.	Sub Total		<ul><li>Hardware</li><li>Lawn &amp; Garden Supplies</li></ul>
		JAns	Tare lb.		·	• Mulch
		•	Net lb.	Del. Chg		● Top Soil & Fill Dirt
ctions				TOTAL	104.94	Wall Stone
			<b>.</b>		4	Cobble Stone     Delirord Ties
_			<u> </u>	$\Omega \cap A \cap A$	Λ.	• Railroad Ties
	delivery, except where the curb a			MI Va	Nu	· 
	rided to actual point of unloading delivery is made inside of curb.	Inside of curb. We will ass	ume no Weigher	Ι	CI ·	BILLING COPY
			1 • 1 · 1 · 1 · 1 · 1 · 1 · 1 · 1 · 1 ·			

F-12)	Price Per Ton	7.0 Jun	Price	Other Produc Always Availai
DATE TIME	JAND,	Gross lb. Tare lb. Net lb.	Sub Total  Del. Ch'g.  TOTAL  104.91	• Fuel Oil • Hardware • Lawn & Garden Su • Mulch • Top Soil & Fill I • Wall Stone • Cobble Stone • Railroad Ties
d prices are for street curb delivery, except w ed and a suitable road provided to actual poi ty for any damages where delivery is made	nt of unloading inside of curb. We will assu	me no	Benut	
OFFICE	187 BRIGHTON A' 908-222-0 VITTED EOS CLUB	IN GUIRE CO. VE. • LONG BRANCH, N 0612 • FAX 908-222-8126	i.J. 07740	13886 n Off Supplies
F112	Price Per Ton	5.23 pm	Price 104.94	Other Produ Always Availa • Fuel Oil
DATE TIME	- Hausen	Gross lb. Tare lb. Net lb.	Del. Chg.	Hardware  ■ Lawn & Garden S  ■ Mulch  ■ Top Soil & Fill  ■ Wall Stone
ed prices are for street curb delivery, except ted and a suitable road provided to actual po lity for any damages where delivery is made	oint of unloading inside of curb. We will ass		ap Deephy	Cobble Stor     Railroad Tie  BILLING
Date Po N.97  Cust. Phone  er's Name TErom	187 BRIGHTON AN 908-222-0 - VI mmizz	IN GUIRE CO. VE. • LONG BRANCH, N 0612 • FAX 908-222-8126		13887 ——— Off — Supplies
OFFICI FILL	Price Per Ton	5.83	104.921	Other Produ
DATE TIME	- Just	7130	Sub Total  Del. Chg.	Always Availa  • Fuel Oil  • Hardware  • Lawn & Garden S  • Mulch  • Top Soil & Fill  • Wall Stone
Tar.		- 	TOTAL	Cobble Stor     Railroad Tie

ा :ct	1-12)	Price Per Ton	5.83 1903	Price	
DATE	TIME	Mass	Gross lb. Tare lb.	Sub Total	→ Always Availa  • Fuel Oil • Hardware • Lawn & Garden St
an arctions			Net lb.	· ·	• Top Soil & Fill I • Wall Stone • Cobble Stone • Railroad Ties
1 protected and a suitable r	eet curb delivery, except where the curoad provided to actual point of unloadies where delivery is made inside of cur	ng inside of curb. We will assur	ne no Weigher		BILLING C
11.11.11 Date \$		187 BRIGHTON AVE 908-222-06	GUIRE CO.   • LONG BRANCH, N   12 • FAX 908-222-8126		13875 Driver On Off
stomer's Name	OFFICERS.	CLID CA		<u></u>	Supplies
) ct	FI. In	Price Per Ton	5.83 yano	Price	494 Other Produc
DATE	TIME	My Carry	Gross lb. Tare lb.	Tax	Always Availaí  • Fuel Oil  • Hardware  • Lawn & Garden Su
ictions ()	EL PARMING LO	T = Lub	Net lb.	TOTAL	• Mulch • Top Soil & Fill E • Wall Stone • Cobble Stone
nretected and a suitable re	et curb delivery, except where the curb bad provided to actual point of unloading s where delivery is made inside of curb	b and sidewalk are entirely brid og inside of curb. We will assum	aged Rec'd By	Clip Dros	• Railroad Ties  Hand BILLING C
1.14.97 Date (20)	2-97-01798 Cust. Pflone	187 BRIGHTON AVE. 908-222-061	GUIRE CO.  • LONG BRANCH, N.  2 • FAX 908-222-8126	J. 07740	13872 Oriver On Off
tomer's Name	From - Vim	tmp Ltr			Supplies
1	FILL	Price Per Ton	583 yam	Price	194 Other Product: Always Availab
DATE	TIME	Manos	Gross lb. Tare lb.	Tax	• Fuel Oil • Hardware • Lawn & Garden Sup • Mulch
ctions			Net lb.	TOTAL /	• Top Soil & Fill Di • Wall Stone • Cobble Stone • Railroad Ties
roted and a suitable roa	t curb delivery, except where the curb id provided to actual point of unloading where delivery is made inside of curb.			up Vaya	BILLING CO

	Fili	Price Per Ton	583 ynr	Price	Other Products
DATE	TIME	JS ypne	Gross lb. Tare lb.	Tax	Always Available  • Fuel Oil  • Hardware  • Lawn & Garden Supp  • Mulch
ictions	<u> </u>		Net lb.  	TOTAL 104.94	<ul> <li>Top Soil &amp; Fill Dirt</li> <li>Wall Stone</li> <li>Cobble Stone</li> <li>Raliroad Ties</li> </ul>
Rand a suitable road	curb delivery, except where the curb d provided to actual point of unloadin there delivery is made inside of curb	g inside of curb. We will ass	oridged Rec'd By ume no Weigher	up engyag	BILLING CO
ate rs Name	N-97-01798  Cust. Pflone  TECOM - VI	187 BRIGHTON A 908-222-	1N GUIRE CO. WE. • LONG BRANCH, N. 0612 • FAX 908-222-8126 272 W & N° !	J. 07740 Driver Or	13868 Off
S Name	OFFICER				
	F.12)	Price Per Ton	15.83 yazz	Price 104,94	Other Products Always Availabl
DATE	TIME	18 YAN	GIOSS ID.	Tax	● Fuel Oil ● Hardware ・ Lawn & Garden Sup
actions	<u> </u>		Tare lb Net lb.	Del. Chg	<ul><li>Mulch</li><li>Top Soil &amp; Fill Di</li><li>Wall Stone</li><li>Cobble Stone</li></ul>
dand a suitable roa	t curb delivery, except where the cur d provided to actual point of unloadir where deliyery is made inside of cur	ng inside of curb. We will ass	bridged Rec'd By	Cho Oasta	Railroad Ties     BILLING CC
397 ate 1999	12.97-01798  Cust. Pflone  F. 17709		IN GUIRE CO. VE. • LONG BRANCH, N. 0612 • FAX 908-222-8126	J. 07740 (L) Driver Or	13848 Off Supplies
<b>)</b>	OFF-KIED'S	Club.	T 63		
	F122	Price Per Ton	5.95 ynns	Price	Other Products Always Availabl
DATE	TIME	Atho	ク Gross Ib. Tare Ib.	Sub Total	● Fuel Oil ● Hardware ● Lawn & Garden Sup ● Mulch
FFICIE TO	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	532-1678	Net lb.	TOTAL 10494	<ul> <li>Top Soil &amp; Fill Di</li> <li>Wall Stone</li> <li>Cobble Stone</li> <li>Railroad Ties</li> </ul>
dand a suitable road	t curb delivery, except where the cur id provided to actual point of unloadir where delivery is made inside of curl	b and sidewalk are entirely ng Inside of curb. We will ass	bridged Rec'd By Weigher	up Jogla.	BILLING CO

\ <i>\_</i>		<del></del>			
fuct	F122	Price Per Ton	583 ynn	Price	Other Produ
	•	10		Tav	Always Avai
DATE	· TIME	18		Tax	• Fuel Oil • Hardward
DAIL	( )(¥( ba-	VARIOS	Gross lb.	Sub Total	- Lawn & Garden
. Johnson	•	7.	Tare lb.	Dol Che	• Mulch
	i.		Net lb.	Del. Chg.	• Top Soil & Fi
ecial		1		TOTAL 104.9	<ul><li>Wall Ston</li><li>Cobble Sto</li></ul>
				$\sim 0.00$	Railroad T
· ·			. Doold Du	(h) Vairas	
protected and a suitable r	reet curb delivery, except where the curb road provided to actual point of unloading	g inside of curb. We will assum	e no	Jay O Jan.	
onsibility for any damage	es where delivery is made inside of curb	·	Weigher		BILLING
11-13.97.0	12.97-01798	IOUN	CHIDE CO	<u>(a)</u>	13846
Date D	Cust. Pflone	187 BRIGHTON AVE	GUIRE CO. . • LONG BRANCH, N.	.J. 07740	
\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \	113°C		2 • FAX 908-222-8126	Driver Or	n Off
tomer's Name	18Com - Vinr	Y1311			Supplies
res <u>s. Ji</u>	FT. Mer.				
	OFFICIERS (	CLUD			
	FILL	Price Per Ton	5.83 ynzn	10494	· Other Produ
luct	1	1 1 61 1011		Price	Always Avail
		18		Tax	• Fuel Oil
DATE	TIME	Altros	O		Hardware
		Y /	Gross Ib.	Sub Total	• Lawn & Garden
i de la companya de l			Tare lb. Net lb.	Del. Chg.	• Mulch • Top Soil & Fil
cia			Net ID.	INHAL	
A. New	······································		•	TOTAL 1011	Cobble Sto
•			•	$\alpha \alpha \alpha \beta \beta \beta \gamma $	Railroad Ti
alluered prices are for etc.	eet curb delivery, except where the curb	and sidewalk are entirely brid	ged Rec'd By	The Jay tay	<u>.</u>
rotected and a suitable re	oad provided to actual point of unloading s where delivery is made inside of curb.	inside of curb. We will assum	e no		BILLING
			Weigher		
11.13.97	1º 12.97-01798	JOHN	I GUIRE CO.	4	13845
Date	Cust. Phone	187 BRIGHTON AVE	ீ. • LONG BRANCH, N	1.0, 07740	n Off
	TECOM - Vim		12 • FAX 908-222-8126	5 Dilled O	•
itomer's Name		1 ', 21			Supplies
Jress L	FT. MCN.	Club			
	1	CIND	/- m 2		- <del> </del>
Juct	FILL	Price Per Ton	5.83 YAM	Price	Other Produ
3001			•		Always Avai
		18.		Tax	_ • Fuel Oil
DATE	TIME	Myno,	Gross lb.	Sub Total	• Hardwar
	*	<i>1</i> * -	Tare lb.	Vus IVIAI	-
			Net lb.	Del. Chg.	- • Top Soil & Fi
ecia			<del></del>	TOTAL 10494	• Wall Ston
A. Carrier				O	• Cobble Sto
•			•	$Y \setminus A$	• Railroad T
dellineed estate are to the	and auch dallions, avenue where the such	and aldowalk are entirely bri	toed Rec'd By	Up) Dentar.	

delivered prices are for street curb delivery, except where the curb and sidewalk are entirely bridged protected and a sultable road provided to actual point of unloading inside of curb. We will assume no passibility for any duringes where delivery is made inside of curb.

Weigher

BILLING

	·············	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		N GUIRE CO.		_ U U 11 m
_ 3	Date (	Cust. Pflone		/E <sup>°.</sup> • LONG BRANCH, N 1612 • FAX 908-222-8126		ver On Off
5	omer⁵s Name _		riv El)			Supplies
ď	ress	FT. Mon.				
~ <b>]</b>		OFFICEDS C				
. j	uct	FILL	Price Per Ton	583 yrm	Price	<del></del>
L			1.71		_	Always Availa
الديد	DATE	TIME	18 mi	/ *	Tax	— • Fuel Oil — • Hardware
- n	51114	-1	y//·	Gross lb.	Sub Total	- Lawn & Garden S
: ز	- Jackson			Tare lb.	Del. Chg.	• Mulch
:	ctions			_ Net lb.	10H	● Top Soil & Fill ● Wall Stone
. J.				-	TOTAL	• Cobble Stor
7	<u> </u>	· · · · · · · · · · · · · · · · · · ·	<del>*************************************</del>	_		Railroad Tie
- 7		reet curb delivery, except where the curb			My Vayla	<u> </u>
		road provided to actual point of unloading es where delivery is made inside of curb.	inside of curb. We will assu	ume no Weigher		BILLING
7	12 6	12.00 11000	; 		<u> </u>	· · · · · · · · · · · · · · · · · · ·
<u> </u>	13:47	12.97.01.198	HOL	N GUIRE CO.	(5)	13844
a	Date , h	Cust. Pfione		E. • LONG BRANCH, N. 612 • FAX 908-222-8126	D	er On Off
ate	omer's Name _	JECOM - VIIM	F12			Supplies
	SS.EL.	I-I. Moor.				
		OFFICEDS C	-L11>			
اد الدارية وفي	ct	Fill	Price Per Ton	5.83 yans	Price	Other Produc
٠ ٦				•	11100	Always Availa
. 3	DATE	TIME	18.		Tax	● Fuel Oil
- 3	DATE	TIME	KULUN	Gross ib.	Sub Total	● Hardware ——— ● Lawn & Garden Sı
: آ ت	an and the		,	Tare lb.	. 5-1-01	• Mulch
				_ Net Ib.	Del. Chg	91/ • Top Soil & Fill i
	3) cctions			- -	TOTAL	• Cobble Ston
. 3			· · · · · · · · · · · · · · · · · · ·	- /	$0.0 \times 1$	Railroad Tie
- 3	tered prices are for sir	reet curb delivery, except where the curb	and sidewalk are entirely br	- ridged Rec'd By	he begin.	·
5 pr	<b>otected a</b> nd a suitable r	road provided to actual point of unloading es where delivery is made inside of curb.	inside of curb. We will assu			BILLING (
				TTGIGHTEL		
_ 5 <u>/4</u>	1397	12-97-01798	НОГ	Ŋ GUIRE CO.	.6	13843
<del>.</del>	Date	Cust Phone		/E.  • LONG BRANCH, N 612  • FAX 908-222-8126	.3. 0/ /40	ver On Off
. <u>.</u>	√	TECOM - VIM				Supplies
الا د	3\$8	FT: mor.			· · · · · · · · · · · · · · · · · · ·	<u> </u>
		OFFICERS	Club			
ر <sub>-</sub> •	ct	FILL	Price Per Ton	5.83 yans	Price10H.9	어 Other Produc
	V				•	Always Availa
	DATE	TIME	18		Tax	Fuel Oil  Hardware
- 1	DATE	HIVIC	AHUL	Gross lb.	Sub Total	- Hardware - Lawn & Garden S:
	a should be		·	Tare lb.	Dal Chair	- • Mulch
			•	41_4 1L	Del. Cha	A Tan Call 9 Eill



# APPENDIX G

Site Health & Safety Plan Prepared by TECOM-Vinell Services, dated 10 November 1997 SITE HEALTH AND SAFETY PLAN

Site Name:

Gibbs Hall

Date:

11/10/97

Prepared By:

Beth Welmaker

TVS

With the assistance of HASP

# \*\* Table of Contents \*\*

1.0	INTRODUCTION1-1
1.1	Scope and Applicability of the Site Health and Safety Plan1-1
1.2	Visitors1-1
2.0	KEY PERSONNEL/IDENTIFICATION OF HEALTH AND SAFETY2-
2.1 <sup>-</sup>	Key Personnel2-1
2.2	Site Specific Health and Safety Personnel2-1
2.3	Organizational Responsibility2-1
3.0	TASK/OPERATION SAFETY AND HEALTH RISK ANALYSIS3-1
3.1	Historical Overview of Site3-1
3.2	Task by Task Risk Analysis3-1
4.0	PERSONNEL TRAINING REQUIREMENTS4-1
4.1	Preassignment and Annual Refresher Training4-1
4.2	Site Supervisors Training4-1
4.3	Training and Briefing Topics4-1
5.0	PERSONAL PROTECTIVE EQUIPMENT TO BE USED5-1
5.1	Levels of Protection5-1
5.2	Level A Personnel Protective Equipment5-2
5.3	Level B Personnel Protective Equipment5-2
5.4	Level C Personnel Protective Equipment5-3
5.5	Level D Personnel Protective Equipment5-4
5.6	Reassessment of Protection Program5-4
5.7	Work Mission Duration5-4
5.8	Chemical Resistance and Integrity of Protective Material5-5
5.9	.5 SCBA Inspection & Checkout5-6
5.1	0.1 Inspection5-8

6.0 MEDICAL SURVEILLANCE REQUIREMENTS6-1
6.1 Baseline or Preassignment Monitoring6-1
6.2 Periodic Monitoring6-1
6.3 Site Specific Medical Monitoring6-1
6.4 Exposure/Injury/Medical Support6-2
6.5 Exit Physical6-2
7.0 FREQUENCY AND TYPES OF AIR MONITORING/SAMPLING7-
7.1 Direct-Reading Monitoring Instruments7-1
7.3.1 Site Air Monitoring and Sampling Program7-6
8.0 SITE CONTROL MEASURES8-1
8.1 Buddy System8-1
8.2 Site Communications Plan8-1
8.3 Work Zone Definition8-1
8.4 Nearest Medical Assistance8-2
8.5 Safe Work Practices8-2
8.6 Emergency Alarm Procedures8-2
9.0 DECONTAMINATION PLAN9-1
9.1 Standard Operating Procedures9-1
9.2 Levels of Decontamination Protection Required for Personnel9-1
9.3 Equipment Decontamination9-1
9.4 Disposition of Decontamination Wastes9-1
10.0 EMERGENCY RESPONSE/CONTINGENCY PLAN10-1
10.1 Pre-Emergency Planning10-1
10.2 Personnel Roles and Lines of Authority10-1
10.3 Emergency Recognition/Prevention10-1
10.4 Evacuation Routes/Procedures10-2
10.7 Emergency Contact/Notification System10-5

10.8 Emergency Medical Treatment Procedures
10.9 Fire or Explosion10-7
10.10 Spill or Leaks10-7
10.11 Emergency Equipment/Facilities10-7
11.0 CONFINED SPACE ENTRY PROCEDURES11-1
11.1 Definitions11-1
11.2 General Provisions
11.3 Procedure for Confined Space Entry11-3
11.4 Confined Space Observer

#### 1.0 INTRODUCTION

This section of the Site Health and Safety Plan (HASP) document defines general applicability and general responsibilities with respect to compliance with Health and Safety programs.

1.1 Scope and Applicability of the Site Health and Safety Plan

The purpose of this Site Health and Safety Plan is to define the requirements and designate protocols to be followed at the Site during investigation and remediation activities. Applicability extends to all Government employees, contractors, subcontractors, and visitors.

All personnel on site, contractors and subcontractors included, shall be informed of the site emergency response procedures and any potential fire, explosion, health, or safety hazards of the operation. This HASP summarizes those hazards in table 3.1 and defines protective measures planned for the site.

This plan must be reviewed and an agreement to comply with the requirements must be signed by all personnel prior to entering the exclusion zone or contamination reduction zone.

During development of this plan consideration was given to current safety standards as defined by EPA/OSHA/NIOSH, health effects and standards for known contaminants, and procedures designed to account for the potential for exposure to unknown substances. Specifically, the following reference sources have been consulted:

- o OSHA 29 CFR 1910.120 and EPA 40 CFR 311
- o NIOSH/OSHA/USCG/EPA Occ. Health and Safety Guidelines
- U.S. EPA, OERR ERT Standard Operating Safety Guides
- o (ACGIH) Threshold Limit Values

#### 1.2 Visitors

All visitors entering the contamination reduction zone and exclusion zone at the the Site will be required to read and verify compliance with the provisions of this HASP. In addition, visitors will be expected to comply with relevant OSHA requirements such as medical monitoring (Sec. 6.0), training (Sec. 4.0), and respiratory protection (if applicable). Visitors will also be expected to provide their own protective equipment.

In the event that a visitor does not adhere to the provisions of the HASP, he/she will be requested to leave the work area.

All nonconformance incidents will be recorded in the site log.

## 2.0 KEY PERSONNEL/IDENTIFICATION OF HEALTH AND SAFETY

### 2.1 Key Personnel

The following personnel and organizations are critical to the planned activities at the Site. The organizational structure will be reviewed and updated periodically by the site supervisor.

DPW

Joe Fallon

# 2.2 Site Specific Health and Safety Personnel

The Site Health and Safety Officer (HSO) has total responsibility for ensuring that the provisions of this HASP are adequate and implemented in the field. Changing field conditions may require decisions to be made concerning adequate protection programs. Therefore, it is vital that personnel assigned as HSO be experienced and meet the additional training requirements specified by OSHA in 29 CFR 1910.120 (see Section 4.0 of this HASP). The HSO is also responsible for conducting site inspections on a regular basis in order to ensure the effectiveness of this plan.

The HSO at the site is Beth Welmaker

Designated alternates include:

- o Karen Roach
- 2.3 Organizational Responsibility

The project direction and responsibility will be under the direction of Joe Fallon, Environmental Specialist with DPW.

### 3.3 Task Hazard Descriptions

## Clearing/grading:

General hazards encountered during mobilization include the following:

- o Back strain from clearing vegetation for road construction with a scythe or other cutting tool.
- o Irritation from dust generated from road construction.
- o Driving vehicles, placing trailers, and collecting rubbish, on uneven surfaces creates a possibility of the vehicle rolling, getting stuck in mud or ditches, or of an accident due to flat tires or striking obstacles, and the vehicles.
- o Crushing or pinching hazard due to trailer placement.
- Several types of hazards can be associated with utility hook-up depending on the particular work activity.
   Construction of temporary poles for electrical and/or telephone lines can disturb potentially contaminated soils.

#### HAZARD PREVENTION

- Back strain can be prevented by frequent breaks in routine. Use slow, even, movements and proper lifting techniques (i.e., with the legs). Work gloves will reduce the incidence of hand injury and blisters associated with hand scything.
- Dust suppression techniques, i.e., wetting the soil with water, will reduce dust exposure.
- o Proper vehicle maintenance will prevent avoidable vehicle breakdown in the field. In order to minimize accidents from uneven terrain, a site surveillance should be performed on foot to choose a clear driving path.
- o Seatbelts should be worn at all times.
- At a minimum, all heavy equipment shall have the safety features outlined in OSHA 29 CFR 1910/1926 Subpart 0.

- Heavy equipment operators should have proper training and experience, and documentation of both. The general provisions of 1910/1926 would apply.
- Hazards associated with the particular utility would be anticipated and proper measures should be undertaken by the subcontractor employer. General provisions of 29 CFR 1910/1926 Subpart K, should be implemented in order to prevent electrical hazards.

### Rubble collection/disposal:

General hazards encountered during mobilization include the following:

- o Back strain from clearing vegetation for road construction with a scythe or other cutting tool.
- o Irritation from dust generated from road construction.
- o Driving vehicles, placing trailers, and collecting rubbish, on uneven surfaces creates a possibility of the vehicle rolling, getting stuck in mud or ditches, or of an accident due to flat tires or striking obstacles, and the vehicles.
- o Crushing or pinching hazard due to trailer placement.
- Several types of hazards can be associated with utility hook-up depending on the particular work activity.
   Construction of temporary poles for electrical and/or telephone lines can disturb potentially contaminated soils.

#### HAZARD PREVENTION

- Back strain can be prevented by frequent breaks in routine. Use slow, even, movements and proper lifting techniques (i.e., with the legs). Work gloves will reduce the incidence of hand injury and blisters associated with hand scything.
- Dust suppression techniques, i.e., wetting the soil with water, will reduce dust exposure.
- o Proper vehicle maintenance will prevent avoidable

vehicle breakdown in the field. In order to minimize accidents from uneven terrain, a site surveillance should be performed on foot to choose a clear driving path.

- Seatbelts should be worn at all times.
- At a minimum, all heavy equipment shall have the safety features outlined in OSHA 29 CFR 1910/1926 Subpart 0.
- Heavy equipment operators should have proper training and experience, and documentation of both. The general provisions of 1910/1926 would apply.
- o Hazards associated with the particular utility would be anticipated and proper measures should be undertaken by the subcontractor employer. General provisions of 29 CFR 1910/1926 Subpart K, should be implemented in order to prevent electrical hazards.

#### Soil excavations:

Hazards encountered during soil and test pit excavation include both chemical and physical agents, and are as follows:

- Exposure to airborne contaminants released during intrusive activities. Flammable atmospheres encountered in excavation.
- Sides of excavation can cave in. Possible burying or crushing of workers due to 1) absence of shoring, 2) misjudgement of stability, 3) defective shoring, and/or 4) undercut sides.
- Falling during access/egress or while monitoring or dismounting equipment, or stumbling into excavation.
- An overhead hazard can result from material, tools, rock, and/or soil falling into the excavation.
- Congested work area due to too many workers in a small area

### HAZARD PREVENTION

- o Monitor for airborne contaminants. Allow test pits to purge and/or use personal protective equipment.
- Provide adequate shoring or sloping of sides of the excavation. Regularly inspect trenches for changing conditions.

Solid rock, cemented sand or gravel = 90 degrees

Compact angular gravel = 63 degrees 26 ft. deep

Compacted sharp sand = 33 degrees 41 ft. deep

Rounded loose sand = 26 degrees 34 ft. deep

- o Provide ramps or ladders to trenches to allow safe access and egress.
- o Provide an adequate barrier around open pits. Material from pit must be placed away from edge to prevent cave ins and instability of pit.
- o To prevent overexertion, limit manual lifting and emphasize mechanical means where practical.
- o Maintain ample work room between workers.

substance in the ambient atmosphere and its toxicity.

- Potential for exposure to substances in air liquids, or other direct contact with material due to work being done.
- o Knowledge of chemicals on-site along with properties such as toxicity, route of exposure, and contaminant matrix.

In situations where the type of chemical, concentration, and possibilities of contact are not known, the appropriate Level of Protection must be selected based on professional experience and judgment until the hazards can be better identified.

### 5.2 Level A Personnel Protective Equipment:

- o Supplied-air respirator approved by the Mine Safety and Health Administration (MSHA) and National Institute for Occupational Safety and Health (NIOSH). Respirators may be positive pressure-demand, self-contained breathing apparatus (SCBA), or positive pressure-demand, airline respirator (with escape bottle for Immediately Dangerous to Life and Health (IDLH) or potential for IDLH atmosphere)
- o Fully encapsulating chemical-resistant suit
- o Coveralls
- o Long cotton underwear
- o Gloves (inner)
- o Boots, chemical-resistant, steel toe and shank (depending on suit construction, worn over or under suit boot)
- o Hard hat (under suit)
- o Disposable gloves and boot covers (worn over fully encapsulating suit)
- o Cooling unit
- o 2-way radio communications (intrinsically safe)

### 5.3 Level B Personnel Protective Equipment:

Supplied-air respirator (MSHA/NIOSH approved).
 Respirators may be positive pressure-demand.
 self-contained breathing apparatus (SCBA), or positive

- o Monitor for airborne contaminants. Allow test pits to purge and/or use personal protective equipment.
- Provide adequate shoring or sloping of sides of the excavation. Regularly inspect trenches for changing conditions.

Solid rock, cemented sand or gravel = 90 degrees

Compact angular gravel = 63 degrees 26 ft. deep

Compacted sharp sand = 33 degrees 41 ft. deep

Rounded loose sand = 26 degrees 34 ft. deep

- Provide ramps or ladders to trenches to allow safe access and egress.
- o Provide an adequate barrier around open pits. Material from pit must be placed away from edge to prevent cave ins and instability of pit.
- o To prevent overexertion, limit manual lifting and emphasize mechanical means where practical.
- o Maintain ample work room between workers.

#### 3.4 Physical Hazards

### General Description:

### POLYCHLORINATED BIPHENYLS-

Polychlorinate biphenyls are colorless to light colored liquids. They are used as coolants in transformers and in electrical capacitors. They are insoluble in water. They are non-volatile and non-combustible. They are extremely persistent in the environment. ((C)AAR, 1986)

#### Health Hazards:

POLYCHLORINATED BIPHENYLS-LIQUID OR SOLID: Irritating to skin and eyes. (USCG, 1985)

Fire/Explosion Hazards:

POLYCHLORINATED BIPHENYLS-Combustible. Irritating gases are generated in fires. (USCG, 1985)

#### First Aid:

#### POLYCHLORINATED BIPHENYLS-

If this chemical comes in contact with the eyes, immediately wash the eyes with large amounts of water, occasionally lifting the lower and upper lids. Get medical attention immediately. Contact lenses should not be worn when working with this chemical. If this chemical comes in contact with the skin, immediately wash the contaminated skin with soap and water. If this chemical penetrates through the clothing, immediately remove the clothing, wash the skin with soap and water, get medical attention promptly. If a person breathes in large amounts of this chemical, move the exposed person to fresh air at once. If breathing has stopped, perform artificial respiration. Keep the affected person warm and at rest. Get medical attention as soon as possible. If this chemical has been swallowed, get medical attention immediately. (NIOSH, 1987)

substance in the ambient atmosphere and its toxicity.

- Potential for exposure to substances in air liquids, or other direct contact with material due to work being done.
- o Knowledge of chemicals on-site along with properties such as toxicity, route of exposure, and contaminant matrix.

In situations where the type of chemical, concentration, and possibilities of contact are not known, the appropriate Level of Protection must be selected based on professional experience and judgment until the hazards can be better identified.

## 5.2 Level A Personnel Protective Equipment:

- o Supplied-air respirator approved by the Mine Safety and Health Administration (MSHA) and National Institute for Occupational Safety and Health (NIOSH). Respirators may be positive pressure-demand, self-contained breathing apparatus (SCBA), or positive pressure-demand, airline respirator (with escape bottle for Immediately Dangerous to Life and Health (IDLH) or potential for IDLH atmosphere)
- o Fully encapsulating chemical-resistant suit
- o Coveralis
- o Long cotton underwear
- o Gloves (inner)
- o Boots, chemical-resistant, steel toe and shank (depending on suit construction, worn over or under suit boot)
- o Hard hat (under suit)
- o Disposable gloves and boot covers (worn over fully encapsulating suit)
- o Cooling unit
- o 2-way radio communications (intrinsically safe)

#### 5.3 Level B Personnel Protective Equipment:

Supplied-air respirator (MSHA/NIOSH approved).
 Respirators may be positive pressure-demand,
 self-contained breathing apparatus (SCBA), or positive

pressure-demand, airline respirator (with escape bottle for IDLH or potential for IDLH atmosphere)

- o Chemical-resistant clothing (overalls and long-sleeved jacket; hooded, one or two-piece chemical-splash suit; disposable chemical-resistant, one-piece suits)
- o Long cotton underwear
- o Coveralls
- o Gloves (outer), chemical-resistant
- o Gloves (inner), chemical-resistant
- o Boots (outer), chemical-resistant, steel toe and shank
- o Boot covers (outer), chemical-resistant (disposable)
- o Hard hat (face shield)
- o 2-way radio communications (intrinsically safe)
- 5.4 Level C Personnel Protective Equipment:
  - Air-purifying respirator, full-face, cartridge-equipped (MSHA/NIOSH approved)
  - o Chemical-resistant clothing (coveralls; hooded, one-piece or two-piece chemical splash suit; chemical-resistant hood and apron; disposable chemical-resistant coveralls)
  - o Coveralls
  - o Long cotton underwear
- o Gloves (outer), chemical-resistant
- o Gloves (inner), chemical-resistant
- o Boots (outer), chemical-resistant, steel toe and shank
- o Boot covers (outer), chemical-resistant (disposable)
- o Hard hat (face shield)
- o Escape mask
- o 2-way radio communications (intrinsically safe)

# 5.5 Level D Personnel Protective Equipment:

- o Coveralls
- o Gloves
- Boots/shoes, leath or chemical-resistant, steel toe and shank
- o Safety glasses
- o Hard hat

### 5.6 Reassessment of Protection Program

The Level of Protection provided by PPE selection shall be upgraded or downgraded based upon a change in site conditions or findings of investigations.

When a significant change occurs, the hazards should be reassessed. Some indicators of the need for reassessment are:

- Commencement of a new work phase, such as the start of drum sampling or work that begins on a different portion of the site.
- o Change in job tasks during a work phase.
- o Change of season/weather.
- o When temperature extremes or individual medical considerations limit the effectiveness of PPE.
- Contaminants other than those previously identified are encountered.
- o Change in ambient levels of contaminants.
- o Change in work scope which effects the degree of contact with contaminants.

#### 5.7 Work Mission Duration

Before the workers actually begin work in their PPE ensembles the anticipated duration of the work mission should be established. Several factors limit mission length, including:

o Air supply consumption (SCBA use).

- o Suit/Ensemble permeation and penetration rates for chemicals (section 5.8).
- o Ambient temperature and weather conditions (heat stress cold stress).
- o Capacity of personnel to work in PPE.
- 5.8 Chemical Resistance and Integrity of Protective Material

The following specific clothing materials are recommended for the site:

Clearing/grading - (Level B)

Inner Gloves - Surgical

Boots/Boot Covers - Steel Toe

Outer Gloves - Work Gloves

Outer Garment/Coveralls - Tyvek

Rubble collection/disposal - (Level B)

Inner Gloves - Surgical

Boots/Boot Covers - TYVEK

Outer Gloves - Work Gloves

Outer Garment/Coveralls - Tyvek

Soil excavations - (Level B)

Inner Gloves - Surgical

Boots/Boot Covers - Latex

Outer Gloves - Work Gloves

Outer Garment/Coveralls - Tyvek

5.9 SOP for Respiratory Protection Devices

The following subsections define standard operating procedures

November 10, 1997

PERSONAL PROTECTIVE EQUIPMENT TO BE [5-5]

for air purifying respirators and self-contained breathing apparatus.

5.9.4 Cleaning and Disinfecting Self Contained Breathing Apparatus

Cleaning procedures for Self Contained Breathing Apparatus (SCBA) facepieces are identical to those for Ultratwin APRs. The backpiece is cleaned with cleaning solution and a brush. Following cleaning, the facepiece is combined with the regulator and an operational check is performed.

## 5.9.5 SCBA Inspection & Checkout

## Monthly Inspection:

- Check cylinder label for current hydrostatic test date.
- 2. Inspect cylinder for large dents or gouges.
- 3. Inspect cylinder gauge for damage.
- 4. Complete routine inspection.
- 5. Fill out the appropriate records with results and recommendations.

Routine Inspection: Perform immediately prior to donning or after cleaning.

- 1. Before proceeding, check that the:
- o High-pressure hose connector is tight on cylinder fitting.
- o By-pass valve is closed.
- o Mainline valve is closed.
- Regulator outlet is not covered or obstructed.
- 2. Backpack and harness assembly:
- Visually inspect straps for wear, damage, and completeness.
- o Check wear and function of belt.
- o Check backplate and cylinder holder for damage.
- 3. Cylinder and high pressure hose assembly:
- o Check cylinder to assure that it is firmly attached to backplate.
- o Open cylinder valve; listen or feel for leakage

- around packing and hose connection.
- o Check high pressure hose for damage or leaks.
- 4. Regulator:
- o Cover regulator outlet with palm of hand.
- o Open mainline valve.
- o Note stoppage of air flow after positive pressure builds.
- o Close mainline valve.
- o Remove hand from regulator outlet.
- o Open by-pass valve slowly to assure proper function.
- o Close by-pass valve.
- o Open mainline valve.
- o Note pressure reading on regulator gauge.
- o Close cylinder valve while keeping hand over regulator outlet.
- o Slowly remove hand from outlet and allow air to
- o Note pressure when low-pressure warning alarm sounds; it should be between 550-650 psi.
- o Remove hand from regulator outlet.
- o Close mainline valve.
- o Check regulator for leaks by blowing air into regulator for 5-10 seconds. Draw air from outlet for 5-10 seconds. If a positive pressure or vacuum cannot be maintained there is a leak. DO NOT USE SCBA.
- 5. Facepiece and corrugated breathing hose:
- o Inspect hand harness and facepiece for damage, serrations, and deteriorated rubber.
- o Inspect lens for damage and proper seal in facepiece. Inspect exhalation valve for damage and dirt build-up.
- o Stretch breathing hose and carefully inspect for holes and deterioration.
- o Inspect connector for damage and presence of washer.
- o Perform negative pressure test with facepiece donned.

- 6. Storage:
- o Refill cylinder to 2216 psi.
- o Close cylinder valve.
- o Tightly connect high pressure hose to cylinder.
- Bleed pressure from high pressure hose by opening mainline valve.
- o Close by-pass valve.
- o Close mainline valve.
- o Fully extend all straps.
- o Store facepiece in a clean plastic bag for protection.

## 5.10 SOP for Personal Protective

## 5.10.1 Inspection

Proper inspection of PPE features several sequences of inspection depending upon specific articles of PPE and it's frequency of use. The different levels of inspection are as follows:

Inspection and operational testing of equipment received from the factory or distributor.

Inspection of equipment as it is issued to workers.

Inspection after use or training and prior to maintenance.

Periodic inspection of stored equipment.

Periodic inspection when a question arises concerning the appropriateness of the selected equipment, or when problems with similar equipment arise.

The primary inspection of PPE in use for activities at the Site will occur prior to immediate use and will be conducted by the user. This ensures that the specific device or article has been checked-out by the user that the user is familiar with its use.

# Table 5.1 Sample PPE Inspection Checklists

## CLOTHING

#### Before use:

- Determine that the clothing material is correct for the specified task at hand.
- o Visually inspect for:
  - imperfect seams
  - non-uniform coatings
  - tears
  - malfunctioning closures
- o Hold up to light and check for pinholes.
- o Flex product:
  - observe for cracks
  - observe for other signs of shelf deterioration
- o If the product has been used previously, inspect inside and out for signs of chemical attack:
  - discoloration
  - swelling
  - stiffness

## During the work task

- o Evidence of chemical attack such as discoloration, swelling, stiffening, and softening. Keep in mind, however, that chemical permeation can occur without any visible effects.
- o Closure failure.
- o Tears.
- o Punctures.
- o Seam Discontinuities.

# **GLOVES**

# Before use:

- o Visually inspect for:
  - imperfect seams
  - tears
  - non-uniform coating
  - pressurize glove with air; listen for pin-hole leaks.

# 5.11 Specific Levels of Protection Planned for the Site

The following levels of protection will be utilized during activities at the Site:

o Level B

Table 5.2 presents the level of protection planned for the completion of individual task assignments and the specific components of each protective ensemble.

# TABLE 5.2 SPECIFIC LEVELS OF PROTECTION PLANNED FOR THE TASK ASSIGNMENTS AT THE SITE

LEVEL A Tasks

LEVEL A Tasks (modified)

## LEVEL B Tasks

- o Clearing/grading
- o Rubble collection/disposal
- o Soil excavations

LEVEL B Tasks (modified)

LEVEL C Tasks

LEVEL C Tasks (modified)

LEVEL D Tasks

LEVEL D Tasks (modified)

## 6.0 MEDICAL SURVEILLANCE REQUIREMENTS

Medical monitoring programs are designed to track the physical condition of employees on a regular basis as well as survey preemployment or baseline conditions prior to potential exposures. The medical surveillance program is a part of each employers Health and Safety program.

#### 6.1 Baseline or Preassignment Monitoring

Prior to being assigned to a hazardous or a potentially hazardous activity involving exposure to toxic materials employee must receive a preassignment or baseline physical. The contents of the physical is to be determined by the employers medical consultant. As suggested by NIOSH/OSHA/USCG/EPA's Occupational Safety & Health Guidance Manual for Hazardous Waste Site Activities, the minimum medical monitoring requirements for work at the Site is as follows:

- Complete medical and work histories.
- Physical examination.
- Pulmonary function tests (FVC and FEV1).
- Chest X-ray (every 2 years).
- EKG
- Eye examination and visual acuity.
- Audiometry.
- Urinalysis.
- Blood chemistry and heavy metals toxicology.

The preassignment physical should categorize employees as fit-for-duty and able to wear respiratory protection.

#### 6.2 Periodic Monitoring

In addition to a baseline physical, all employees require a periodic physical within the last 12 months unless the advising physician believes a shorter interval is appropriate. The employers medical consultant should prescribe an adequate medical which fulfills OSHA 29 CFR 1910.120 requirements. The preassignment medical outlined above may be applicable.

All personnel working in contaminated or potentially contaminated area's at the Site will verify currency (within 12 months) with respect to medical monitoring. This is done by indicating date of last physical on the safety plan agreement form.

6.3 Site Specific Medical Monitoring

For activities at the Site, the following specific tests will be required prior to individuals entering the Exclusion Zone or Contamination Reduction Zone.

## 6.4 Exposure/Injury/Medical Support

As a follow-up to an injury or possible exposure above established exposure limits, all employees are entitled to and encouraged to seek medical attention and physical testing. Depending upon the type of exposure, it is critical to perform follow-up testing within 24-48 hours. It will be up to the employers medical consultant to advise the type of test required to accurately monitor for exposure effects.

## 6.5 Exit Physical

At termination of employment or reassignment to an activity or location which does not represent a risk of exposure to hazardous substances, an employee shall require an exit physical. If his/her last physical was within the last 6 months, the advising medical consultant has the right to determine adequacy and necessity of exit exam.

# 7.0 FREQUENCY AND TYPES OF AIR MONITORING/SAMPLING

This section explains the general concepts of an air monitoring program and specifies the surveillance activities that will take place during project completion at the Site.

The purpose of air monitoring is to identify and quantify airborn contaminants in order to verify and determine the level of worker protection needed. Initial screening for identification is often qualitative, i.e., the contaminant, or the class to which it belongs, is demonstrated to be present but the determination of its concentration (quantification) must await subsequent testing. Two principal approaches are available for identifying and/or quantifying airborne contaminants:

- o The onsite use of direct-reading instruments.
- Laboratory analysis of air samples obtained by gas sampling bag, collection media (i.e., filter, sorbent), and/or wet-contaminant collection methods.

## 7.1 Direct-Reading Monitoring Instruments

Unlike air sampling devices, which are used to collect samples for subsequent analysis in a laboratory, direct-reading instruments provide information at the time of sampling, enabling rapid decision-making. Data obtained from the real-time monitors are used to assure proper selection of personnel protection equipment, engineering controls, and work practices. Overall, the instruments provide the user the capability to determine if site personnel are being exposed to concentrations which exceed exposure limits or action levels for specific hazardous materials.

Of significant importance, especially during initial entries, is the potential for IDLH conditions or oxygen deficient atmospheres. Real-time monitors can be useful in identifying any IDLH conditions, toxic levels of airborne contaminants, flammable atmospheres, or radioactive hazards. Periodic monitoring of conditions is critical, especially if exposures may have increased since initial monitoring or if new site activities have commenced.

Table 7.1. excerpted from Occupational Safety and Health Guidelines for Hazardous Waste Site Activities, provides an overview of available monitoring instrumentation and their specific operating parameters.

# TABLE 7.1 SOME DIRECT-READING INSTRUMENTS FOR GENERAL SURVEY

Instrument: Combustible gas indicator (CGI)

Hazard Monitored: Combustible gases and vapors.

Application: Measures the concentration of a combustible gas or vapor.

Detection Method: A filament, usually made of platinum, is heated by burning the combustible gas of vapor. The increase in heat is measured. Gases and vapors are ionized in a flame. A current is produced in proportion to the number of carbon atoms present.

General Care/Maintenance: Recharge or replace battery. Calibrate immediatly before use.

Typical Operating Time: Can be used for as long as the battery lasts, or for the recommended interval between calibrations, whichever is less.

Instrument: Flame Ionization Detector (FID) with Gas Chromatography Option. Example: Foxboro OVA.

Hazard Monitored: Many organic gases and vapors.

Application: In survey mode, detects the concentration of many organic gases and vapors. In gas chromatography (GC) mode identifies and measures specific compounds. In survey mode, all the organic compounds are ionized and detected at the same time. In GC mode, volatile species are separated.

General Care/Maintenance: Recharge or replace battery. Monitor fuel and/or combustion air supply gauges. Perform routine maintenance as described in the manual. Check for leaks.

Typical Operating Time: 8 hours; 3 hours with strip chart recorder.

Instrument: Portable Infrared (IR) Spectrophotometer

Hazard Monitored: Many gases and vapors.

Application: Measures concentration of many gases and vapors in air. Designed to quantify one or two component mixtures.

Detection Method: Passes different frequencies of IR through the sample. The frequencies absorbed are specific for each compound.

General Care/Maintenance: As specified by manufacturer.

Instrument: Ultraviolet (UV) Photoionization Detector (PID) Example: HNU.

Hazard Monitored: Many organic and some inorganic gases and vapors.

Application: Detects total concentration of many organic and some inorganic gases and vapors. Some identification of compounds are possible if more than one probe is measured.

Detection Method: Ionizes molecules using UV radiation; produces a current that is proportional to the number of ions.

General Care/Maintenance: Recharge or replace battery. Regularly clean lamp window. Regularly clean an maintain the instrument and accessories.

Typical Operating Time: 10 hours. 5 hours with strip chart recorder.

Instrument: Direct Reading Colorimetric Indicator Tube

Hazard Measured: Specific gas and vapors.

Application: Measures concentration of specific gases and vapors.

Detection Method: The compound reacts with the indicator chemical in the tube, producing a stain whose length or color change is proportional to the compound's concentration.

General Care/Maintenance: Do not use a previously opened tube even if the indicator chemical is not stained. Check pump for leaks before and after use. Refrigerate before use to maintain a shelf life of about 2 years. Check expiration date of tubes. Calibrate pump volume at least quarterly. Avoid rough handling which may cause channeling.

Instrument: Oxygen Meter

Hazard Monitored: Oxygen (O2)

Application: Measures the percentage of O2 in the air.

Detection Method: Uses an electrochemical sensor to measure the partial pressure of O2 in the air, and converts that reading to O2 concentration.

General Care/Maintenance: Replace detector cell according to manufacturers recomendations. Recharge or replace batteries prior to expiration of the specified interval. If the ambient air is more than 0.5% CO2, replace the detector cell frequently.

Typical Operating Time: 8-12 hours.

Instrument: Real Time Aerosol Monitor

Hazard Monitored: Particulates

Application: Measures total particulates in air.

Detection Method: Uses an internal light source. The particulates defract the light beam and the amount of diffraction is converted into concentration (mg/m3).

General Care/Maintenance: Recharge batteries. Replace dessicant when necessary.

Typical Operating Time: 8-12 hours.

Instrument: Monitox

Hazard Moniored: Gases and Vapors

Application: Measures specific gases and vapors

Detection Method: Electrochemical sensor relatively specific for the chemical species in question.

General Care/Maintenance: Moisten sponge before use; check the function swith; change the battery when needed.

Instruments: Gamma Radiation Survey Instrument

Hazard Monitored: Gamma Radiation

Application: Environmental radiation monitor

Detection Method: Scintillation detector

General Care/Maintanence: Must be calibrated annually at a specialized facility.

Typical Operating Time: Can be used for as long as tha battery lasts, or for the recommended interval between calibrations, whichever is less.

After site mitigation activities have commenced, the selective monitoring of high-risk workers, i.e., those who are closest to the source of contaminant generation, is essential. Personal monitoring samples should be collected in the breathing zone and, if workers are wearing respiratory protective equipment, outside the facepiece.

Those employees working closest with the source have the highest likelihood of being exposed to concentrations which exceed established exposure limits. Representative sampling approaches emphasizing worst case conditions, those employees with the greatest risk of exposure, is acceptable. However, the sampling strategy may change if the operation or tasks change onsite or if exposures potentially increase.

7.3 Specific Contaminants to be monitored at the Site

The following checklist provides a summary of the contaminants to be monitored for and frequency/schedule of monitoring. The air sampling checklist will serve as a site monitoring plan.

# 7.3.1 Site Air Monitoring and Sampling Program

## A. Air Monitoring Instruments

Flame Ionization Detector (FID)

Frequency: Twice daily - once in morning and once in afternoon Locations:

Upwind and downwind of site activities Near residents, etc.

#### B. Action Levels

## Particulates:

Action Level Action

Depends on contaminant

Consult standard reference manuals for air concentration/toxicity data. Action level depends on PEL/REL/TLV. Action Level is 1/2 the current standard. See Table 3.1.

# C. Reporting Format

- o Trip report
- o Field notebook
- o Air monitoring log

#### **8.0 SITE CONTROL MEASURES**

The following section defines measures and procedures for maintaining site control. Site control is an essential component in the implementation of the site health and safety program.

#### 8.1 Buddy System

During all Level B activities or when some conditions present a risk to personnel, the implementation of a buddy system is mandatory. A buddy system requires at least two people who work as a team; each looking out for each other. For example, Level B operations generally require three people. Table 8.1 lists those tasks which require a buddy system and any additional site control requirements.

#### 8.2 Site Communications Plan

Successful communications between field teams and contact with personnel in the support zone is essential. The following communications systems will be available during activities at the Site.

- o Two-way radio
- o Intrinsically safe radio
- o Whistle
- o Hand Signals

Signal	Definition
***	***
Hands clutching throat	Out of air/cannot breath
Hands on top of head	Need assistance
Thumbs up	OK/I am all right/I understand
Thumbs down	No/negative
Arms waving upright	Send backup support
Grip partners wrist	Exit area immediately

#### 8.3 Work Zone Definition

The three general work zones established at the Site are the Exclusion Zone, Contamination Reduction Zone, and Support Zone. Figure 8.1 provides a site map with the work zones designated on it.

The Exclusion Zone is defined as the area where contamination is either known or likely to be present, or because of activity, will provide a potential to cause harm to personnel. Entry into the Exclusion Zone requires the use of personnel protective equipment.

The Contamination Reduction Zone is the area where personnel conduct personal and equipment decontamination. It is essentially a buffer zone between contaminated areas and clean areas. Activities to be conducted in this zone will require personal protection as defined in the decontamination plan.

The Support Zone is situated in clean areas where the chance to encounter hazardous materials or conditions is minimal. Personal protective equipment is therefore not required.

#### 8.4 Nearest Medical Assistance

Figure 8.2 provides a map of the route to the nearest medical facility which can provide emergency care for individuals who may experience an injury or exposure on-site. The route to the hospital should be verified by the HSO, and should be familiar to all site personnel.

The following individuals on site have current certification in CPR and/or first aid:

o Joe Rogers

#### 8.5 Safe Work Practices

Table 8.2 provides a list of standing orders for the Exclusion Zone.

Table 8.3 provides a list of standing orders for the Contamination Reduction Zone.

#### 8.6 Emergency Alarm Procedures

The warning signals described in section 10.4 "Evacuation Routes and Procedures," will be deployed in the event of an emergency. Communication signals will also be used according to section 8.2.

# TABLE 8.1. PERSONNEL REQUIREMENTS

Task Control Measures Comments

\*\*Clearing/grading
Buddy system
Line of Sight

\*\*Rubble collection/disposal
Buddy system
Line of Sight

\*\*Soil excavations
Buddy system

Line of Sight

FIGURE 8.1 SITE MAP DEPICTING WORK ZONES





FIGURE 8.2
MAP DEPICTING ROUTE TO NEAREST MEDICAL FACILITIES



# TABLE 8.2 STANDING ORDERS FOR EXCLUSION ZONE

- o No smoking, eating, or drinking in this zone.
- o No horse play.
- o No matches or lighters in this zone.
- o Check-in on entrance to this zone.
- o Check-out on exit from this zone.
- o Implement the communications system.
- o Line of sight must be in position.
- o Wear the appropriate level of protection as defined in the Safety Plan.

# TABLE 8.3 STANDING ORDERS FOR CONTAMINATION REDUCTION ZONE

- o No smoking, eating, or drinking in this zone.
- o No horse play.
- o No matches or lighters in this zone.
- o Wear the appropriate level of protection.

#### 9.0 DECONTAMINATION PLAN

Table 5.2 lists the tasks and specific levels of protection required for each task. Consistent with the levels of protection required, the decontamination figure provides a step by step representation of the personnel decontamination process for either level A, B, or C. These procedures should be modified to suit site conditions and protective ensembles in use.

#### 9.1 Standard Operating Procedures

Decontamination involves the orderly controlled removal of contaminants. Standard decontamination sequences are presented in the decontamination figure. All site personnel should minimize contact with contaminants in order to minimize the need for extensive decon.

### 9.2 Levels of Decontamination Protection Required for Personnel

The levels of protection required for personnel assisting with decontamination will be Level B

The Site Safety Officer is responsible for monitoring decontamination procedures and determining their effectiveness.

#### 9.3 Equipment Decontamination

Sampling equipment will be decontaminated in accordance with procedures as defined in the work plan, Chapter 9

The sequence of decontamination steps required for non-sampling equipment and heavy machinery can be found in the Quality Assurance Sampling Plan.

#### 9.4 Disposition of Decontamination Wastes

All equipment and solvents used for decontamination shall be decontaminated or disposed of properly. Commercial laundries or cleaning establishments that decontaminate protective clothing or equipment shall be informed of the potentially harmful effects of exposures.

# FIGURE 9.1. LEVEL A DECONTAMINATION STEPS

- Step 1 Segregated equipment drop
- Step 2 Boot cover and glove wash
- Step 3 Boot cover and glove rinse
- Step 4 Tape removal boot and glove
- Step 5 Boot cover removal
- Step 6 Outer glove removal
- Step 7 Suit/safety boot wash
- Step 8 Suit/safety boot rinse
- Step 9 Safety boot removal
- Step 10 Fully encapsulating suit and hard hat removal
- Step 11 SCBA backpack removal
- Step 12 Inner glove wash
- Step 13 Inner glove rinse
- Step 14 Face piece removal
- Step 15 Innver glove removal
- Step 16 Inner clothing removal
- Step 17 Field wash
- Step 18 Redress

# FIGURE 9.2. LEVEL B DECONTAMINATION STEPS

- Step 1 Segregated equipment drop
- Step 2 Boot cover and glove wash
- Step 3 Boot cover and glove rinse
- Step 4 Tape removal outer glove and boot
- Step 5 Boot cover removal
- Step 6 Outer glove removal
- Step 7 Suit/safety boot wash
- Step 8 Suit/SCBA/boot/glove rinse
- Step 9 Safety boot removal
- Step 10 SCBA backpack removal
- Step 11 Splash suit removal
- Step 12 Inner glove wash
- Step 13 Inner glove rinse
- Step 14 Face piece removal
- Step 15 Inner glove removal
- Step 16 Inner clothing removal
- Step 17 Field wash
- Step 18 Redress

# FIGURE 9.3. LEVEL C DECONTAMINATION STEPS

- Step 1 Segregated equipment drop
- Step 2 Boot cover and glove wash
- Step 3 Boot cover and glove rinse
- Step 4 Tape removal
- Step 5 Boot cover removal
- Step 6 Outer glove removal
- Step 7 Suit/safety boot wash
- Step 8 Suit/safety boot rinse
- Step 9 Safety boot removal
- Step 10 Splash suit removal
- Step 11 Inner glove wash
- Step 12 Inner glove rinse
- Step 13 Face piece removal
- Step 14 Inner glove removal
- Step 15 Inner clothing removal
- Step 16 Field wash
- Step 17 Redress

# FIGURE 9.4. LEVEL D DECONTAMINATION STEPS

Step 1 Remove outer garments (i.e., coveralls)

Step 2 Remove gloves

Step 3 Wash hands and face

# 10.0 EMERGENCY RESPONSE/CONTINGENCY PLAN

This section describes contingencies and emergency planning procedures to be implemented at the Site. This plan is compatible with local, state and federal disaster and emergency management plans as appropriate.

### 10.1 Pre-Emergency Planning

During the site briefings held periodically/daily, all employees will be trained in and reminded of provisions of the emergency response plan, communication systems, and evacuation routes. Table 10.1 identifies the hazardous conditions associated with specific site activities. The plan will be reviewed and revised if necessary, on a regular basis by the HSO. This will ensure that the plan is adequate and consistent with prevailing site conditions.

## 10.2 Personnel Roles and Lines of Authority

The Site Supervisor has primary responsibility for responding to and correcting emergency situations. This includes taking appropriate measure to ensure the safety of site personnel and the public. Possible actions may involve evacuation of personnel from the site area, and evacuation of adjacent residents. He/she is additionally responsible for ensuring that corrective measures have been implemented, appropriate authorities notified, and follow-up reports completed. The HSO may be called upon to act on the behalf of the site supervisor, and will direct responses to any medical emergency. The individual contractor organizations are responsible for assisting the project manager in his/her mission within the parameters of their scope of work.

The Site Supervisor(s): Joe Rogers.

The HSO is Beth Welmaker

Alternates are:

o Karen Roach

#### 10.3 Emergency Recognition/Prevention

Table 3.1 provides a listing of chemical and physical hazards onsite. Additional hazards as a direct result of site activities are listed in Table 10.1 as are prevention and control techniques/mechanisms. Personnel will be familiar with techniques of hazard recognition from preassignment training

and site specific briefings. The HSO is responsible for ensuring that prevention devices or equipment is available to personnel.

## 10.4 Evacuation Routes/Procedures

In the event of an emergency which necessitates an evacuation of the site, the following alarm procedures will be implemented:

Evacuation alarm notification should be made using three short blasts on the air horn, supplemented using the hand held radios. All personnel should evacuate upwind of any activities. Insure that a predetermined location is identified off-site in case of an emergency, so that all personnel can be accounted for.

Personnel will be expected to proceed to the closest exit with your buddy, and mobilize to the safe distance area associated with the evacuation route. Personnel will remain at that area until the re-entry alarm is sounded or an authorized individual provides further instructions.

# TABLE 10.1 EMERGENCY RECOGNITION/CONTROL MEASURES

HAZARD	PREVENTION/CONTROL	LOCATION
Fire/Explosion	Fire Extinguisher Alarm System Fire Inspections	On Vehicle
Spill	Berms/Dikes Sorbent Materials Foams	Contact the Fire Dept.
Air Release	Water Spray Foam Alarm System Evacuation Routes	

Figure 10.1 provides a map depicting evacuation routes for the site and immediate area. Also indicated are muster areas and safe distances in the event of a major incident.

## 10.7 Emergency Contact/Notification System

The following list provides names and telephone numbers for emergency contact personnel. In the event of a medical emergency, personnel will take direction from the HSO and notify the appropriate emergency organization. In the event of a fire or spill, the site supervisor will notify the appropriate local, state, and federal agencies.

Organization	Contact	Telephone
Ambulance:	Work Control	<del></del>
Police:	Work Condo	911
Fire:		911
State Police:		911
Hospital 1:		911
Hospital 2:		
Poison Control Center		
Regional EPA:		
EPA Emergency Response	Team	908-321-6660
State Authority:		
National Response Center	·	800-424-8802
Center for Disease Control		404-488-4100
Chemtrec		800-424-9555

FIGURE 10.1 **EVACUATION ROUTES AND SAFE DISTANCES** Tinton Falls FORT POWELL COURTS LAGOON 2021 OFFICER'S OPEN \ MESS \ 2000 SWIMMING POOL HOUSING 2022

## 10.8 Emergency Medical Treatment Procedures

Any person who becomes ill or injured in the exclusion zone must be decontaminated to the maximum extent possible. If the injury or illness is minor, full decontamination should be completed and first aid administered prior to transport. If the patient's condition is serious, at least partial decontamination should be completed (i.e., complete disrobing of the victim and redressing in clean coveralls or wrapping in a blanket.) First aid should be administered while awaiting an ambulance or paramedics. All injuries and illnesses must immediately be reported to the project manager.

Any person being transported to a clinic or hospital for treatment should take with them information on the chemical(s) they have been exposed to at the site. This information is included in Table 3.1.

Any vehicle used to transport contaminated personnel will be treated and cleaned as necessary.

## 10.9 Fire or Explosion

In the event of a fire or explosion, the local fire department should be summoned immediately. Upon their arrival, the project manager or designated alternate will advise the fire commander of the location, nature, and identification of the hazardous materials onsite.

If it is safe to do so, site personnel may:

- o Use fire fighting equipment available onsite to control or extinguish the fire, and,
- o Remove or isolate flammable or other hazardous materials which may contribute to the fire.

## 10.10 Spill or Leaks

In the event of a spill or a leak, site personnel will:

- o Inform their supervisor immediately;
- Locate the source of the spillage and stop the flow if it can be done safely; and,
- o Begin containment and recovery of the spilled materials.

## 10.11 Emergency Equipment/Facilities

Figure 10.2 provides a map of the site and identifies the location of the following emergency equipment:

- o First aid kit
- o Fire extinguisher

# 11.0 CONFINED SPACE ENTRY PROCEDURES

No Confined Space Entries Will Be Performed

## 12.0 SPILL CONTAINMENT PROGRAM

The procedures defined in this section comprise the spill containment program in place for activities at the Site.

- All drums and containers used during the clean-up shall meet the appropriate DOT, OSHA, and EPA regulators for the waste that they will contain.
- o Drums and containers shall be inspected and their integrity assured prior to being moved. Drums or containers that cannot be inspected before being moved because of storage conditions, shall be positioned in an accessible location and inspected prior to further handling.
- Operations on site will be organized so as to minmize the amount of drum or container movement.
- o Employees involved in the drum or container operations shall be warned of the hazards associated with the containers.
- o Where spills, leaks, or ruptures may occur, adequate quantities of spill containment equipment (absorbent, pillows, etc.) will be stationed in the immediate area. The spill containment program must be sufficient to contain and isolate the entire volume of hazardous substances being transferred.
- o Drums or containers that cannot be moved without failure, shall be emptied into a sound container.
- Fire extinguishing equipment meeting 29 CFR part 1910.
   subpart 1 shall be on hand and ready for use to control fires.

# 13.0 HAZARD COMMUNICATION

In order to comply with 29 CFR 1910.1200, Hazard Communication, the following written Hazard Communication Program has been established. All employees will be briefed on this program, and have a written copy for review.

## A. CONTAINER LABELING

All containers received on site will be inspected to ensure the following: (1) all containers will be clearly labeled as to the contents; (2) the appropriate hazard warnings will be noted; and (3) the name and address of the manufacturer will be listed.

All secondary containers will be labeled with either an extra copy of the original manufacturer's label or with generic labels which have a block for identify and blocks for the hazard warning.

# B. MATERIAL SAFETY DATA SHEETS (MSDSs)

Copies of MSDSs for all hazardous chemicals known or suspected on site will be maintained in the work area. MSDSs will be available to all employees for review during each work shift.

# C. EMPLOYEE TRAINING AND INFORMATION

Prior to starting work, each employee will attend a health and safety orientation and will receive information and training on the following: (1) an overview of the requirements contained in the Hazard Communication Standard, 29 CFR 1910.1200;

- (2) chemicals present in their workplace operations;
- (3) location and availability of a written hazard program;
- (4) physical and health effects of the hazardous chemicals;
- (5) methods and observation techniques used to determine the presence or release of hazardous chemicals; (6) how to lessen or prevent exposure to these hazardous chemicals through usage of control/work practices and personal protective equipment; (7) emergency procedures to follow if they are exposed to these chemicals; (8) how to read labels and review MSDSs to obtain appropriate hazard information; (9) location of MSDS file and location of hazardous chemical list.



## APPENDIX H

Post-Excavation Soil Analytical Data Packages
Fort Monmouth Environmental Testing Laboratory – Analytical Data Report
Project CW-7, Lab ID #:3165, 10 December 1997

# FORT MONMOUTH ENVIRONMENTAL TESTING LABORATORY

# **DIRECTORATE OF PUBLIC WORKS**

PHONE: (732) 532-6224 FAX: (732) 532-6263

WET-CHEM - METALS - ORGANICS - FIELD SAMPLING CERTIFICATIONS: NJDEP #13461, NYSDOH #11699



# ANALYTICAL DATA REPORT Fort Monmouth Environmental Laboratory ENVIRONMENTAL DIVISION Fort Monmouth, New Jersey PROJECT: CW-7

Bldg. 2000/PCB's

	Diug	. ZUUU/P	OD 3	
Field Sample Location	Laboratory	Matrix	Date and Time	Date Received
•	Sample ID#		of Collection	
A2 96-102"	3165.01	Soil	19-Nov-97 15:35	11/19/97
B2 96-102"	3165.02	Soil	19-Nov-97 15:25	11/19/97
C 96-102"	3165.03	Soil	19-Nev-97 15:15	11/19/97
D 96-102"	3165.04	Soil	19-Nov-97 15:30	11/19/97
E 96-102"	3165.05	Soil	19-Nov-97 15:20	11/19/97
F 96-102"	3165.06	Soil	19-Nov-97 15:10	11/19/97
A1 0-6"	3168.01	Soil	20-Nov-97 10:22	11/20/97
B1 0-6"	3168.02	Soil	20-Nov-97 10:25	11/20/97
C1 0=6"	3168.03	Soil	20=Nov=97 10:29	11/20/97
G 72-78"	3168.04	Soil	20-Nov-97 14:15	11/20/97
H 72-78"	3168.05	Soil	20-Nov-97 14:20	11/20/97
172-78"	3168.06	Soil	20-Nov-97 14:25	11/20/97
J 48-54"	3178.01	Soil	21-Nov-97 16:00	11/25/97
K 48-54"	3178.02	Soil	21-Nov-97 16:03	11/25/97
L 48-54"	3178.03	Soil	21-Nov-97 16:06	11/25/97
M 48-54"	3178.04	Soil	21-Nov-97 16:09	11/25/97
N 48-54"	3178.05	Soil	21-Nov-97 16:12	11/25/97
O 48-54"	3178.06	Soil	21-Nov-97 16:15	11/25/97
P 48-54"	3179.01	Soil	23-Nov-97 14:46	11/25/97
Q 48-54"	3179.02	Soil	23-Nov-97 14:49	11/25/97
R 48-54"	3179.03	Soil	23-Nov-97 14:52	11/25/97
S 48-54"	3179.04	Soil	23-Nov-97 14:55	11/25/97
T 48-54"	3179.05	Soil	23-Nov-97 14:59	11/25/97
U 48-54"	3179.06	Soil	23-Nov-97 15:02	11/25/97
V1 0-6*	3179.07	Soil	23-Nov-97 15:05	11/25/97
V2 48-54"	3179.08	Soil	23-Nov-97 15:08	11/25/97
W 24-30"	3182.01	Soil	25-Nov-97 14:33	11/25/97
X 24-30"	3182.02	Soil	25-Nov-97 14:36	11/25/97
Y 24-30"	3182.03	Soil	25-Nov-97 14:39	11/25/97
Z 24-30"	3182.04	Soil	25-Nov-97 14:42	11/25/97
AA 24-30"	3182.05	Soil	25-Nov-97 14:45	11/25/97
BB 24-30"	3182.06	Soil	25-Nov-97 14:48	11/25/97

# SAMPLE LOCATION AND IDENTIFICATION

CC 24-30"	3182.07	Soil	25-Nov-97 14:48	11/25/97
DD 24-30"	3182.08	Soil	25-Nov-97 14:50	11/25/97
EE1 0-6"	3182.09	Soil	25-Nov-97 14:52	11/25/97
EE2 24-30"	3182.10	Soil	25-Nov-97 14:54	11/25/97
FF 24-30"	3182.11	Soil	25-Nov-97 14:56	11/25/97
GG 24-30"	3182.12	Soil	25-Nov-97 14:58	11/25/97
HH 24-30"	3182.13	Soil	25-Nov-97 15:00	11/25/97
II 0-6"	3182.14	Soil	25-Nov-97 15:03	11/25/97
JJ 0-6"	3182.15	Soil	25-Nov-97 15:05	11/25/97
KK 0-6*	3182.16	Soil	25-Nov-97 15:08	11/25/97
LL 0-6"	3182.17	Soil	25-Nov-97 15:10	11/25/97
A1 0-6"	3299.01	Soil	27-Jan-98 09:38	01/28/98
A2 12=18"	3299.02	Soil	27-Jan-98 09:38	01/28/98
A3 24-30"	3299.03	Soil	27-Jan-98 09:38	01/28/98
A4 36-42"	3299.04	Soil	27-Jan-98 09:38	01/28/98
B1 0-6"	3299.05	Soil	27-Jan-98 10:36	01/28/98
B2 12-18"	3299.06	Soil	27-Jan-98 10:36	01/28/98
B3 24-30"	3299.07	Soil	27-Jan-98 10:36	01/28/98
B4 36-42"	3299.08	Soil	27-Jan-98 10:36	01/28/98
C1 0-6"	3299.09	Soil	27-Jan-98 11:14	01/28/98
C2 12-18"	3299.10	Soil	27-Jan-98 11:14	01/28/98
C3 24-30"	3299.11	Soil	27-Jan-98 11:14	01/28/98
C4 36-42"	3299.12	Soil	27-Jan-98 11:14	01/28/98
D1 0-6"	3299.13	Soil	27-Jan-98 12:57	01/28/98
D2 12-18"	3299.14	Soil	27-Jan-98 12:57	01/28/98
D3 24-30"	3299.15	Soil	27-Jan-98 12:57	01/28/98
D4 36-42"	3299.16	Soil	27-Jan-98 12:57	01/28/98
E1 0-6"	3299.17	Soil	27-Jan-98 13:47	01/28/98
E2 12=18"	3299.18	Soil	27=Jan=98 13:47	01/28/98
E3 24-30"	3299.19	Soil	27-Jan-98 13:47	01/28/98
E4 36-42"	3299.20	Soil	27-Jan-98 13:47	01/28/98
F1 0-6"	3299,21	Soil	27-Jan-98 14;31	01/28/98
F2 12-18"	3299.22	Soil	27-Jan-98 14:31	01/28/98
F3 24-30"	3299.23	Soil	27-Jan-98 14:31	01/28/98
F4 36-42"	3299.24	Soil	27-Jan-98 14:31	01/28/98
G1 0-6"	3299.25	Soil	27-Jan-98 15:15	01/28/98
G2 12-18"	3299.26	Soil	27-Jan-98 15:15	01/28/98
G3 24-30"	3299.27	Soil	27-Jan-98 15:15	01/28/98
G4 36-42"	3299.28	Soil	27-Jan-98 15:15	01/28/98
DUP	3299.29	Soil	27-Jan-98	01/28/98
Field Blank	3299.30	Soil	27-Jan-98	01/28/98
G2 144-150"	3326.01	Soil	09-Feb-98 15:00	02/09/98
H2 144-150°	3326.02	Soil	09-Feb-98 15:00	02/09/98
A3 0-6"	3330.01	Soil	10-Feb-98 10:00	02/10/98
B3 0=6"	3330.02	Soil	10-Feb-98 10:05	02/10/98

ANALYSIS:

FORT MONMOUTH ENVIRONMENTAL LAB

PCB's

Daniel Wright/Date Laboratory Director

# CHAIN OF CUSTODY

# Fort Monmouth Environmental Testing Laboratory

Bldg. 173, SELFM-PW-EV, Fort Monmouth, NJ 07703

Chain of Custody Record

Tel (908)532-4359 Fax (908)532-3484 EMail:appleby@doim6.monmouth.army.mil NJDEP Certification #13461

Remarks / Preservation Method Comments: Date/Time: Received by (signature): Received by (signature): Date/Time: Analysis Parameters Relinquished by (signature): Relinquished by (signature): 5,870 1535 50:1 Bla-2000 Beceived by (signature): Received by (signature): 075/ 1530 3751 1515 Time DAY DOS UST Project No: 2000-A2 94-102/11-11-17 Location: 文字:20 19/// Samplers Name / Company : 5/677 wear Man Date/Time: Date/Time: Sample Location (X)DERA ( )OMA ( )Other: Customer: Soe CAlle A Relinquished by (signature): Relinquished by (signature): 03 0 Lab Sample I.D. Phone #:

Remarks:

Hrs.

Days, ( )ASAP Verbal

Report Type: (JFull, (\_)Reduced, (\_)Standard, (\_)Screen / non-certified

Turnaround time: (\_)Standard 4 wks, (\_)Rush\_

Fort Monmouth Environmental Testing Laboratory

Bidg. 173, SELFM-PW-EV, Fort Monmouth, NJ 07703

Tel (908)532-4359 Fax (908)532-3484 EMail:appleby@doim6.monmouth.army.mil

Customer: 7/4 C.11.	[21]. A				
Phone **	201107	- By Br. Con market	<b>+</b>	Analysis Parameters	Comments:
rnone #: X JULCS	2.5	Location:	3		
ODERA ()OMA ()Other	Other:	1819 2000	8.		-
Samplers Name / Company:	any: Ica Ca	Non O OPW Sample	) <sub>0</sub>		
Lab Sample I.D.	Sample Location	Date, Time Type	pottles		Remarks / Drassarvation Mathed
3168,01	"9-0 1t	77 1822 Am			Netter As 1 1 Cast Validii IVEHIOL
7	19-0-18	11 /20/47/101517m			
7 50,	1. 0-6"	11/20/07/1029 PM			
) 60,	5 .72".78"	11/00/11			
-) >o;	15C-1,2C +	11/20/97			
790.	"SK-"5K-	11/2/11	>		
			8		
Relinquished by (signature):	Dete/Time: F	Received by (signature):	Relinquished by (signature):	Date/Time: Received by (signature):	ignature):
Relinquished by (signature):	Date/Time:	Refeived by (signifure):	Relinquished by (signature):	Date/Time: Received by (signature):	gnature):
Report Type: (_)Full, (_)Reduced. (_)Standard, (_)Screen / non-certified Turnaround time: (_)Standard 4 wks, (_)Rush Days, (_)ASAP Verb	ced. (_)Standard, (_)Scree 4 wks, (_)Rush Days,	)Screen / non-certified Days, ( )ASAP Verbal Hrs	Remarks:		
· .					

Bldg. 173, SELFM-PW-EV, Fort Monmouth, NJ 07703
Tel (908)532-4359 Fax (908)532-3484 EMail:appleby@doim6.monmouth.army.mil
NJDEP Certification #13461

# Fort Monmouth Environmental Testing Laboratory

Customer: Tox Fallon	Project No. S. to CW-+	Analysis Parameters	ameters	Comments:
Phone #: X 2623	Location:			
(XOERA ( )OMA ( )Other:	18145. COLD	5/1		<del></del>
Samplers Name / Company : Jour Follow	1 OM Sample	<u> </u>		
e Location	Date, Time Type	pottles		Remarks / Preservation Method
/>	11/21/17 400 Sil	×		
3	11/2/47 H.03Pm	-		1000
-	Cal			
18	11/2/47 4:00pm			
/	11/2,10			
	1,610 4150	144		-
200 000	11/2/12/17			
Relinquished by (signature): Dato/Time:	Received by (signature):	Relinquished by (signature):	Date/Time: Received by	Received by (signature):
On Fillm 11240 1:30PM	a . Carelina-			
Kelinquished by (signature): Date/Time:	Received by (signature):	Relinquished by (signature):	Date/Time: Received by	Received by (signature):
Report Type: (_)Full, (_)Reduced, (_)Standard, (_)Screen / non-certified	reen / non-certified	Remarks:		
Turnaround time: (_)Standard 4 wks, (_)RushDays, (_	iys, ( )ASAP Verbal Hrs.			

	Fort Monmo		uth Environmental Testing Laboratory	esting La	boratory
	Bidg. 173, SELFM-PW-EV, For Tel (908)532-4359 Fax (908)53 NJDEP Certification #13461		03 sy@doim6.monmouth.army.mil	Chain	Chain of Custody Record
er: 10a /	allen	Project No: 5, 16 OW-7		Analysis Parameters	Comments:
- [ ]	23	Location:	\$		
Samplers Name / Company:	100 Fally		70 [#		
Lab Sample I.D.	mple Location	Date Time	pottles		Remarks / Preservation Method
1	18,2411	m Zylepn	       		
	181-54	11/23/97 249Pm			
. 03 K	484.54111	11/22/01/52Pm			->0h7
P 40'	UK"-54"	11/23 K1255Am			
D. B.	118:85	1123/97 2598m			
7 90'	18:84	11/23/17 302 Pm			
1 70	10-01	11/23/9/205Pm			
1/ 80' /	18,31,	11/23/57 308PM	>		
Relinguished by (signature):	Date/Time:	Received by (signature):	Relinquished by (signature):	Date/Time: Received	Received by (signature):
Relinquished by (signature):	Date/Time:	Received by (signature):	Relinquished by (signature):	Date/Time: Received	Received by (signature):
<pre>Report Type: (_)Full, (_)Reduced, (_)Standard, (_)Screen / non-certified Imparming time: (_)Standard 4 wks (_)Rush</pre>	, (_)Standard, (_)Screen	en / non-certified	Remarks:		
milmomic mile.		אביים אביים			

# Fort Monmouth Environmental Testing Laboratory

Bidg. 173, SELFM-PW-EV, Fort Monmouth, NJ 07703

Tel (908)532-4359 Fax (908)532-3484 EMail:appleby@doim6.monmouth.army.mil NJDEP Certification #13461

Customer: Joz Fille A	Project No. 5.4 CC	4	Analysis	Analysis Parameters	Comments:
Phone #: X26.223					
XIDERA ( )OMA ( )Other:	1 6145 2000		-59		
Samplers Name / Company: Jog f-4/100	lon	Sample #	رد رون'		
Lab Sample I.D. Sample Location	Date 23ther T	Type bottles	7		Remarks / Preservation Method
3182.01 10 24"3"	11/242 12/4/150:1	1 13			
02 × 24-30"	1 233 Pm				
03 4 24-30"	2.3cm				7
04 2 24:30"	239Fm				
105 AA 24-3"	242 Fm				
1. 24:20					
1,08,752 77 60					
108 BO 34"30"	250 Fm				
104 EE1 6-6"					
10 EE 2 24:30"					
11 FF 24"30"					
12 65 21.3"					
"VE" HH 24"30"	m) 308				
	V 333Fm V				
hed by (signature):	Received by (signature):	Reling	Relinquished by (signature):	Date/Time: Received	Received by (signature):
X 40 Um 4540 400 K	Dilluma.	-			
Relinquished by (signature): Date/Time:	Received by (signature):	Reling	Relinquished by (signature):	Date/Time: Received	Received by (signature):
Report Type: (_)Full, (_)Reduced, (_)Standard, (_)Screen / non-certified	reen / non-certified		Remarks:		
Turnaround time: ( )Standard 4 wks, ( )Rush Da	Days, ( )ASAP Verbal Hrs.				

# Fort Monmouth Environmental Testing Laboratory

The second secon

Bldg. 173, SELFM-PW-EV, Fort Monmouth, NJ 07703

Tel (908)532-4359 Fax (908)532-3484 EMail:appleby@doim6.monmouth.army.mil

Chain of Custody Record

NJDEP Certification #13461

Justomer: 104 F	1101	Project No. 5, 1/2 (20-7)	th 12	4-1	$\vdash$		Analysis	Analysis Parameters		Comments:
"hone #: X 2 623		Location:	50.0							10.500 to 1
DERA (YOMA ( )Other:	r.	Cp19	iorr			9				
amplers Name / Company:	Ju Fallen	100	3	Sample	*	2]				6000
Lab Sample I.D.	Sample Location	Date			pottles					Remarks / Preservation Method
12/12	,, 9-0	· 6452/11	405E	1/19	/					
16 KK	0-6"	= 1	208Fm	/						1, 1.6.0
77 17	0-6"		36Pm	7		7				k~
		1	•	\	\					
						-				
							•			
					$\dashv$					
clinquished by (signature):	Date/Fime:	Received by (signature):	gnature):		Relinqu	Relinquished by (signature):	ignature):	Date/Time:	Received by (signature):	(signature):
In taken	11/12/40/40/EN	THE PROPERTY OF THE PROPERTY O	400					_		
dinquished by (signature):	Date/Time:	Refeived by (signature)			<b>Celinqu</b>	Relinquished by (signature):	ignature):	Date/Time:	Received by (signature):	(signature):
port Type: (_)Full, (_)Reduced, (_)Standard, (_)Screen / non-certified	, (_)Standard, (_)Scre	en / non-certified				Remarks:				
rnaround time: (_)Standard 4 wks, (_)Rush Days, (_)ASAP Verbal	ks, (_)RushDays	, (_)ASAP Verb	al Hrs.		1					

Page of

~me1413.xls11/17/97

print legibly

# FOI Bidg. 17 Tei (908 NJDEP

# Fort Monmouth Environmental Testing Laboratory

Bidg. 173, SELFM-PW-EV, Fort Monmouth, NJ 07703

Tel (908)532-4359 Fax (908)532-3484 EMail:appleby@doim6.monmouth.army.mil

Chain of Custody Record.

NJDEP Certification #13461

\* Remarks / Preservation Method \*= SAMPLES KEPT BELOW 4°C Comments: Received by (signature): Received by (signature): Datc/Time: Datc/Time: Analysis Parameters Relinquished by (signature): Relinquished by (signature): sarros & 5,87d Type bottles Sample Soit Project No: 97-1148 Location: B. 2000 Time 1-27-98 0938 Roccined by (sighature): Received by (signature): Samplers Name / Company: GARY DINIMATINIS - TUS Days, (\_)ASAP Verbal Report Type: (\_)Full. (\_)Reduced, (\_)Standard, (\_)Sereen / non-certified Date Date/Time: Datc/Time: Sample Location Customer: JOE FALLON - DPW 3 Turnaround time: (\_)Standard 4 wks, (\_)Rush\_ MDERA ( )OMA ( )Other: Relinquished by (signature):

Fort Monmo		estir	ig Laboratory
Tel (908)532-4359 Fax (908)532-	Fax (908)532-3484 EMail:appleby@doim6.monmouth.army.mil tion #13461		
Customer: The Fallon-Mal.	Project No. 97- //48	Analysis Parameters	Comments:
16223	2000		* SAMPLES
MDERA ( )OMA ( )Other:			76/1 00 000
s Nume / Company: GAR; DIM	#471.015-77/5 Sample # 35 55		7 C
I ab Sample I.D. Sample Location	Time Type bottles	2	Kemarks / Freservation Memod
1	1.27-8 1.257 5014 1	X	*
HQ 7/1	->		
	(34)		
20,000			
2	× 7		
27 77			i
<b>2 3 3 3 3 3 3 3 3 3 3</b>			
T (	>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		
5			
7.5 3.7 3.7 3.7 3.7 3.7 3.7 3.7 3.7 3.7 3.7			
143 1×1	→ → → →		>
Replifyished Polising aprice)	Received by (signature): Relinquished b	Relinquished by (signature): Date/Time: Received h	Received by (signature):
1444/11/2/1- VINIX 110	4. Signa		Victor by the state of the stat
Reliactushed by (signature): Date/Fime:	Received by (significate): Relinquished b	Relinquished by (signature):   Date(1 me:   Keeel Ved	Kecelved by (signature).
become of	Standard ( )Screen / non-certified Remarks:	ks:	
iii. (_)ivoutecu,	Days ( )ASAP Verbal [4rs.		

# Fort Monmouth Environmental Testing Laboratory

Bldg. 173, SELFM-FW-EV, Fort Monmouth, NJ 07703

Tel (908)532-4359 Fax (908)532-3484 EMail:appleby@doim6.monmouth.army.mil NJDEP Certification #13481


1	01111 00	Analysis Parameters Com	Comments:
Customer: Joe FALLOU-UPU	Project NO: 7/-/76		Co. O. C. Kept
Phone #: 26223	Location: 2 7,77		** SHW/CE 3 KE
ADERA ( JOMA ( JOther:	0.000		)
GARY D	MARTINIS-705 Sample	85 2 82	
Sample I D Sample Location	Date Time Type bottles	70	Remarks / Preservation Method
. 2	1.27.98 5616	X	TO DUPLICATE *
20 CA		7	FIELD BLOWK V
)	•		
	-		
			٠
, , , ,			
Residence by (sparkers): A Date Time:	Received by (signature):	Relinquished by (signature): Datc/Time: Received by (signature):	ature):
Relinquished by (signature): Date/Time:	Received by (signature):	Relinquished by (signature): Date/Time: Received by (signature):	nture):
Report Type: (_)Full. (_)Reduced. (_)Standard. (_)Sercen / non-certified	n/non-certified / ASSAP/erhal Hrs.	Remarks:	
I umaround umc: ( ) Standard + wks, ( ) Musii			

	Fort Monmo	onmouth Env	iron	mental Te	sting	outh Environmental Testing Laboratory	
	Bidg. 173, SELFM-PW-EV, For Tel (732)532-4359 Fax (732)53: NJDEP Certification #13461	Bidg. 173, SELFM-PW-EV, Fort Mommouth, NJ 07703           Tel (732)532-4359 Fax (732)532-3484 EMail:appleby@doim6.monmouth.army.mil           NJDEP Certification #13461	03 by@doim6.:	monmouth.army.mil		Chain of Custody Record	ا منت
Sustamer: (>(>)	J. T. Pallon	Project No: S' ta CW-7	4	Analysis Parameters	arameters	Comments:	
"hone #: 26333		Location:		S			
DERA ( )OMA ( )Other:		66g. 2000		<b>.</b> 187			
Samplers Name / Company:	141	Sample	**	Ū.			
I sh Sample I D.	e Location	Date Time Type	bottles			Remarks / Preservation Method	
F	OCI NAI CIC	39-98 15.00 £	14.	\ \ \			
	100 - NE	29-98 1560		×			
-							
			-				
							- 1
							ļ
							1
			-				Ì
							1
							1
			-				ļ
	-		-				J
Relinquished by (signature):	); Date/Time:	Received by (signature):	Relinqu	Relinquished by (signature):	Date/Time:	Received by (signature):	
of the Mary	0451 8640	1 / Whilehall					1
Relinquished by (signature):		Received by (signature):	Relingu	Relinquished by (signature):	Date/Time:	Received by (signature):	- 1
teport Type: (_)Full, (_)Re				Remarks:			
Turnaround time: (_)Standard 4 wks, (_)Rush	ırd 4 wks, (_)RushDa	Days, ( )ASAP Verbal Hrs.	1;				ł

60101011 - ---

	Fort Monmo		ith E	nvire	)mme	ental T	esting	Labo	uth Environmental Testing Laboratory
	Bidg. 173, SELFM-PW-EV, Fort Mommouth, NJ 07703 Tel (732)532-4359 Fax (732)532-3484 EMail:appleby@doim6.monmouth.army.mil NJDEP Certification #13461	~1	Monmouth, ] :3484 EMail	NJ 07703 :appleby@d	oim6.monn	10uth.army.mil		Chain o	Chain of Custody Record
Customer: DRU T	table C	Project No:	GITE CW-7	5-75		Analysis	Analysis Parameters		Comments:
		Location:	- -	(	S				
<b>⋈DERA ()OMA ()Other:</b>		ই	Qd 7000	30	રે દિ				
Samplers Name / Company;	A Marlio	CMO!		Sample #	DX				
Lab Sample I.D. ASar	A Sample Location	Date	Time	Type bottles					Remarks / Preservation Method
3330. 01 NAT.	A30-6"	24-01-5	3 000	-       	X				
i	130-6"			<del> </del>	~				
		•							
	:								
			ī		,				
Relinquished by (signature):	Date/Time: 3-10-18   10.30	Received by (s	(signature):	. J	inquished by	Relinquished by (signature):	Date/Time:	Received by (signature):	signature):
Kelinquished by (signature):	Date/Time:	Received by (signature):	ifenture):	Rel	inquished by	Relinquished by (signature):	Date/Time:	Received by (signature):	signature):
Report Type: (Full, ()Reduced, ()Standard, ()Screen I non-certified	()Standard, ()Scree	in from-certific	<b>l</b> .		Remarks:	· u			
I untaround time: ( )Standard 4 WKS, ( )Raisin 1,2838, ( )AKSAR Verous	S, (JEUSII Lays	Tacky)	on the						

# GPS MAPS



# CW-7 BLDG. 2000 OFFICER CLUB GPS POSITION & COORDINATES

US STATE PLANE 1983 NJ ( NY EAST) 2900 NAD 1983 ( CONUS )

(IN US SURVEY FEET)

# **SAMPLE POINTS**

POSITION / DESC.	Y COORD. ( NORTHING )	X COORD. (EASTING)
Α .	535270.748	611263.249
A1, A2	535275.67	611251.623
A3	535275.14	611251.585
AA	535304.031	611181.657
В	535271.116	611259.939
B1, B2	535289.161	611249.635
B3	535289.162	611250.36
BB	535319.794	611185.495
С	535277.096	611262.46
C1, C2	535301.332	611246.322
CC	535329.545	611203.76
D (FROM 1/27/98)	535276.943	611259.199
D	535273.998	611242.072
DD	535333.705	611220.622
E	535286.317	611239.843
E (FROM 1/27/98)	535281.595	611261.311
EE	535331.657	611241.824
F	535298.952	611237.637
F (FROM 1/27/98)	535280.474	611257.408
FF	535335.135	611203.866
G (FROM 1/27/98)	535284.185	611256.672
G	535272.871	611233.427
GG	535352.096	611211.626
Н	535284.147	611232.3
HH	535340.368	611222.03
1	535295.869	611231.466
11	535351.224	611223.286
J	535293.575	611213.218
JJ	535354.916	611198.033
K ·	535289.46	611209.406
KK	535332.839	611188.832
L	535287.087	611201.492
LL	535338.411	611240.256
M	535298.013	611193.746
N	535306.344	611200.874
0	535302.366	611207.764
Р	535315.048	611214.711
Q	535300.452	611224.074

R	535305.004	611236.465
S	535307.563	611247.073
T	535313.277	611233.306
U	535307.727	611230.088
V1, V2	535317.727	611245.034
W	535311.8	611244.489
X	535317.936	611229.826
Υ	535311.139	611204.081
Z	535293.048	611188.54

# **REFERENCE POSITIONS**

POSITION / DESC.	Y COORD. ( NORTHING )	X COORD. ( EASTING )
TRNSFRMR CTR	535302.239	611218.323
MANHOLE	535339.857	611210.732
MWR SIGN	535340 120	611232 943

# CASE NARRATIVE

# **CASE NARRATIVE**

Site: CW-7 PCB Investigation

The Field Duplicate for samples taken on 1/27/98 is C4 36-42" (Lab ID 3299.12).

# ANALYTICAL RESULTS

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3165

Sample Received: 11/19/97 Analysis Start: 11/31/97

Analysis Completed: 12/10/97

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

## ANALYTICAL RESULTS SUMMARY

PCB	MDL	3165.01	3165.02	3165.03	3165.04	3165.05
Arochlor	(mg/Kg)	2000-A2	2000-B2	2000-C2	2000-D	2000-E
(mg/Kg)	` "	96"-102"	96"-102"	96"-102"	96"-102"	96"-102"
1016	0.05	ND	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND .	ND
1242	0.05	ND	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND	ND
1260	0.05	ND	ND	ND	ND	ND
1200						
Total PCB	0.35	ND	ND	ND	ND	ND

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3165

Sample Received: 11/19/97

Analysis Start: 11/31/97

Analysis Completed: 12/10/97

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

# ANALYTICAL RESULTS SUMMARY

PCB Arochlor (mg/Kg)	MDL (mg/Kg)	3165.06 2000-F 96"-102"			
1016	0.05	ND			
1221	0.05	ND			
1232	0.05	ND	<u> </u>		
1242	0.05	ND			
1248	0.05	ND	 		
1254	0.05	ND			
1260	0.05	ND			
Total PCB	0.35	ND		<u> </u>	

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3168

Sample Received: 11/21/97 Analysis Start: 11/31/97

Analysis Completed: 12/10/97

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

# ANALYTICAL RESULTS SUMMARY

PCB	MDL	3168.01	3168.02	3168.03	3168.04	3168.05
Arochlor	(mg/Kg)	A1	B1	Cl	G	H
(mg/Kg)	( 0,	0-6"	0-6"	0-6"	72"-78"	72"-78"
1016	0.05	ND	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND	- ND
1242	0.05	ND	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND	ND
1260	0.05	24.9	ND	ND	47.5	ND
Total PCB	0.35	24.9	ND	ND	47.5	ND

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

Lab ID #: 3168

DPW, SELFM-PW-EV

Sample Received: 11/21/97

Bldg. 173

Analysis Start: 11/31/97

Ft. Monmouth, NJ 07703

Analysis Completed: 12/10/97

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

# ANALYTICAL RESULTS SUMMARY

PCB	MDL	3168.06			
Arochlor	(mg/Kg)	I		1	
(mg/Kg)		72"78"		 	 
1016	0.05	ND_			
1221	0.05	ND		 	
1232	0.05	ND_			
1242	0.05	ND	ļ	 	 
1248	0.05	ND			 
1254	0.05	ND		 	 
1260	0.05	ND		 	 
				 	 <u> </u>
Total PCB	0.35	ND		 	 <u> </u>

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3178

Sample Received: 11/25/97 Analysis Start: 12/02/97

Analysis Completed: 12/10/97

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

## ANALYTICAL RESULTS SUMMARY

PCB	MDL	3178.01	3178.02	3178.03	3178.04	3178.05
Arochlor	(mg/Kg)	. <b>J</b>	K	L	M	N
(mg/Kg)	, , ,	48"-54"	48"-54"	48"-54"	48"-54"	48"-54"
1016	0.05	ND	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND	ND
1242	0.05	ND	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND	ND
1260	0.05	ND	ND	ND	3.86	0.29
Total PCB	0.35	ND	ND	ND	3.86	0.29

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3178

Sample Received: 11/25/97

Analysis Start: 12/02/97 Analysis Completed: 12/10/97

Site: Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

## ANALYTICAL RESULTS SUMMARY

PCB	MDL	3178.06			
Arochlor	(mg/Kg)	О		·	
(mg/Kg)		48"-54"	 		
1016	0.05	ND			
1221	0.05	ND	 	·	
1232	0.05	ND			
1242	0.05	ND			
1248	0.05	ND			
1254	0.05	ND	 <u> </u>		
1260	0.05	0.81			
			l		
Total PCB	0.35	0.81			

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3179

Sample Received: 11/25/97

Analysis Start: 12/02/97

Analysis Completed: 12/10/97

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

# ANALYTICAL RESULTS SUMMARY

PCB	MDL	3179.01	3179.02	3179.03	3179.04	3179.05
Arochlor	(mg/Kg)	P	Q	R	S	T
(mg/Kg)	(86)	48"-54"	48"-54"	48"-54"	48"-54"	48"-54"
1016	0.05	ND	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND	ND
1242	0.05	ND	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND	ND
1260	0.05	0.76	0.22	ND	ND	0.11
1200						
Total PCB	0.35	0.76	0.22	ND	ND	0.11

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3179

Sample Received: 11/25/97

Analysis Start: 12/02/97

Analysis Completed: 12/10/97

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

				·		
PCB	MDL	3179.06	3179.07	3179.08		
Arochlor	(mg/Kg)	U	VI	V2		
(mg/Kg)	`	48"-54"	0-6"	48"-54"		
1016	0.05	ND	ND	ND		
1221	0.05	ND	ND	ND		
1232	0.05	ND	ND	ND	<u></u>	<u> </u>
1242	0.05	ND	ND	ND		
1248	0.05	ND	ND	ND		
1254	0.05	ND	ND	ND		
1260	0.05	ND	0.06	ND		
1						
Total PCB	0.35	ND	0.06	ND		

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3182

Sample Received: 11/25/97 Analysis Start: 12/02/97

Analysis Completed: 12/10/97

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

PCB	MDL	3182.01	3182.02	3182.03	3182.04	3182.05
Arochlor	(mg/Kg)	W	X	Y	Z	AA
(mg/Kg)	` "	24"-30"	24"-30"	24"-30"	24"-30"	24"-30"
1016	0.05	ND	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND	. ND
1242	0.05	ND	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND	ND
1260	0.05	ND	0.86	ND	0.11	0.28
1200						
Total PCB	0.35	ND	0.86	ND	0.11	0.28

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3182

Sample Received: 11/25/97

Analysis Start: 12/02/97

Analysis Completed: 12/10/97

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

PCB	MDL	3182.06	3182.07	3182.08	3182.09	3182.10
Arochlor	(mg/Kg)	BB	CC	DD	EE1	EE2
(mg/Kg)	` 5 0,	24"-30"	24"-30"	24"-30"	0-6"	24"-30"
1016	0.05	ND	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND	ND
1242	0.05	ND	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND	ND
1260	0.05	ND	ND	0.61	0.43	ND
Total PCB	0.35	ND	ND	0.61	0.43	ND.

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3182

Sample Received: 11/25/97 Analysis Start: 12/02/97

Analysis Completed: 12/10/97

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

PCB	MDL	3182.11	3182.12	3182.13	3182.14°	3182.15
Arochlor	(mg/Kg)	FF	GG	HH	п	JJ
(mg/Kg)	(66)	24"-30"	24"-30"	24"-30"	0-6"	0-6"
1016	0.05	ND	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND	ND
1242	0.05	ND	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND	ND
1260	0.05	ND	ND	ND	ND	ND
Total PCB	0.35	ND	ND	ND	ND	ND

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

Lab ID #: 3182

DPW, SELFM-PW-EV

Sample Received: 11/25/97

Bldg. 173

Analysis Start: 12/02/97

Ft. Monmouth, NJ 07703

Analysis Completed: 12/10/97

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### **ANALYTICAL RESULTS SUMMARY**

PCB	MDL	3182.16	3182.17		
Arochlor	(mg/Kg)	KK	LL		
(mg/Kg)		0-6"	0-6"		
1016	0.05	ND	ND		
1221	0.05	ND	ND		
1232	0.05	ND	ND		
1242	0.05	ND	ND		
1248	0.05	ND	ND		
1254	0.05	ND	ND		
1260	0.05	ND	ND		
			-		
Total PCB	0.35	ND	ND		

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

Lab ID #: 3299

DPW, SELFM-PW-EV

Sample Received: 01/27/98

Bldg. 173

Analysis Start: 01/29/98

Ft. Monmouth, NJ 07703

Analysis Completed: 02/01/98

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### **ANALYTICAL RESULTS SUMMARY**

PCB	MDL	3299.05	3299.06	3299.07	3299.08
Arochlor	(mg/Kg)	B1	B2	B3	B4
(mg/Kg)	(IIIg/IXg)	0-6"	12"-18"	24"-30"	36"-42"
1016	0.05	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND
1242	0.05	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND
1260	0.05	ND	ND	ND	ND
Total PCB	0.35	ND	ND	ND	ND

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

Lab ID #: 3299

DPW, SELFM-PW-EV

Sample Received: 01/27/98

Bldg. 173

Analysis Start: 01/29/98

Ft. Monmouth, NJ 07703

Analysis Completed: 02/01/98

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

PCB	MDL	3299.09	3299.10	3299.11	3299.12
Arochlor	(mg/Kg)	C1	C2	C3	C4
(mg/Kg)		0-6"	12"-18"	24"-30"	36"-42"
1016	0.05	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND
1242	0.05	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND
1260	0.05	ND	ND	ND	ND
Total PCB	0.35	ND	ND	ND	ND

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3299

Sample Received: 01/27/98 Analysis Start: 01/29/98

Analysis Completed: 02/01/98

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

PCB	MDL	3299.13	3299.14	3299.15	3299.16
Arochlor	(mg/Kg)	D1	D2	D3	D4
(mg/Kg)		0-6"	12"-18"	24"-30"	36"-42"
1016	0.05	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND
1242	0.05	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND
1260	0.05	ND	ND	ND	ND
·					
Total PCB	0.35	ND	ND	ND	ND

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3299

Sample Received: 01/27/98 Analysis Start: 01/29/98

Analysis Completed: 02/01/98

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

PCB	MDL	3299.17	3299.18	3299.19	3299.20
Arochlor	(mg/Kg)	E1	E2	E3	E4
(mg/Kg)		0-6"	12"-18"	24"-30"	36"-42"
1016	0.05	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND
1242	0.05	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND
1260	0.05	ND	ND	ND	ND
Total PCB	0.35	ND	ND	ND	ND

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3299

Sample Received: 01/27/98 Analysis Start: 01/29/98

Analysis Completed: 02/01/98

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

					T
PCB	MDL	3299.21	3299.22	3299.23	3299.24
Arochlor	(mg/Kg)	F1	F2	F3	F4
(mg/Kg)_	`	0-6"	12"-18"	24"-30"	36"-42"
1016	0.05	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND
1242	0.05	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND
1260	0.05	ND	ND	ND	ND
					,
Total PCB	0.35	ND	ND	ND	ND

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

Lab ID #: 3299

DPW, SELFM-PW-EV

Sample Received: 01/27/98 Analysis Start: 01/29/98

Bldg. 173

Analysis Completed: 02/01/98

Ft. Monmouth, NJ 07703

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

PCB	MDL	3299.25	3299.26	3299.27	3299.28
Arochlor	(mg/Kg)	G1	G2	G3	G4
(mg/Kg)		0-6"	12"-18"	24"-30"	36"-42"
1016	0.05	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND
1242	0.05	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND
1260	0.05	ND	ND	ND	ND
Total PCB	0.35	ND	ND	ND	ND

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3299

Sample Received: 01/27/98

Analysis Start: 01/29/98

Analysis Completed: 02/02/98

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

PCB	MDL	3299.29
Arochlor	(mg/Kg)	DUP
(mg/Kg)		
1016	0.05	ND
1221	0.05	ND
1232	0.05	ND
1242	0.05	ND
1248	0.05	ND
1254	0.05	ND
1260	0.05	ND
Total PCB	0.35	ND

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3299

Sample Received: 01/27/98

Analysis Start: 01/29/98 Analysis Completed: 02/02/98

Site:

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-608 Matrix: Aqueous

### ANALYTICAL RESULTS SUMMARY

PCB	MDL	3299.30
Arochlor	(ug/L)	FB
1016	.11	ND
1221	.21	ND
1232	.14	ND
1242	.16	ND
1248	.06	ND
1254	.04	ND
1260	.04	ND
Total PCB		ND

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

Lab ID #: 3326

DPW, SELFM-PW-EV

Sample Received: 02/09/98

Bldg. 173

Analysis Start: 02/11/98

Ft. Monmouth, NJ 07703

Analysis Completed: 02/20/98

Site:

CW-7

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

PCB Arochlor (mg/Kg)	MDL (mg/Kg)	3326.01 G-2 144"-150"	3326.02 H-2 144"-150"
1016	0.05	ND	ND
1221	0.05	ND	ND
1232	0.05	ND	ND
1242	0.05	ND	ND
1248	0.05	ND .	ND
1254	0.05	ND	ND
1260	0.05	ND	ND
Total PCB	0.35	ND	ND

ND = None Detected

MDL = Method Detection Limit

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3330

Sample Received: 02/10/98

Analysis Start: 02/11/98

Analysis Completed: 02/20/98

Site: CW-7

Bldg. 2000

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### **ANALYTICAL RESULTS SUMMARY**

PCB	MDL	3330.01	3330.02
Arochlor	(mg/Kg)	A3	B3
(mg/Kg)		0-6"	0-6"
1016	0.05	ND	ND
1221	0.05	ND	ND
1232	0.05	ND	ND
1242	0.05	ND	ND
1248	0.05	ND	ND
1254	0.05	ND	ND
1260	0.05	ND	ND
Total PCB	0.35	ND	ND

ND = None Detected

MDL = Method Detection Limit



### APPENDIX I

UST Disposal Documentation Mazza & Sons, Inc., Tinton Falls, NJ, 19 November 1997

THIS CHECK IS DELIVERED FOR ITAYIM NT ON THE FOLLOWING ACCOUNTS	24 S. Martin C. S. Salar de de C. Salar de de S. Salar de de S. Salar de de de S. Salar de de S. Salar de de S	1/00
DATE AMOUNT	MAZZA & SONS, INC. RECYCLING DIVISION	1496
	3230 SHAFPO RD. TINTON FALLS, NJ. 07753	55-7233/2212
g		11/19/97
TOTAL OF INVOICES	PAY 1/2 //	
LERS , % DISCOUNT	TO THE ORDER OF TECON VIANUL Service?	\$ 87.50
LESS FREIGHT	PAY TO THE ORDER OF TECOM Vinnell Service?  Gighty Seven + 50/1N	DOLLARS DELL
TOTAL DEDUCTIONS	AC Paula	DOLLANG COMMISSION
AMOUNT OF CHECK	Sovereign Bank	
	Con	man and an
8	#885 PPO4 PO 000 10 5 6 5 7 5 4 5 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	in it is a contract of the second sec	
The state of the s		
	The state of the s	America de la companya del companya della companya
	MAZZA & SONS, INC.	NO
	Metal Recyclers	. 67
	3230 Shafto Rd. Tinton Falls, NJ	DATE. 19 Now 97
	(908) 922-9292	
	(700) 722 7272	
Customer'	Name Teconi VIIVINECC	
Customer	5 (Vaine	
Address _		
Weight Pric	e	Weight Price
Cast Iron	<del></del>	Lt. Copper
/		Brass
Steel 87.5	(B) 2000) 10760 LB	
<u> 79. K </u>	9 3000 LB	Alum Clean
C	- 2500	Lead
Copper #1	Q300	Stainless
Copper #2		Stainless
		Battery
\$		
	Nov 1 9 1997	
	— IF NOV 19 19 19	\$ 87.50
	\\ \\\\ \\\\\\\\\\\\\\\\\\\\\	TOTAL AMOUNT:
<u> </u>	1	1//
	<del></del>	
	Customer //	
Weigher	Customer Hy	

- 4

 $\in \mathfrak{P}$ 



### APPENDIX J

Soil Stockpile – Waste Characterization
Analytical Data Package
Fort Monmouth Environmental Testing Laboratory – Analytical Data Report
Project CW-7, Lab ID #:3367, 3 March 1998

# For Bidg. 173, Tel (732):

Fort Monmouth Envir ...mental Testing Laboratory

Bldg. 173, SELFM-PW-EV, Fort Monmouth, NJ 07703

Tel (732)532-4359 Fax (732)532-3484 EMail:appleby@doim6.monmouth.army.mil NJDEP Certification #13461

Chain of Custody Record

					-			1			F	
Customer: 50E FALLON	ON	Project No:	ナーのい	_1			Analy	Analysis Parameters	meters			Comments:
Phone #: 26223		Location:	501L PI	PILE			之	(J.)	A~V	b o t	ا حا ت	
( )DERA ( )OMA ( )Other:								• • • • • • • • • • • • • • • • • • • •	ا? اح	″ ÷÷t	1/	
Samplers Name / Company:				Sample	#	ת ממ	(4) 444) 1743		<b>Ч</b> э 72	WA	<del>اد</del> ج	
Lab Sample I.D. Samp	Sample Location	Date	Time	Type b	bottles				T	ç	A.	Remarks / Preservation Method
- \ \ \	_	STATE OF	0060	Soil	2							-
03 SP-	2	)	0905		2		×	X	X	×	Z	3367.01-03
03 SP-3	8		0360		7	-	^_					
h-25 ho	<b>+</b>		5160		2							
8-85	S	,	0420		2		× ^	×	X X	X	×	3367,04-06
2-92 da	9-		5280		7					-		
ì	7		2690		2		X					
8-92 80	8		0460		7		x <	\ \	人 人	X	く	3367.07 09
	0		57.60		2							
01-95 01	2		0360		2							
11 SP-11	11		10955		2		X	X	X X	X	X	3367.10-13
11 58-12	12	·	0001.		2							
13 50-13	-13		0430		2		7					
14 F1640	Dup.	€	1005	>	2	<b>ラ</b>		_	_			
1 by (signature):	Date/Time:		(signature):		Relinqui	shed by (	Relinquished by (signature):		Date/Time:		ed by (s	Received by (signature):
Mark Jan 2	05:01 86-92-2	イブダイ	25 %					+				
Relinquished by (signature):	Date/Time:	Received by	signature):		Relinqui	shed by (	Relinquished by (signature):		Date/Time:		ed by (s	Received by (signature):
Report Type: (_)Full, (_)Reduced, (_)Standard, (_)Screen / non-certified	_)Standard, (_)Scre	en / non-certifi	pa		M	Remarks:	- 					
Turnaround time: (_)Standard 4 wks, (_)Rush		Days, ()ASAP Verbal	rbal Hrs.	ď		ļ						

print lealbly

Client:

U.S. Army

Lab. ID#:

3367

DPW. SELFM-PW-EV

Date Rec'd:

26-Feb-98

Bldg. 173

Analysis Start:

02-Mar-98

Ft. Monmouth, NJ 07703

Analysis Complete:

03-Mar-98

Analysis:

OQA-QAM-025

UST Reg. #:

Matrix:

Soil

Closure #:

Analyst:

D.DEINHARDT

DICAR #:

Ext. Meth:	Shake			Location #:		SOIL PILE
Sample	Field ID	Dilution Factor	Weight (g)	% Solid	MDL (mg/kg)	TPHC Result (mg/kg)
3367.01	SP-1	1.00	15.38	76.56	200	ND
3367.02	SP-2	1.00	15.10	76.51	203	241.53
3367.03	SP-3	1.00	15.64	84.06	179	ND
3367.04	SP-4	1.00	15.50	81.02	187	ND
3367.05	SP-5	1.00	15.57	80.38	188	ND
3367.06	SP-6	1.00	15.09	82.42	189	ND
3367.07	SP-7	1.00	15.13	80.75	192	ND
3367.08	SP-8	1.00	15.42	81.18	188	ND
3367.09	SP-9	1.00	15.46	77.86	195	ND
3367.10	SP-10	1.00	15.59	74.20	203	359.78
3367.11	SP-11	1.00	15.21	80.78	191	ND
3367.12	SP-12	1.00	15.24	87.35	177	353.95
3367.13	SP-13	1.00	15.20	79.35	195	237.07
3367.14	FIELD DUP	1.00	15.32	78.98	194	1319.12
				·		
METHOD BLANK	2-Mar-98	1.00	15.00	100.00	157	ND

ND = Not Detected

MDL = Method Detection Limit

Daniel K. Wright

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3367

Sample Received: 02/26/98

Analysis Start: 03/05/98

Analysis Completed: 03/12/98

Site:

CW-7 Soil Pile

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

PCB	MDL	3367.01	3367.02	3367.03	3367.04
Arochlor	(mg/Kg)	SP-1	SP-2	SP-3	SP-4
(mg/Kg)					
1016	0.05	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND
1242	0.05	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND
1254	0.05	ND	ND	ND	. ND
1260	0.05	0.12	1.92	0.15	1.76
Total PCB	0.35	0.12	1.92	0.15	1.76

ND = None Detected MDL = Method Detection Limit Results are Reported on a Dry Wt.Basis

Daniel K. Wright
Laboratory Director

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3367

Sample Received: 02/26/98

Analysis Start: 03/05/98

Analysis Completed: 03/12/98

Site:

CW-7 Soil Pile

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

PCB Arochlor	MDL (mg/Kg)	3367.05 SP-5	3367.06 SP-6	3367.07 SP-7	3367.08 SP-8
(mg/Kg)				) II	ND
1016	0.05	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND
1242	0.05	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND
1260	0.05	14.2	4.10	2.11	0.47
Total PCB	0.35	14.2	4.10	2.11	0.47

ND = None Detected

MDL = Method Detection Limit

Results are Reported on a Dry Wt.Basis

Daniel K. Wright

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3367

Sample Received: 02/26/98

Analysis Start: 03/05/98

Analysis Completed: 03/12/98

Site:

CW-7 Soil Pile

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

PCB	MDL	3367.09	3367.10	3367.11	3367.12
Arochlor	(mg/Kg)	SP-9	SP-10	SP-11	SP-12
(mg/Kg)					
1016	0.05	ND	ND	ND	ND
1221	0.05	ND	ND	ND	ND
1232	0.05	ND	ND	ND	ND
1242	0.05	ND	ND	ND	ND
1248	0.05	ND	ND	ND	ND
1254	0.05	ND	ND	ND	ND
1260	0.05	3.85	1.18	0.22	1.27
Total PCB	0.35	3.85	1.18	0.22	1.27

ND = None Detected

MDL = Method Detection Limit

Results are Reported on a Dry Wt.Basis

Daniel K. Wright

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3367

Sample Received: 02/26/98

Analysis Start: 03/05/98

Analysis Completed: 03/12/98

Site:

CW-7 Soil Pile

Ft. Monmouth, NJ

Method: EPA-SW846-8080

Matrix: Soil

### ANALYTICAL RESULTS SUMMARY

PCB Arochlor (mg/Kg)	MDL (mg/Kg)	3367.13 SP-13	3367.14 Field DUP	
1016	0.05	ND	ND	
1221	0.05	ND	ND	
1232	0.05	ND	ND	
1242	0.05	ND	ND	
1248	0.05	ND	ND	
1254	0.05	ND	ND	
1260	0.05	1.50	ND	
Total PCB	0.35	1.50	ND	

ND = None Detected MDL = Method Detection Limit Results are Reported on a Dry Wt.Basis

Daniel K. Wright

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3367

Sample Received: 02/26/98

Sample Matrix: Soil

Site: Site-A

Ft. Monmouth. New Jersey

TEST PARAMETER: IGNITABILITY
TEST METHOD: SW-846 1010 - Pensky-Martens Closed Cup

Laboratory ID#	Sample Location/ Identification	Flashpoint deg. F
3367.01-03	Composite	> 140
3367.04-06	Composite	> 140
3367.07-09	Composite	> 140
3367.10-13	Composite	> 140

NA - Not Applicable

Daniel K. Wright

Laboratory Director

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3367

Sample Received: 02/26/98

Analysis Start: 03/12/97

Analysis Completed: 03/12/97

Site:

CW-7, Soil Pile

Ft. Monmouth, New Jersey

TEST PARAMETER: pH TEST METHOD: EPA SW-846 - 9045

Laboratory ID#	Sample Location/ Identification	pН
3367.01-03	Composite	5.23
3367.04-06	Composite	5.39
3367.07-09	Composite	5.14
3367.10-13	Composite	5.40

Daniel K. Wright

### US ARMY FT. MONMOUTH ENVIRONMENTAL LABORATORY **NJDEPE # 13461**

### **REPORT OF ANALYSIS**

Client:

U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Project:

Volatiles - BTEX

CW-7 Soil Pile Composite

Project #

3367

Date Rec.

02/26/98

Date Compl. 03/12/98

Released by:

Daniel K. Wright Laboratory Director

FIELD ID.

			NUDED #	40404	VBI	LK31	- 1
Lab Name:	FMETL		NJDEP#	13461	_		
Project:		Case No.:	3367 Location	n: <u>CW7</u> S	SDG No.: _		
Matrix: (soil/	water)	SOIL	Lal	b Sample ID:	VBLK31		
Sample wt/ve	ol:	5.0 (g/ml)	G Lal	b File ID:	V03130.D		
Level: (low/r	med)	LOW	Da	ite Received:	02/26/98		
% Moisture:	not dec.	0	Da	ate Analyzed:	03/12/98		
GC Column:	Rtx502	2.2 ID: <u>0.25</u> (m	nm) Dil	lution Factor:	1.0		
Soil Extract \	Volume:	(uL)	So	oil Aliquot Vol	ume:		(uL)
			CONCENTRA	TION UNITS:	:		
CAS NO	Э.	COMPOUND	(ug/L or ug/Kg)	) <u>UG/KG</u>	<u> </u>	Q	
71-43	2	Benzene			1	U	
108-8		Toluene			1	U	
100-4		Ethylbenzene	)		2	U	
100 .	<u> </u>						- 1

m+p-Xylenes

o-Xylene

1330-20-7 1330-20-7

FIELD ID.

U

U

U

3

4

		•	SP1-3	
Lab Name: FMETL		NJDEP # 13461		
Project:	Case No.: 3367	Location: CW7 SD	G No.:	
Matrix: (soil/water)	SOIL	Lab Sample ID: 3	3367Comp1	
Sample wt/vol:	5.0 (g/ml) <u>G</u>	Lab File ID:	V03131.D	
Level: (low/med)	LOW	Date Received:	02/26/98	
% Moisture: not dec.	22.8	Date Analyzed:	03/12/98	
GC Column: Rtx502	2.2 ID: 0.25 (mm)	Dilution Factor:	1.0	
Soil Extract Volume:	(uL)	Soil Aliquot Volun	ne:	(uL)
		CONCENTRATION UNITS:		٠.
CAS NO.	COMPOUND	(ug/L or ug/Kg) UG/KG	Q	
71-43-2	Benzene		1 U	

108-88-3

100-41-4

1330-20-7 1330-20-7 Toluene

o-Xylene

Ethylbenzene

m+p-Xylenes

	IILLU	10.		
ı		<del></del>		-
			_	

_ab Name: FME	TL	NJDEP # 13461	374-0	
Project:	Case No.: 3367	Location: CW7 SI	OG No.:	<del></del>
Matrix: (soil/water)	SOIL	Lab Sample ID:	3367Comp2	
Sample wt/vol:	5.0 (g/ml) <u>G</u>	Lab File ID:	V03132.D	
Level: (low/med)	LOW	Date Received:	02/26/98	
% Moisture: not de	ec. 17.5	Date Analyzed:	03/12/98	
GC Column: Rt	x502.2 ID: 0.25 (mm)	Dilution Factor:	1.0	
Soil Extract Volum	ne: (uL)	Soil Aliquot Volu	me:	(uL
		ONCENTRATION UNITS:		

CAS NO.	COMPOUND	(ug/L or ug/Ny)	UG/NG	Q
71-43-2	Benzene		11	U
108-88-3	Toluene		1	U
100-41-4	Ethylbenzene		2	U
1330-20-7	m+p-Xylenes		4	U
1330-20-7	o-Xvlene		2	U

FIELD ID.

2

3

U

Ü

Lab Name: FMETL		NJDEP# 13461	SP10-13	
Project:	Case No.: 3367	Location: CW7 SE	OG No.:	
Matrix: (soil/water)	SOIL	Lab Sample ID:	3367Comp4	
Sample wt/vol:	5.0 (g/ml) G	Lab File ID:	V03134.D	
Level: (low/med)	LOW	Date Received:	02/26/98	
% Moisture: not dec.	7.2	Date Analyzed:	03/12/98	
GC Column: Rtx50	02.2 ID: 0.25 (mm)	Dilution Factor:	1.0	
Soil Extract Volume:	(uL)	Soil Aliquot Volur	me:	(uL)
	en e	CONCENTRATION UNITS:	•	
CAS NO.	COMPOUND	(ug/L or ug/Kg) UG/KG	Q	
71-43-2	Benzene		1 U	

108-88-3

100-41-4

1330-20-7

1330-20-7

Toluene

Ethylbenzene

m+p-Xylenes o-Xylene

## US ARMY FT. MONMOUTH ENVIRONMENTAL LABORATORY NJDEPE # 13461

### **REPORT OF ANALYSIS**

Client:

U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Project:

Volatiles - TCLP

CW-7 Soil Pile Composite

Project # 3367
Date Rec. 02/26/98
Date Compl. 03/24/98

Released by:

Daniel K. Wright Laboratory Director

## US ARMY FT. MONMOUTH ENVIRONMENTAL LABORATORY NJDEPE # 13461

### **REPORT OF ANALYSIS**

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Project: Volatiles - TCLP

CW-7 Soil Pile Composite

> Project # 3367 Date Rec. 02/26/98 Date Compl. 03/24/98

Released by:

Daniel K. Wright Laboratory Director

## Vlatile Analysis Report U.S. Army, For Monmouth Environmental Laboratory NJDEP Certification #13461

Data File Name

V03318.D

1 033 10.1

Skelton

Sample Name

Field ID

VBLK38 VBLK38

perator
Date Acquired

24 Mar 1998 9:24

Sample Multiplier

1

					Regulatory		
CAS#	Name	R.T.	Response	Result	Level	MDL	Qualifiers
75-01-4	Vinyl Chloride			not detected	0.2	0.0026 mg/L	
75-35-4	1,1-Dichloroethene			not detected	0.7	0.0007 mg/L	
78-93-3	2-Butanone			not detected	200.0	0.0021 mg/L	
67-66-3	Chloroform			not detected	6.0	0.0004 mg/L	
56-23-5	Carbon Tetrachloride			not detected	0.5	0.0012 mg/L	
71-43-2	Benzene			not detected	0.5	0.0005 mg/L	
107-06-2	1,2-Dichloroethane			not detected	0.5	0.0013 mg/L	
79-01-6	Trichloroethene			not detected	0.5	0.0009 mg/L	
127-18-4	Tetrachloroethene			not detected	0.7	0.0009 mg/L	
108-90-7	Chlorobenzene			not detected	100.0	0.0007 mg/L	

### **Qualifiers**

B = Compound in related blank

E = Value above linier range

D = Value from dilution

MDL = Method detection limit

R.T. = Retention time

## U.S. Army, For Monmouth Environmental Laboratory NJDEP Certification #13461

Data File Name

v03333.d

Sample Name

3367.01-03

perator

Skelton

Field ID

Comp1

Date Acquired

24 Mar 1998 20:03

Sample Multiplier

				Regulatory				
CAS#	Name	R.T.	Response	Result	Level	MDL	Qualifiers	
75-01-4	Vinyl Chloride	1		not detected	0.2	0.0026 mg/L		
75-35-4	1,1-Dichloroethene			not detected	0.7	0.0007 mg/L		
78-93-3	2-Butanone			not detected	200.0	0.0021 mg/L		
67-66-3	Chloroform			not detected	6.0	0.0004 mg/L		
56-23-5	Carbon Tetrachloride			not detected	0.5	0.0012 mg/L		
71-43-2	Benzene			not detected	0.5	0.0005 mg/L		
107-06-2	1,2-Dichloroethane			not detected	0.5	0.0013 mg/L		
79-01-6	Trichloroethene			not detected	0.5	0.0009 mg/L		
127-18-4	Tetrachloroethene			not detected	0.7	0.0009 mg/L		
108-90-7	Chlorobenzene			not detected	100.0	0.0007 mg/L		

#### **Qualifiers**

B = Compound in related blank

E = Value above linier range

D = Value from dilution

MDL = Method detection limit

R.T. = Retention time

### platile Analysis Report U.S. Army, For Monmouth Environmental Laboratory NJDEP Certification #13461

Data File Name

Date Acquired

perator

v03334.d

Skelton

24 Mar 1998 20:46

Sample Name

3367.04-06

Field ID

Comp2

Sample Multiplier

1

					Regulatory	,	
CAS#	Name	R.T.	Response	Result	Level	MDL	Qualifiers
75-01-4	Vinyl Chloride			not detected	0.2	0.0026 mg/L	
75-35-4	1,1-Dichloroethene			not detected	0.7	0.0007 mg/L	
78-93-3	2-Butanone			not detected	200.0	0.0021 mg/L	
67-66-3	Chloroform			not detected	6.0	0.0004 mg/L	
56-23-5	Carbon Tetrachloride			not detected	0.5	0.0012 mg/L	
71-43-2	Benzene			not detected	0.5	0.0005 mg/L	
107-06-2	1,2-Dichloroethane			not detected	0.5	0.0013 mg/L	
79-01-6	Trichloroethene			not detected	0.5	0.0009 mg/L	
127-18-4	Tetrachloroethene	1		not detected	0.7	0.0009 mg/L	
108-90-7	Chlorobenzene			not detected	100.0	0.0007 mg/L	

### **Qualifiers**

B = Compound in related blank

E = Value above linier range

D = Value from dilution

MDL = Method detection limit

R.T. = Retention time

Data File Name

Date Acquired

v03336.d

24 Mar 1998 22:11

Sample Name

Field ID

3367.10-13

Operator

Skelton

on

Sample Multiplier

Comp4

					Regulatory		
CAS#	Name	R.T.	Response	Result	Level	MDL	Qualifiers
75-01-4	Vinyl Chloride			not detected	0.2	0.0026 mg/L	
75-35-4	1,1-Dichloroethene			not detected	0.7	0.0007 mg/L	
78-93-3	2-Butanone			not detected	200.0	0.0021 mg/L	
67-66-3	Chloroform			not detected	6.0	0.0004 mg/L	
56-23-5	Carbon Tetrachloride			not detected	0.5	0.0012 mg/L	
71-43-2	Benzene			not detected	0.5	0.0005 mg/L	
107-06-2	1,2-Dichloroethane			not detected	0.5	0.0013 mg/L	
79-01-6	Trichloroethene			not detected	0.5	0.0009 mg/L	
127-18-4	Tetrachloroethene			not detected	0.7	0.0009 mg/L	
108-90-7	Chlorobenzene			not detected	100.0	0.0007 mg/L	

### **Qualifiers**

B = Compound in related blank

E = Value above linier range

D = Value from dilution

MDL = Method detection limit

### US ARMY FT. MONMOUTH ENVIRONMENTAL LABORATORY **NJDEPE # 13461**

### **REPORT OF ANALYSIS**

Client:

U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Project:

Semi-Volatiles - TCLP

CW-7 Soil Pile Composite

Project #

3367

Date Rec. Date Compl. 03/27/98

02/26/98

Released by:

Daniel K. Wright Laboratory Director

Data File Na bn1204.d

**FITZPATRICK** 

Operator Date Acquire 03/27/98 13:11 Sample Name

**SBLK 40** 

Misc Info

SBLK 40

Sample Multiplier 1

CAS#	Name	R.T.	Response	Result	Regulatory Level (mg/L)	MDL	Qualifiers
110-86-1	Pyridine			not detected	5.00	5.00 ug/L	
106-46-7	1,4-Dichlorobenzene			not detected	7.50	0.23 ug/L	
	2-Methylphenol (o-cresol)			not detected	200.00	0.14 ug/L	
	4-Methylphenol (m,p-cresol)			not detected	200.00	0.14 ug/L	
67-72-1	Hexachioroethane			not detected	3,00	0.33 ug/L	
98-95-3	Nitrobenzene			not detected	2.00	0.46 ug/L	,
87-68-3	Hexachlorobutadiene			not detected	0.50	0.38 ug/L	
88-06-2	2,4,6-Trichlorophenol			not detected	2.00	0.42 ug/L	,
	2,4,5-Trichlorophenol			not detected	400.00	0.31 ug/L	,
121-14-2	2,4-Dinitrotoluene			not detected	0.13	0.36 ug/L	
118-74-1	Hexachlorobenzene			not detected	0.13	0.82 ug/L	,
87-86-5	Pentachlorophenol			not detected	100.00	1.08 ug/L	

### Qualifiers

E = Value exceded linear range

D = Value from dilution

B = Compound in related blank

MDL = Method Detection Limit

Data File Na bn1206.d

Operator FITZPATRICK

Date Acquire 03/27/98 14:43

Sample Name

TCLP BLANK

Misc Info

TCLP BLANK

Sample Multiplier 10

CAS#	Name	R.T.	Response	Result	Regulatory Level (mg/L)	MDL	Qualifiers
110-86-1	Pyridine			not detected	5.00	5.00 ug/I	
106-46-7	1,4-Dichlorobenzene			not detected	7.50	0.23 ug/I	4
	2-Methylphenol (o-cresol)			not detected	200.00	0.14 ug/I	4
	4-Methylphenol (m,p-cresol)			not detected	200.00	0.14 ug/I	4
67-72-1	Hexachloroethane			not detected	3.00	0.33 ug/I	
98-95-3	Nitrobenzene			not detected	2.00	0.46 ug/I	
87-68-3	Hexachlorobutadiene			not detected	0.50	0.38 ug/l	
88-06-2	2,4,6-Trichlorophenol			not detected	2.00	0.42 ug/l	
	2,4,5-Trichlorophenol			not detected	400.00	0.31 ug/l	
121-14-2	2,4-Dinitrotoluene			not detected	0.13	0.36 ug/l	
118-74-1	Hexachlorobenzene			not detected	0.13	0.82 ug/l	
87-86-5	Pentachlorophenol			not detected	100.00	1.08 ug/l	4

### Qualifiers

E = Value exceded linear range

D = Value from dilution

B = Compound in related blank

MDL = Method Detection Limit

Data File Na bn1209.d

Sample Name

3367.01-03

Operator

**FITZPATRICK** 

Misc Info

SP1-3

Date Acquire 03/27/98 17:05

Sample Multiplier 10

CAS#	Name	R.T.	Response	Result	Regulatory Level (mg/L)	MDL	Qualifiers
110-86-1	Pyridine			not detected	5.00	5.00 ug/	
106-46-7	1,4-Dichlorobenzene			not detected	7.50	0.23 ug/	L
	2-Methylphenol (o-cresol)			not detected	200.00	0.14 ug/	L
	4-Methylphenol (m,p-cresol)			not detected	200.00	0.14 ug/	L
67-72-1	Hexachloroethane			not detected	3.00	0.33 ug/	니
98-95-3	Nitrobenzene			not detected	2.00	0.46 ug/	L
87-68-3	Hexachlorobutadiene			not detected	0.50	0.38 ug/	L
88-06-2	2,4,6-Trichlorophenol			not detected	2.00	0.42 ug/	L
	2,4,5-Trichlorophenol			not detected	400.00	0.31 ug/	
121-14-2	2,4-Dinitrotoluene			not detected	0.13	0.36 ug/	
118-74-1	Hexachlorobenzene			not detected	0.13	0.82 ug/	L
87-86-5	Pentachlorophenol			not detected	100.00	1.08 ug/	L

### **Qualifiers**

E = Value exceded linear range

D = Value from dilution

B = Compound in related blank

MDL = Method Detection Limit

Data File Na bn1210.d

Sample Name

3367.04-06

Operator FITZPATRICK

Misc Info

SP4-6

Date Acquire 03/27/98 17:50

Sample Multiplier 10

CAS#	Name	R.T.	Response	Result	Regulatory Level (mg/L)	MDL		Qualifiers
110-86-1	Pyridine			not detected	5.00	5.00	ug/L	
106-46-7	1,4-Dichlorobenzene			not detected	7.50		ug/L	_
	2-Methylphenol (o-cresol)			not detected	200.00	0.14	ug/L	
	4-Methylphenol (m,p-cresol)			not detected	200.00	0.14	ug/L	
67-72-1	Hexachloroethane			not detected	3.00		ug/L	
98-95-3	Nitrobenzene			not detected	2.00	0.46	ug/L	
87-68-3	Hexachlorobutadiene			not detected	0.50		ug/L	
88-06-2	2,4,6-Trichlorophenol			not detected	2.00		ug/L	<u> </u>
	2,4,5-Trichlorophenol			not detected	400.00		ug/L	
121-14-2	2,4-Dinitrotoluene			not detected	0.13		ug/L	
118-74-1	Hexachlorobenzene			not detected	0.13		ug/L	
87-86-5	Pentachlorophenol			not detected	100.00	1.08	ug/L	

### Qualifiers

E = Value exceded linear range

D = Value from dilution

B = Compound in related blank

MDL = Method Detection Limit

Data File Na bn1211.d

Operator

**FITZPATRICK** 

Date Acquire 03/27/98 18:36

Sample Name

3367.07-09

Misc Info

SP7-9

Sample Multiplier 10

CAS#	Name	R.T.	Response	Result	Regulatory Level (mg/L)	MDL		Qualifiers
110-86-1	Pyridine		1	not detected	5.00	5.00 u	_	
106-46-7	1,4-Dichlorobenzene			not detected	7.50	0.23 ι	ıg/L	
	2-Methylphenol (o-cresol)			not detected	200.00	0.14 เ		
	4-Methylphenol (m,p-cresol)			not detected	200.00	0.14 เ	ıg/L	
67-72-1	Hexachloroethane			not detected	3.00	.0.33 เ		
98-95-3	Nitrobenzene	,		not detected	2.00	0.46 เ		
87-68-3	Hexachlorobutadiene			not detected	0.50	0.38 เ	_	
88-06-2	2,4,6-Trichlorophenol			not detected	2.00	0.42 เ	ug/L	
	2,4,5-Trichlorophenol			not detected	400.00	0.31 เ		
121-14-2	2,4-Dinitrotoluene			not detected	0.13	0.36 เ		
118-74-1	Hexachlorobenzene			not detected	0.13	0.82 1	ug/L	
87-86-5	Pentachlorophenol			not detected	100.00	1.08	ug/L	

### **Qualifiers**

E = Value exceded linear range

D = Value from dilution

B = Compound in related blank

MDL = Method Detection Limit

Data File Na BN1213.D

Operator

**FITZPATRICK** 

Date Acquire 03/27/98 19:21

Sample Name

3367.10-13

Misc Info

SP10-13

Sample Multiplier 10

CAS#	Name	R.T.	Response	Result	Regulatory Level (mg/L)	MDL		Qualifiers
110-86-1	Pyridine			not detected	5.00		ug/L	
106-46-7	1,4-Dichlorobenzene			not detected	7.50		ug/L	
	2-Methylphenol (o-cresol)			not detected	200.00		ug/L	
	4-Methylphenol (m,p-cresol)			not detected	200.00	0.14	ug/L	
67-72-1	Hexachloroethane			not detected	3.00	0.33	ug/L	
98-95-3	Nitrobenzene			not detected	2.00	0.46	ug/L	
87-68-3	Hexachlorobutadiene			not detected	0.50		ug/L	
88-06-2	2,4,6-Trichlorophenol			not detected	2.00	0.42	ug/L	
	2,4,5-Trichlorophenol			not detected	400.00	0.31	ug/L	
121-14-2	2,4-Dinitrotoluene			not detected	0.13	0.36	ug/L	,
118-74-1	Hexachlorobenzene			not detected	0.13	0.82	ug/L	,
87-86-5	Pentachlorophenol			not detected	100.00	1.08	ug/L	4

### Qualifiers

E = Value exceded linear range

D = Value from dilution

B = Compound in related blank

MDL = Method Detection Limit

Client:

U.S. Army

Lab. ID#:

3367.01-03

DPW, SELFM-PW-EV

Date Rec'd:

2/26/98

Bldg. 173

TCLP Ext. Date:

3/12/98

Ft. Monmouth, NJ 07703

Extraction Date: Analysis Date:

3/19/98 4/6/98

Analysis:

**EPA Method 608** 

Matrix:

Aqueous

Location:

CW-7 Soil Pile

Analyst: Ext. Meth: D. Wright

Sep. Funnel

Field ID:

SP-1, SP-2, SP-3

TCLP PESTICIDES	Dilution Factor	Retention Time	Regulatory Level (mg/L)	MDL (mg/L)	Result (mg/L)
Chlordane	1		0.03	0.00014	ND
Endrin	1		0.02	0.00003	ND
Heptachlor	1		0.008	0.00003	ND
Heptachlor Epoxide	1		0.008	0.00002	ND
Lindane	1		0.40	0.00003	ND
Methoxychlor	1		10.00	0.00010	ND
Toxaphene	1		0.50	0.00020	ND

ND = Not Detected

Column-Primary:

Rtx-5 30m/.32mmID/.25um

MDL = Method Detection Limit

Column-Confirmation:

Rtx-1701 30m/.32mmID/.25um

NA = Not Applicable

Daniel K. Wright

**Laboratory Director** 

Client:

U.S. Army

Lab. ID#:

3367.04-06

DPW, SELFM-PW-EV

Date Rec'd:

2/26/98

Bldg. 173

**TCLP Ext. Date:** 

3/12/98

**Extraction Date:** 

3/19/98

Ft. Monmouth, NJ 07703

**Analysis Date:** 

4/6/98

Analysis:

**EPA Method 608** 

Matrix:

Aqueous

Location:

CW-7 Soil Pile

Analyst: Ext. Meth: D. Wright

Sep. Funnel

Field ID:

SP-4, SP-5, SP-6

TCLP PESTICIDES	Dilution Factor	Retention Time	Regulatory Level (mg/L)	MDL (mg/L)	Result (mg/L)
Chlordane	1		0.03	0.00014	ND
Endrin	1		0.02	0.00003	ND
Heptachlor	. 1		0.008	0.00003	ND
Heptachlor Epoxide	1		0.008	0.00002	ND
Lindane	1		0.40	0.00003	ND
Methoxychlor	1		10.00	0.00010	ND
Toxaphene	1		0.50	0.00020	ND

ND = Not Detected

Column-Primary:

Rtx-5 30m/.32mmlD/.25um

MDL = Method Detection Limit

Column-Confirmation:

Rtx-1701 30m/.32mmlD/.25um

NA = Not Applicable

**Laboratory Director** 

Client:

U.S. Army

Lab. ID#:

3367.07-09

DPW, SELFM-PW-EV

Date Rec'd:

2/26/98

Bldg. 173

TCLP Ext. Date:

3/12/98

Ft. Monmouth, NJ 07703

Extraction Date: Analysis Date:

3/19/98 4/6/98

Analysis:

**EPA Method 608** 

Matrix:

Aqueous

Location:

CW-7 Soil Pile

Analyst: Ext. Meth: D. Wright

Sep. Funnel

Field ID:

SP-7, SP-8, SP-9

TCLP PESTICIDES	Dilution Factor	Retention Time	Regulatory Level (mg/L)	MDL (mg/L)	Result (mg/L)
Chlordane	1		0.03	0.00014	ND
Endrin	1		0.02	0.00003	ND
Heptachlor	1		0.008	0.00003	ND
Heptachlor Epoxide	1		0.008	0.00002	ND
Lindane	1		0.40	0.00003	ND
Methoxychlor	1		10.00	0.00010	ND
Toxaphene	1		0.50	0.00020	ND

ND = Not Detected

Column-Primary:

Rtx-5 30m/.32mmID/.25um

MDL = Method Detection Limit

Column-Confirmation:

Rtx-1701 30m/.32mmlD/.25um

NA = Not Applicable

Daniel K. Wright

Laboratory Director

Client U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: Tclp Blank

Sample Received: 02/26/98

Sample Matrix: Aq

Site:

CW-7

Soil Pile

Std. Methods 18th, Method 3120B, 3112B Method of Analysis:

Method of Digestion: E.P.A SW-846, Method 3015

### **TEST PARAMETER: TCLP Metals**

Element	Date	Result	Regulatory	MDL
	Analyzed	(mg/L)	Level (mg/L)	(mg/L)
Arsenic	03/19/98	ND	5	0.004
Barium	03/19/98	0.009	100	0.001
Cadmium	03/19/98	ND	1	0.001
Chromium	03/19/98	ND	5	0.001
Lead	03/19/98	ND	- 5	0.004
Mercury	03/20/98	0.0003	0.2	0.0002
Selenium	03/19/98	0.007	1	0.006
Silver	03/19/98	ND	5	0.006

ND = Not Detected, MDL = Method Detection Limit, NA = Not Applicable

Daniel K. Wright

Client U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3367.01-.03

Sample Received: 02/26/98

Sample Matrix: Soil

Site: CW-7

Soil Pile

Field ID: SP:1-3

Method of Analysis:

Std. Methods 18th, Method 3120B, 3112B

Method of Digestion: E.P.A SW-846, Method 3015

### TEST PARAMETER: TCLP Metals

Element	Date	Result	Regulatory	MDL
·	Analyzed	(mg/L)	Level (mg/L)	(mg/L)
Arsenic	03/19/98	ND	5	0.004
Barium	03/19/98	1.138	100	0.001
Cadmium	03/19/98	0.001	1	0.001
Chromium	03/19/98	ND	5	0.001
Lead	03/19/98	0.025	5	0.004
Mercury	03/20/98	ND	0.2	0.0002
Selenium	03/19/98	0.009	1	0.006
Silver	03/19/98	ND	5	0.006

ND = Not Detected, MDL = Method Detection Limit, NA = Not Applicable

Daniel K. Wright

Client: U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3367.04-.06

Sample Received: 02/26/98

Sample Matrix: Soil

Site:

CW-7

Soil Pile

Field ID: SP:4-6

Method of Analysis:

Std. Methods 18th, Method 3120B, 3112B

Method of Digestion: E.P.A SW-846, Method 3015

### TEST PARAMETER: TCLP Metals

Element	Date	Result	Regulatory	MDL
	Analyzed	(mg/L)	Level (mg/L)	(mg/L)
Arsenic	03/19/98	ND	5	0.004
Barium	03/19/98	0.699	100	0.001
Cadmium	03/19/98	ND	1	0.001
Chromium	03/19/98	ND	5	0.001
Lead	03/19/98	0.069	5	0.004
Mercury	03/20/98	ND	0.2	0.0002
Selenium	03/19/98	0.007	1	0.006
Silver	03/19/98	ND	5	0.006

ND = Not Detected, MDL = Method Detection Limit, NA = Not Applicable

Daniel K. Wright

Client U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3367.07-.09

Sample Received: 02/26/98

Sample Matrix: Soil

Site:

CW-7

Soil Pile

Field ID: SP:7-9

Method of Analysis:

Std. Methods 18th, Method 3120B, 3112B

Method of Digestion: E.P.A SW-846, Method 3015

### TEST PARAMETER: TCLP Metals

Element	Date	Result	Regulatory	MDL
	Analyzed	(mg/L)	Level (mg/L)	(mg/L)
Arsenic	03/19/98	ND	5	0.004
Barium	03/19/98	0.195	100	0.001
Cadmium	03/19/98	0.001	1	0.001
Chromium	03/19/98	ND	5	0.001
Lead	03/19/98	0.101	5	0.004
Mercury	03/20/98	ND	0.2	0.0002
Selenium	03/19/98	0.008	ī	0.006
Silver	03/19/98	ND	5	0.006

ND = Not Detected, MDL = Method Detection Limit, NA = Not Applicable

Daniel K. Wright

Client U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3367.10-.13

Sample Received: 02/26/98

Sample Matrix: Soil

Site:

CW-7

Soil Pile

Field ID: SP:10-13

Method of Analysis:

Std. Methods 18th, Method 3120B, 3112B

Method of Digestion: E.P.A SW-846, Method 3015

### **TEST PARAMETER: TCLP Metals**

Element	Date	Result	Regulatory	MDL
	Analyzed	(mg/L)	Level (mg/L)	(mg/L)
Arsenic	03/19/98	ND	5	0.004
Barium	03/19/98	0.915	100	0.001
Cadmium	03/19/98	ND	1	0.001
Chromium	03/19/98	ND	5	0.001
Lead	03/19/98	0.023	5	0.004
Mercury	03/20/98	ND	0.2	0.0002
Selenium	03/19/98	0.008	1	0.006
Silver	03/19/98	0.030	5	0.006

ND = Not Detected, MDL = Method Detection Limit, NA = Not Applicable

Daniel K. Wright



# FORT MONMOUTH NJDEP STANDARD PACKAGE

PROJECT: CW-7

LAB#: AA62903 - AA62907

NJDEP CERT. #14622,CT CERT. #PH0671 PADER CERT. #68-463,MA CERT.#NJ386 NYDOH CERT. #11408

Client U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Lab ID #: 3367.10-.13

Sample Received: 02/26/98

Sample Matrix: Soil

Site:

CW-7

Soil Pile

Field ID: SP:10-13

Method of Analysis:

Std. Methods 18th, Method 3120B, 3112B

Method of Digestion: E.P.A SW-846, Method 3015

### **TEST PARAMETER: TCLP Metals**

Element	Date	Result	Regulatory	MDL
	Analyzed	(mg/L)	Level (mg/L)	(mg/L)
Arsenic	03/19/98	ND	5	0.004
Barium	03/19/98	0.915	100	0.001
Cadmium	03/19/98	ND	1	0.001
Chromium	03/19/98	ND	5	0.001
Lead	03/19/98	0.023	5	0.004
Mercury	03/20/98	ND	0.2	0.0002
Selenium	03/19/98	0.008	1	0.006
Silver	03/19/98	0.030	5	0.006

ND = Not Detected, MDL = Method Detection Limit, NA = Not Applicable

Daniel K. Wright



# FORT MONMOUTH NJDEP STANDARD PACKAGE

PROJECT: CW-7

LAB#: AA62903 - AA62907

NJDEP CERT. #14622,CT CERT. #PH0671 PADER CERT. #68-463,MA CERT.#NJ386 NYDOH CERT. #11408 CT#: PH-0671

MA #: NJ386

NY #: 11408

NJ#: 14622

PA #: 68-463

# Report Of Analysis veritech laboratories

To: Fort Monmouth

**Environmental Testing Lab** 

Bldg. 173

SELFM-PW-EV

Attention:

**CHUCK APPLEBY** 

Project:

**CW-7** 

Date Collected:

2/26/98

Date Submitted:

3/18/98

Date Reported:

4/21/98

	onmouth	NJ 07703					
Lab#	Samplel TestGroup	) Analyte		Units	MDL	PQL	Result
AA62903	3367.01-	03					
The state of the s	% Solids						80
		% Solids		Percent			<b></b>
	Reactive Cya	NICE Cyanide (Reactive)		mg/kg	100	100	nd
	Reactive Sulf	• •					
	Reacure out	Sulfide (Reactive)		mg/kg	250	250	nd
	TCLP Herbici	ides					
		2,4-0		mg/L (PPM) mg/L (PPM)	0.00046 0.00066	0.002 0.002	ND ND
	Total Organic	Silvex		mgsc (r r m)	0.0000		
	rotal Organic	Total Organic Halogen		mg/kg	25	25	nd
0.00004	3367.04-						
AA62904		-					
	% Solids	% Solids		Percent			82
	Reactive Cya						
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Cyanide (Reactive)		mg/kg	100	100	nd
	Reactive Sulf	fide	•				
		Sulfide (Reactive)		mg/kg	250	250	nd
	TCLP Herbic			mg/L (PPM)	0.00046	0,002	ND
		2,4-0 Silvex		mg/L (PPM)	0.00068	0.002	ND
	Total Organic	c Halide					
	_	Total Organic Halogen		mg/kg	24	24	nd
AA62905	3367.07	-09					
	% Solids						
	,, CO	% Solids		Percent			76
	Reactive Cya	nide					
		Cyanide (Reactive)		mg/kg	100	100	nd
	Reactive Sul				250	250	nd
		Sulfide (Reactive)		mg/kg	250	200	
	TCLP Herbic	ides 2,4-0	•	mg/L (PPM)	0.00048	0.002	ND
		Silvex		mg/L (PPM)	88000.0	0.002	ND
	Total Organi			_		20	nd
		Total Organic Halogen		mg/kg	26	26	IIG.

Lab#	SamplelD						
	TestGroup	 Analyte		Units	MDL	PQL	Result
AA6290	6 3367.10-13						
AAGZSU				<del></del>			
	% Solids	% Solids		Percent			81
	Reactive Cyanid						
	Reactive Oyuma	Cyanide (Reactive)		mg/kg	100	100	nd
	Reactive Sulfide	•				252	
		Sulfide (Reactive)		mg/kg	250	250	nd
	TCLP Herbicide	s		mg/L (PPM)	0.00048	0.002	ND
		2,4-D Silvex	•	mg/L (PPM)	0.00066	0.002	ND
	Total Organic H	alide					*.
		Total Organic Halogen		mg/kg	24	24	nd
AA6290	7 TCLP Blan	k		•			
	TCLP Herbicide	s	•				
	, 52 , , , , , , , , , , , , , , , , , ,	2,4-D		mg/L (PPM) mg/L (PPM)	0.00046 0.00066	0.002 0.002	ФИ ФИ
		Silvex		mg/L (FFM)	0.0000	0.102	
	This report is a true	e report of results obtained fro	om our tests of this ma	terial. In lieu of a	formal contract	ct document,	the total
	aggregate li	ability of Veritech to all parties	shall not exceed Veri	tech's total fee for	analytical sen	nces rendere	a.
	Chris H	eltrel	Or				
Ch	ıris Heltzel - Lab	oratory Manager	St	anley Gilewic	z - Laborato	ry Director	•

# Fort Monmouth Environmental Testing Laboratory

Bidg. 173, SELFM-PW-EV, Fort Monmouth, NJ 07703

Tel (732)532-4359 Fax (732)532-3484 EMail:appleby@doim6.monmouth.army.mil

Chain of Custody Record Remarks / Preservation Method WARA 3-13-95 \* TCLP extraction (OH 3/14/18) Comments: date Date/Time: Received by (signature): Date/Time: | Received by (signature): Analysis Parameters Relinquished by (signature): Relinquished by (signature): Remarks: bottles 2 weeks Sample Type Location: CW-7 Received by (signature): Received by (signature): Time Days, (\_)ASAP Verbal Repr. Type: (\_)Full, (\_)Reduced, (MStandard, (\_)Screen / non-certified Project No: 8× 72-2 Date 3367.64-06 Date/Time: 3367.07-09 3367.01-03 8124 3367,10-13 Sample Location and time: (\_)Standard 4 wks, (\_)Rush DERA (NOMA ( )Other: Samplers Name / Company: Refinquished by (signature): Achinquished by (signature): Lab Sample I.D. 2905 Customer: Phone #:

Date Received: Client:	3-13-88 Filed By: TF  F+ Mon mout 4 Project/Account:
	INITIAL CONDITIONS
YES NO	or an analysis of the samples?
	[1] Is there a corresponding Chain of Custody included with the samples?
	[2] Are the samples in a container such as a cooler or ice chest?
	[3] Are the custody seals intact?  IF NO, please circle one of the following: missing broken
<u>29</u> ℃	[4] Please specify the temperature inside the container.
	SAMPLE INFORMATION
YES NO	
	[5] Are the samples properly refrigerated (where required)?
	[6] Are the samples within holding times for the parameters listed on the COC'
	If NO, list parameters and associated samples:
	Land balong
	[7] Are all of the sample bottles intact? If NO, specify sample numbers below:
	broken:
	leaking:
	[8] Are all of the sample labels or numbers legible? If NO, specify:
	Samples  Samples
	[9] Do the contents of the container which the transcript and 107-00
	and 10-13) has four Jars a blece  [10] Is there enough sample sent for the analyses listed on the COC? If NO. specify:
0	[10] Is there enough sample sent for the analyses listed on the COC III Jars on [1]  Samples 3367 (01-03) (04-06) has soil Jars on [1]
	and (07-09) [0-13) has 3511 and 219 and 5 and pH readings)?  [11] Are the samples preserved correctly (see Preservation Form for actual pH readings)?
	[12] Are all soil VO(NJ) samples properly preserved in methanol with the correct soil weights
	(8g - 12g) and accompanied by dry soil?
	(8g - 12g) and accompanies of the
	OTHE
	OTHE
	[13] Specify:
	[13] Specify:
	CORRECTIVE ACTION
NO.	ACTION

### Form1 ORGANICS TCLP HERBICIDES REPORT

Sample Number: AA62903

Client Id: 3367.01-03 Data File: CNU81.ATB

Data Analyzed: 04-01-1998

Matrix: Water

Initial Volume: 100ml

Final Volume: 10ml

Dilution Factor: 1

Percent Solids: 0

Date Received/Extracted: 3/13/98-3/20/98

Column: J&W-Scientific db-608/1701 30m .32mmID

CAS#	Compound	PQL/MDL	Concentration mg/L (PPM)
94757	2,4-D	0.0020	U
93721	Silvex	0.0020	

### Total Target Concentration 0

U - Indicates the compound was analyzed but not detected.

J - Indicates an estimated value when a compound is detected at less than the specified detection limit.

B - Indicates the analyte was found in the blank as well as in the sample.
E - Indicates the analyte concentration exceeds the calibration range of the instrument.

\*\*\*\*\*\* EXTERNAL STANDARD TABLE Data File: P:CNU81 \* Sample Name: AA62903, A, HERB \* Date: 04-01-1998 10:31:35 Method: R:MHERBU 04-01-1998 08:55:55 # \* Interface: 5 Cycle#: 81 Operator MCS Channel#: 0 Vial#: N.A. Starting Peak Width: 2 Threshold: 5 Area Threshold: 1000 \*\*\*\*\*\*\*\*\*\*\*\*\* Column Type: CAPILLARY/MEGABORE Instrument Type: HP-5890 Solvent Description: \* Conditions: 150deg/.5m 5deg/m to 270 hold for 10 Detector 1: ECD Detector 0: ECD \* Misc. Information: DET 0: DB-1701 -- DET 1: DB-608 SCRN: \*\*\*\*\*\*\*\*\*\*\*\* Ending retention time: Starting Delay: 0.00 500 One sample per 0.202 sec. Area reject: Dilution factor: 1.00 Amount injected: 1.00000 Sample Weight: REF \* DELTA AREA/ CONCENTRATION in NORMALIZED PEAK PEAK RET RET TIME PEAK CONC/AREA HEIGHT HEIGHT BL NUM TIME -8.0653E-03 906 2369 <u>-0.2755%</u> 6031 3.3 1 14 1815 -3 3707 ---7.3184E-04 17 ... 0 6506 2.0 1

18435

3.4 1

n 7001%

1233.0780 100.7677% 538194 157278

TOTAL AMOUNT = 1223.6834

17 . 3 377 2 4 5-5

18 3.592 2,4-db

4 7615

0


7.8401E-03

Areas, times, and heights stored in: P:CNU81.ATB

Data File = P:CNU81.PTS Printed on 04-02-1998 at 11:02:48

Start time: 0.00 min. Stop time: 12.50 min. Offse

Full Range: 200 millivolts Offset: 0 mv.



# ORGANICS TCLP HERBICIDES REPORT

Sample Number: AA62904

Client Id: 3367.04-06

Data File: CNU82.ATB

Data Analyzed: 04-01-1998

Date Received/Extracted: 3/13/98-3/20/98

Matrix: Water

Initial Volume: 100ml

Final Volume: 10ml

Dilution Factor: 1

Percent Solids: 0

Column: J&W-Scientific db-608/1701 30m .32mmID

CAS#	Compound	PQL/MDL	Concentration mg/L (PPM)
94757	2,4-D	0.0020	U
93721	Silvex	0.0020	U

### Total Target Concentration 0

U - Indicates the compound was analyzed but not detected.

J - Indicates an estimated value when a compound is detected at less than the specified detection limit.
B - Indicates the analyte was found in the blank as well as in the sample.

E - Indicates the analyte concentration exceeds the calibration range of the instrument.

\*\*\*\*\*\* EXTERNAL STANDARD TABLE \*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\* 04-02-1998 11:02:50 Version 5.1 \*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\* Data File: P:CNU82 \* Sample Name: AA62904, A, HERB \* Date: 04-01-1998 10:49:36 Method: R:MHERBU 04-01-1998 08:55:55 # \* Interface: 5 Cycle#: 82 Operator MCS Channel#: 0 Vial#: N.A. \* Starting Peak Width: 2 Threshold: 5 Area Threshold: 1000 \*\*\*\*\*\*\*\*\*\*\*\*\*\*\* Column Type: CAPILLARY/MEGABORE \* Instrument Type: HP-5890 Solvent Description: \* Conditions: 150deg/.5m 5deg/m to 270 hold for 10 Detector 1: ECD Detector 0: ECD \* Misc. Information: DET 0: DB-1701 -- DET 1: DB-608 SCRN: \*\*\*\*\*\*\*\*\*\*\*\*\*\*\* Ending retention time: Starting Delay: 0.00One sample per 0.202 sec. 500 Area reject: Dilution factor: 1.00 Amount injected: 1.00000 Sample Weight: REF CONCENTRATION in NORMALIZED AREA/ PEAK RET RET TIME PEAK CONC/AREA CONC AREA HEIGHT HEIGHT BL PPB NAME NUM TIME 7.6600E-04 0.4294 7555 1352.3523 100.3435% 599955 174320 3.4 1 14 3.592 2,4-db

TOTAL AMOUNT = 1347.7225

PEAKS NOT FOUND IN THIS RUN
NAME ADJUSTED RET.TIME
2,4-D 2.60


ADJUSTED RET.TIME. REFERENCE PEAK 2.60 2.4-D

703/20

Areas, times, and heights stored in: P:CNU82.ATB
Data File = P:CNU82.PTS Printed on 04-02-1998 at 11:02:52

Offset: 0.00 min. Stop time: 200 millivolts 0 mv. 12.50 min. Start time:

Full Range:



# ORGANICS TCLP HERBICIDES REPORT

Sample Number: AA62905

Client Id: 3367.07-09 Data File: CNU83.ATB

Data Analyzed: 04-01-1998

Date Received/Extracted: 3/13/98-3/20/98

Matrix: Water

Initial Volume: 100ml

Final Volume: 10ml

Dilution Factor: 1

Percent Solids: 0

Column: J&W-Scientific db-608/1701 30m .32mmID

CAS#	Compound	PQL/MDL	Concentration mg/L (PPM)
94757	2,4-D	0.0020	U
93721	Silvex	0.0020	

### Total Target Concentration 0

U - Indicates the compound was analyzed but not detected.

J - Indicates an estimated value when a compound is detected at less than the specified detection limit.

B . Indicates the analyte was found in the blank as well as in the sample.

E - Indicates the analyte concentration exceeds the calibration range of the instrument.

\*\*\*\*\*\* EXTERNAL STANDARD TABLE Data File: P:CNU83 \* Sample Name: AA62905, A, HERB \* Date: 04-01-1998 11:07:25 Method: R:MHERBU 04-01-1998 08:55:55 # \* Interface: 5 Cycle#: 83 Operator MCS Channel#: 0 Vial#: N.A. \* Starting Peak Width: 2 Threshold: 5 Area Threshold: 1000 \*\*\*\*\*\*\*\*\*\*\*\*\*\*\* Column Type: CAPILLARY/MEGABORE Instrument Type: HP-5890 Solvent Description: \* Conditions: 150deg/.5m 5deg/m to 270 hold for 10 Detector 1: ECD Detector 0: ECD \* Misc. Information: DET 0: DB-1701 -- DET 1: DB-608 SCRN: \*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\* Ending retention time: Starting Delay: 0.00 Area reject: 500 One sample per 0.202 sec. 1.00 Dilution factor: Amount injected: 1.00 1.00000 Sample Weight: \* DELTA REF AREA/ NORMALIZED CONCENTRATION in PEAK RET PEAK RET TIME AREA HEIGHT HEIGHT BL PEAK CONC/AREA CONC PPR NUM TIME NAME \_\_15\_-7.9770E-04 0.53631 25036 7 0908 15 3 177 2 4 5-b 16 7.7757E-03 587964 170578 3.4 1 1326.3666 100.3209% 16 3.592 2,4-db

> 1322.1245 TOTAL AMOUNT =

PEAKS NOT FOUND IN THIS RUN ADJUSTED RET.TIME. REFERENCE PEAK NAME 2.59 2,4-D

2,4-D

```
****** EXTERNAL STANDARD TABLE
Data File: P:CNU87
* Sample Name: AA62906, A, HERB
* Date: 04-01-1998 12:18:49 Method: R:MHERBU 04-01-1998 08:55:55 # 125
* Interface: 5 Cycle#: 87 Operator MCS Channel#: 0 Vial#: N.A. * Starting Peak Width: 2 Threshold: 5 Area Threshold: 1000
************
                                  Column Type: CAPILLARY/MEGABORE
  Instrument Type: HP-5890
            Solvent Description:
* Conditions: 150deg/.5m 5deg/m to 270 hold for 10
                                      Detector 1: ECD
           Detector 0: ECD
* Misc. Information: DET 0: DB-1701 -- DET 1: DB-608 SCRN:
************
                                     Ending retention time:
Starting Delay: 0.00
                                     One sample per 0.202 sec.
               500
Area reject:
                                     Dilution factor:
                                                         1.00
                    1.00
Amount injected:
                    1.00000
Sample Weight:
                                                       * DELTA
                                        AREA/
            CONCENTRATION in NORMALIZED
PEAK RET
        PEAK
                     CONC AREA HEIGHT HEIGHT BL
                                              PEAK
              PPB
NUM TIME
                                5301
                                                            7.2373E-04
                                19356 6399 3-1-1
 16 . 3 380 2,4,5at
```

1173.9882 100.1861% 521381 148961 3.5 1

TOTAL AMOUNT = 1171.8080

17 3.596 2,4-db

PEAKS NOT FOUND IN THIS RUN

NAME ADJUSTED RET.TIME. REFERENCE PEAK

Dicamba 1.96 Dicamba


298 y 02/986

7.8812E-03

Areas, times, and heights stored in: P:CNU87.ATB
Data File = P:CNU87.PTS Printed on 04-02-1998 at 11:03:44

0.00 min. Stop time: Offset: 12.50 min. 0 mv.

Start time: Full Range: 200 millivolts



# ORGANICS TCLP HERBICIDES REPORT

Sample Number: AA62907

Client Id: TCLP Blank

Data File: CNU88.ATB

Data Analyzed: 04-01-1998

Date Received/Extracted: 3/13/98-3/20/98

Initial Volume: 100ml

Matrix: Water

Final Volume: 10ml

Dilution Factor: 1

Percent Solids: 0

Column: J&W-Scientific db-608/1701 30m .32mmID

CAS#	Compound	PQL/MDL	Concentration mg/L (PPM)
94757	2,4-D	0.0020	Ü
93721	Silvex	0.0020	

### Total Target Concentration 0

U - Indicates the compound was analyzed but not detected.

J - Indicates an estimated value when a compound is detected at less than the specified detection limit.

B - Indicates the analyte was found in the blank as well as in the sample.

E - Indicates the analyte concentration exceeds the calibration range of the instrument

### \*\*\*\*\*\* EXTERNAL STANDARD TABLE \*\*\*\*\*\* \* 04-02-1998 11:03:46 Version 5.1 \*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\* Data File: P:CNU88 \* Sample Name: AA62907,A,HERB \* Date: 04-01-1998 12:36:39 Method: R:MHERBU 04-01-1998 08:55:55 # 1250\* Operator MCS Channel#: 0 Vial#: N.A. \* Interface: 5 Cycle#: 88 \* Starting Peak Width: 2 Threshold: 5 Area Threshold: 1000 \*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\* Column Type: CAPILLARY/MEGABORE \* Instrument Type: HP-5890 Solvent Description: \* Conditions: 150deg/.5m 5deg/m to 270 hold for 10 Detector 1: ECD Detector 0: ECD \* Misc. Information: DET 0: DB-1701 -- DET 1: DB-608 SCRN: \*\*\*\*\*\*\*\*\*\*\*\*\*\*\* Ending retention time: 0.00 Starting Delay: One sample per 0.202 sec. 500 Area reject: Dilution factor: 1.00 Amount injected: 1.00000 Sample Weight: \* DELTA AREA/ CONCENTRATION in NORMALIZED CONC/AREA PEAK RET RET TIME PEAK AREA HEIGHT HEIGHT BL . PPB CONC NUM TIME NAME -1.1391E-02 1.6767E-05 0.00282 -4.3923E-03 2366 891 2.7.1 4.5691E-04 10361 3083 3.4 1 35 3 387 7,4,5-E 8.0223E-03 101.1456% 416627 121137 3.4 1 971.8035 16 3.596 2,4-db

TOTAL AMOUNT = 960.7969


Color Young

Areas, times, and heights stored in: P:CNU88.ATB

Data File = P:CNU88.PTS Printed on 04-02-1998 at 11:03:47

Start time: 0.00 min. Stop time: 12.50 min. Offse Offset: 0 mv.

200 millivolts Full Range:





#### APPENDIX K

Hazardous and Non-Hazardous Waste Manifests and Disposal Certificates
State of New York Hazardous Waste Manifest, November 1997
Certificates of Disposal, CWM Chemical Services, Model City, NY, November 1997
Certificate of Destruction and Recycling, Clean Earth of New Castle, New Castle,
DE, June 1998

# YB8830755

STATE OF NEW YORK
DEPARTMENT OF ENVIRONMENTAL CONSERVATION

DIVISION OF SOLID & HAZARDOUS MATERIALS



\*lease type or print. Do not staple.

#### **HAZARDOUS WASTE MANIFEST** P.O. Box 12820, Albany, New York 12212

				-				·	
_	UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's	S US EPA No.		st Doc. No.		, anom	nation withi required b	in heavy bold line y Federal Law.
	FORT MONMOUTH MI 07703 SE	ectronic Lem-Ph-ev,	COMMANO CHARLES W	OOO AITEA		A. B. G	NYB 8	3830	755
	Generator's Telephone Number     Transporter 1 (Company Name)		L 6 410 ED4 18	Alleration	·.		HAME	· · · · · · · · · · · ·	· ·
	Freeliold Cartage	e Inc	6. US EPAID	Number 4 1 2 6	111 44		ransporter's Te		743 4627
	7. Transporter 2 (Company Name)		8. US EPA ID			E. S	State Transporte	rs ID 🛭 🛂	K1871- NJ
	FREEHOLD CARTAGE  9. Designated Facility Name and Site Address	INC	M2DQ2	7126	167		ransporter's Tel	ephone (*	1321462-1001
	EVA CHEMICAL SERVICES, INC. 1550 BALMER RD.		10. US EPA ID	) Number					1
	MODEL CITY NY 14107		排了到初年		6 7 9		acility Telephor	-0231	, 
1	11. US DOT Description (Including Proper Shipp	oing Name, Hazard	Class and ID Num	ıber)	12. Cont Number		13. Total Quantity	14.Unit Wt/Vol	1
	a RQ. PULYCHLORINATED BIPHE	HTL. HLXTUR	E.9,082315	. 1 & L	TTGINGET	1,750	Quantity	1	EPA MORE
	:				991	OM	1977	3 K	STATE (MA)?
_	b.		· · · · · · · · · · · · · · · · · · ·						EPA
HAIO					11				STATE
E P	C				!!				EPA
	and the second s								STATE
	d.	· · · · · · · · · · · · · · · · · · ·	<del></del>	· · · · · · · · · · · · · · · · · · ·			<del></del>		EPA ,
1					11	1	1111		STATE
1	J. Additional Descriptions for Materials listed Abo	ove		<del></del>		K. Ha	andling Codes for	or Wastes	Listed Above
ŀ	a	С	· · · · · · · · · · · · · · · · · · ·			a		<u> </u>	
	ь 11			1 1	ı	ь			
t	15. Special Handling Instructions and Additional	Information ////	1× 147	······································	·	D.			
	a. PCB Out of Service Date:				•		,,,,		
	CHERTREC Emergency Response	·					8147		
	<ol> <li>GENERATOR'S CERTIFICATION: 1 her dassified, packed, marked and labeled, and are regulations and state laws and regulations.</li> </ol>	n an respects in p	roper condition for	transport by high	way accord	ing to a	pplicable internat	ional and r	national government
	If I am a large quantify generator, I certify that I hat practicable and that I have selected the practicab health and the environment; OR If I am a small get me and that I can afford.	HI ITHEUTOO OF TREATME	nt storage or dispo	cal cumantu avai	ishle to me	which m	unimizac tha arac	ant and fut	ura throat ta burana
	Printed Typed Name No. Fall	<b>)</b> ^\.	Signature	uph C	mi	606	Un	1/	Mo. Day Year
-	<ol> <li>Transporter 1 Acknowledgement of Receipt or Printed/Typed Name</li> </ol>	Materials	1 5:	1	: 1//				do. Day Year
	Harold Jordan		Signature	- woll	/ _	_			
-	18. Transporter 2 Acknowledgement of Receipt of	f Materials	· · · · · · · · · · · · · · · · · · ·	/	/			<del>-</del>	
	Printed Typed Name PAUL W BLACK	· ·	Signature	Paule	Black	r.	`ـِ`	1	
T	19. Discrepancy Indication Space								
	setul jund	17	741 K	<u></u>	<del></del>	·			
	20. Facility Owner or Operator: Certification of rec	ceipt of hazardous	1	by this manifest	except as	noted in	n Item 19.	<del></del>	A. Day Year
ľ	Caloon M	1 1000	Signature	1.	a.,			۰ . ۱	No. Day Year

# DISPOS STANDARDS FOR NEW YC (STATE REGULATED HAZARDOUS PCB WASTES

GENERATO	R NAME: US ARMY COMMU	NICATIONS ELECTRONIC	COMMAND				
MANIFEST #	<sup>4</sup> NYB8830755	CWM PROFIL	E#BV-2104				
UNIQUE DR	UM#NA	_ OUT OF SERVICE D	ATE: <u>// ←/</u>	4-97			
	NY State regulated wastes and Part 376. Refer to 6 NYCRR 3						
[] B001	[] B002 [] B003	[] B004 [] B005	[] B006	<b>B</b> 007			
Certification -	Waste Meets Treatment Standa	urds					
×	I am the generator of the wast under 6 NYCRR Part 376. It applicable treatment standards fore, it can be land disposed w	nave determined that this was set forth in 6 NYCRR 370	aste meets all				
I certify under penalty of law that I personally have examined and an familiar with the waste through analysis and testing or through knowledge of the waste to support this certification that waste complies with the treatment standards specified in Part 376, Section 376.4 and all applicable prohibitions set forth in subdivision 376.3(b) of Part 376 or RCRA Section 3004(d). I believe that the information I submitted is true, accurate and complete. I am aware that there are significant penalties for submitting a false certification including the possibility of a fine or imprisonment.							
Notification -	Waste Does Not Meet Treatme	nt Standards					
[]	I am the generator of a waste identified above. I notify the familiar with the waste the knowledge of the waste to surnot comply with the treatment 376.4(f). This waste must be to in 6 NYCRR 376.4(f) prior to	at I personally have examough analysis and testing pport this notification that the standards specified in 6 reated to the applicable standards.	nined and am g or through he waste does NYCRR Part				
GENERATO	r's signature: 010	phm. Fall	Um	1			
- ^	wonmertal Dec	intest DATE:	11/18/	97			

updated 04/24/97



#### Waste Management, Inc.

CWM Chemical Services, Inc. 1550 Balmer Rd. P.O. Box 200 Model City, N. Y. 14107 Phone 716/754-8231

Federal EPA ID: NYD049836679

US ARMY COMMUNICATION/ELECTRONIC COMMAND ATTN: SELFM PW EV NJ2210020978 CHARLES WOOD AREA FORT MONMOUTH NJ 07703

#### CERTIFICATE OF DISPOSAL

CWM Chemical Services, Inc. has received waste material from US ARMY COMMUNICATION/ELECTRONIC COMMAND on 11/21/97 as described on Hazardous Waste Manifest number NYB8830755 Sequence number 01. CWM Chemical Services, Inc., hereby certifies that the above described material was landfilled in accordance with the 40 CFR part 761 as it pertains to the land disposal of polychlorinated biphenyl contaminated materials.

Profile Number: BV2104 CWM Tracking ID: 8147832201

CWM Unit #: 1\*0
Disposal Date: 11/21/97

Under civil and criminal penalties of law for the making or submission of false or fraudulent statements or representations (18 U.S.C 1001 and 15 U.S.C. 2615) I certify that the information contained in or accompanying this document is true accurate and complete. As to the identified section(s) of this document for which I cannot personally verify truth and accuracy, I certify as the company official having supervisory responsibility for the persons who, acting under my direct instructions, made the verification that this information is true accurate and complete.

Certificate # 100036

For questions please call our Customer Service Dept. at (800) 843-3604

\*U.S. GOVERNMENT PRINTING OFFICE: 1994-510-852

80,010 (Lbs. G.) 43, 430 (Lbs. G.) 43, 580 (Lbs. Lbs. I. & April (Lbs. N.) 43, 580 (Lbs. I. & April (	WEIGHTMASTER US Army Garrison Fort Monmouth  HT TICKET Directorate for Installation Logistics, Sup Svcs Div. Fort Monmouth, New Jersey 07703
36, 430  28, 430  28, 430  21, 1 the Mbs. The Man of Common of Com	WEIGHT
36, 430  43, 580 JIN THY THE	80,010
43,580 21. 1 the Lab. No. 19. 1 the Lab. No. 19. 10. 10. 10. 10. 10. 10. 10. 10. 10. 10	
DX# 400 BIL NUMBER  ITH - DWW - ENVIRO  DRIVER SIGNATURE  THE DRIVER ON THE COMMODING OF CARRIER  WEIGHMASTER	21.8 trus
THE GO BOX# 4606  FOR SHIPPER  THOMMUTH - DIW - ENVIRO  THOM	
Monmuth - DMV - ENVIRO  PRINCE SIGNATURE  THE DAINER SIGNATURE  THE DAINER OF CARRIER  THE CARRI	5016
Monmuth - DNW - ENVIRO  SHIVER SIGNATURE  TO DANCE ON  WEIGHMASTER	
PRIVER SIGNATURE  DRIVER SIGNATURE  DRIVER SIGNATURE  WEIGHMASTER	V. ENVIRO ITAIT
□ DRIVER ON WEIGHMASTER	
☐ DRIVER ON WEIGHMASTER	
	□ DRIVER ON X DRIVER OFF
	WEIGHMASTER
10 NOU 99	Luna



#### P.O. BOX 5010 • FREEHOLD, NJ 07728-5010 (732) 462-1001 • FAX (732) 308-0924

MANIFEST FCI EPA ID NO: NJD054126164 T22762

	175 BARTOW MUN. AIRPORT BARTOW, FL 33830 PHONE: [941] 533-4599 FAX: [941] 533-1613	108 MONAHAN DUNMORE, PA PHONE: (717); FAX: (717) 342	18512 1 342-7232 F	950 PIGEON POIN NEW CASTLE, DE PHONE: (302) 658 FAX: (302) 658-622	19720 E 2005 F	UTAWVILL	VOOD DENVE LE, SC 29948 X: [803] 492-9595	<b>I</b> 3	FCI EPA I NJD0541	12616
ERATOR NAME/ADDRESS FOR TOWN CIREP. LOADING (PRINT) HOLD OF TOWN COMMENTS OR DELAYS AT G	NTO 7 PROCE RIO CLA Live	703 TRAC	732)		. 622 EX REMOVE 20 -1	- 2	APPOINTMENT TIJ	TOR (MILIT	209  ARY TIME ONL  2:36  PARTURE TIME  EVERY	$\geq$
3ROKER: £ ( ) ~	TRON	. ,		STATE	MANIF	EST	NO.: 41(1	050	200	
PO#:	WO#:		<sub>T</sub> 1			1	1 · ·	15,00	001	15
PROPER U.S. D.O.	T. SHIPPING NAME	U.S. D.O.T. HAZARDOUS CLASS	NA/UN/NO.	PACKING GROUP	NO. CONT.	CONT. TYPE	NET QUANTITY	UNIT MEASURE	WASTE NO.	FORM
1 See man	ifost	9	2315			Cm	19773	9	B∞7	S
3										
"NERATOR'S CERTIFICATION portation according to the applicatment, Storage or Disposing knowledge.	plicable regulations of the E sal Facility can and will acc	epartment of Tra ept the shipment of	nsportation, U.S of hazardous wa	EPA and the S iste, and has a v	tate. The wa ralid permit (	istes desc to do so. I	cribed above were co certify that the foreg	onsigned to the oing is true and	Transported r correct to the	named. best of
2 the contractor. PLEASE PRINT NAME/TITLE	<del></del>	GE	NERATOR'S SI	GNATURE				DATE LOAD	ED	
Josaph Fal	lon	х		ABOVE AND SINDE	RISTAND AND A	AGREE TO A	LL OF ITS CONTENT.	11 / MO.	18 /9	) <u>/</u> YR.
TSDF NAME/ADDRESS, CWM Chain 1550 Buln	jer Ro	COL PHONI (AREA TRACT	CODE	TRAILER	- 82.	اد	TSDF EPA ID NO.  APPOINTMENT TIN	198E	366	79
CI REP. UNLOADING (PRINT)	PROCEL	DURE	BOX SPOTT	ED BO	X REMOVE	.D	TIME AT TSDE	· ·	ARY TIME ONLY	n —
COMMENTS OR DELAYS AT TS	DF						EQUIPMENT USED			
PLEASE PRINT NAME/TITLE		X	OF SIGNATURE			1		DATE UNLO	/_	YR.
PC 944 CT CT-HW-307 1 DE DE-HW-203	ME ME-HWT-47 ME-WOT-47 MD HWH-167 96-OP-1765 MA MA-294	MO H-1490 ND WH-429 NH TNH-00 NJ S-2265		NOVA SCOT OH 333-HW OK 3358 ONTARIO, C	,		RI TX	EBEC, CANAE RI-535 40705 11602	DA QC-6ML-0	147

PA PA-AH-0067

NJ S-2265 15939

NY JA-113

SWH-1540

MN 61572

# DEPARTMENT OF ENVIRONMENTAL CONSERVATION DIVISION OF SOLID & HAZARDOUS MATERIALS

# **HAZARDOUS WASTE MANIFEST**

Please type or print. Do not staple.

P.O. Box 12820, Albany, New York 12212

		erator's US EPA No	o. Mani   u   y   / a / //	fest Doc. No.	2. Pag	- 111101		heavy bold line Federal Law.	
	3. Generator's Name and Mailing Address (A) ARMY CAMMINING STECTRONI SELFH-UL-EN-HU STIFF-DI-		S WOOD AREA		Ä.	^ NYB8830764			
	FORT HONMOUTH BJ 07763	u made aster	`		enerator's ID				
	4. Generator's Telephone Number  5. Transporter 1 (Company Name)	6 USE	PA ID Number	<del>-</del>	<u> </u>		ter's ID 🔥 😅	1 1	
	Firshold Chitage INC	بمعديا ا		SH(14				11 ( ) 41 . 100	
1	7. Transporter 2 (Company Name)	8. USE	PA ID Number	. 1 /1 1 5				A= 1180 N	
ı	9. Designated Facility Name and Site Address	4 5 4	15411	9 7 9		ansporter's T tate Facility II		1081 462-10	
	CVN CHENICAL SERVICES, 1963.	• * • • •		•	u. 5	tato i domity it			
	1550 BALMER RD. MODEL CITY WY 14107	10. US 1	EPA ID Number	21211111111	H. Fa	acility Telepho	one (	)	
	GOOGL CITT BY 14101	(A) ( D)	0 5 9 8 3	╼╁╾┵┷╌	L	13. Total	14.Unit	1	
	11. US DOT Description (Including Proper Shipping Name, F	lazard Class and I	D Number)	12. Con	. 1	Quantit			
	a. EQ. POLYCHLONINATED BIFHERYL MI	TURE, 9, UN	2315,111	112113	177-			EPA MUNC	
				lagi		2772	215 K	STATE BOO7	
	b:			1911		<u> 77 (1 (1 7</u>	<del></del>	EPA	
8				1.,	<u> </u>	1 1 1	,	STATE	
ERATOR							<u> </u>	EPA	
g E	<b>c.</b>								
								STATE	
	d						.	EPA	
						111	1	STATE	
	J. Additional Descriptions for Materials listed Above	<del></del>			K. Ha	ındling Codes	for Wastes	Listed Above	
	1872104  a		4 : 1	1 1	a		]   。		
1							7	<b></b>	
	b d	l 1 i	. [.	1.1	Ь		<u> </u>		
	15. Special Handling Instructions and Additional Information	, , ,	r7		٠.,				
İ	A. M.B. Out of Service Date:	T (800) 1424	-8300	٠.	Gred Gred	/ <b>7</b> /2	17 -		
	16. GENERATOR'S CERTIFICATION: I hereby declare	that the contents of	this consignment are	fully and accu	rately de	scribed above	by proper ship	pping name and are	
	classified, packed, marked and labeled, and are in all respe regulations and state laws and regulations.	cts in proper condit	ion for transport by h	nighway accor	ding to a	pplicable inten	national and r	national government	
	If I am a large quantity generator, I certify that I have a program practicable and that I have selected the practicable method of health and the environment; OR if I am a small generator, I hav	treatment, storage,	or disposal currently a	avallable to me	which m	ninimizes the p	resent and fut	ture threat to human	
-	me and that I can afford. Printed/Typed Name	Signature		1 6	70	· · · · · · · · · · · · · · · · · · ·	<del> </del>	Mo. Day Year	
	Joseph M. Hallon		- Jose	ph"	In.	tall	lan 1	111/1/1	
Ţ	17. Transporter 1 Acknowledgement of Receipt of Materials				The A	/		Va Day Var	
į	Printed/Typed Name	Signature	e jaren. Karansa		9.7	٠, ١	ı'	Mo. Day Year	
Z P	18. Transporter 2 Acknowledgement of Receipt of Materials			***************************************	<u> </u>				
1	Printed/Typed Name	Signature	•		,			Mo. Day Year	
+	19. Discrepancy Indication Space		· · · · · · · · · · · · · · ·	<del></del>					
	A. T. Francisco Company	277	101 W						
<u> </u>	20. Facility Owner or Operator: Certification of receipt of haz	ardous materials o	overed by this manif	achaycant a	s noted i	n Item 19			
٤	Printed Typed Name	Signatu	<del>,</del>	CSI Except d	Y HOLBU I		<del></del> ,	vio. Day Y	
	Colson M I Jose	10/	10/11	M.	1	Market Market		والخليليا	
	COPY 5-(	Generatorm	ailed by TSD	facility			· ·		

# DISPC L STANDARDS FOR NEW Y RK STATE REGULATED HAZARDOUS PCB WASTES

•						
GENERATO	R NAME: US	S ARMY COM	TUNICATIONS	ELECTRONIC	COMMAND	
MANIFEST	#NYB883076	54	C	WM PROFIL	E#BV-2104	1
UNIQUE DI	RUM #	A .	OUT OF	SERVICE I	DATE: <u>                                     </u>	4-47
The following to 6 NYCRR all that apply:	, NY State regula Part 376. Refer t	ted wastes ar o 6 NYCRR	nd land restrict 376.4(f) for N	ed in the State Iew York land	e of New York I disposal requ	and are subject irements. Check
[] B001	[] B002	[] B003	[] B004	[] B005	[] B006	B007
Certification -	Waste Meets Tre	eatment Stand	lards			
X	I am the general under 6 NYCR applicable treating fore, it can be last a certify under familiar with the knowledge of complies with a 376.4 and all applicable applications or RC submitted is the submitted in the submitted in the submitted in the submitted is the submitted in th	R Part 376. If ment standard and disposed appenalty of law the waste the waste the treatment plicable prohocological prohocolo	have determined set forth in without further without further without further withough analysto support the standards spibitions set for 3004(d). I be	ned that this was 6 NYCRR 37 or treatment.  Inally have existed and testing and testing certification ecified in Parth in subdivision believe that the	aste meets all 6 and, there- amined and an g or through on that waste t 376, Section on 376.3(b) of information I	
•	significant pena possibility of a f	Ities for sub-	mitting a false	e certification	including the	
Notification -	Waste Does Not 1	Meet Treatme	ent Standards			
[]	I am the generate identified above familiar with the knowledge of the not comply with 376.4(f). This was in 6 NYCRR 37	e. I notify the waste the waste to sun the treatments aste must be	nat I personal rough analysi pport this not on standards streated to the	ly have exames and testing ification that the specified in 6 applicable stares.	nined and am g or through he waste does NYCRR Part	
GENERATOR	r'S SIGNATURE	: Osc	reph )	n Fol	Usr .	
Δ.	ulron min	the D.	Lecentor	DATE:	11/18	197

updated 04/24/97



#### Waste Management, Inc.

CWM Chemical Services, Inc. 1550 Balmer Rd. P.O. Box 200 Model City, N. Y. 14107 Phone 716/754-8231

Federal EPA ID: NYD049836679

US ARMY COMMUNICATION/ELECTRONIC COMMAND ATTN: SELFM PW EV NJ2210020978 CHARLES WOOD AREA FORT MONMOUTH NJ 07703

#### CERTIFICATE OF DISPOSAL

CWM Chemical Services, Inc. has received waste material from US ARMY COMMUNICATION/ELECTRONIC COMMAND on 11/21/97 as described on Hazardous Waste Manifest number NYB8830764 Sequence number 01. CWM Chemical Services, Inc., hereby certifies that the above described material was landfilled in accordance with the 40 CFR part 761 as it pertains to the land disposal of polychlorinated biphenyl contaminated materials.

Profile Number: BV2104
CWM Tracking ID: 8147831601
CWM Unit #: 1\*0
Disposal Date: 11/21/97

Under civil and criminal penalties of law for the making or submission of false or fraudulent statements or representations (18 U.S.C 1001 and 15 U.S.C. 2615) I certify that the information contained in or accompanying this document is true accurate and complete. As to the identified section(s) of this document for which I cannot personally verify truth and accuracy, I certify as the company official having supervisory responsibility for the persons who, acting under my direct instructions, made the verification that this information is true accurate and complete.

JIL KNICKERBOCKER
TECHNICAL MANAGER
Certificate # 100035
11/24/97

For questions please call our Customer Service Dept. at (800) 843-3604



P.O. BOX 5010 • FREEHOLD, NJ 07728-5010 (732) 462-1001 • FAX (732) 308-0924

108 MONAHAN AVENUE DUNMORE, PA 18512 PHONE: (717) 342-7232 FAX: (717) 342-7367

350 PIGEON POINT ROAD NEW CASTLE, DE 19720 PHONE: (302) 658-2005 FAX: (302) 658-6229

156 DRIFTWOOD DRIVE EUTAWVILLE, SC 29048 PHONE/FAX: (803) 492-9595

MANIFEST FCI EPA ID NO.: NJD054126164

I38717

	175 BARTOW MUN, AIRPORT BARTOW, FL 33830 PHONE: [941] 533-4599 FAX: [941] 533-1613
--	---

· ` ` <del> </del>		····										
ERATOR NAME/ADDRESS		PHONE	Ē				- 1	GENERATO	OR EPA ID I	NO.	_ 1	1 -
ro mon			00051				<i>\</i>	ノココ	<u>'</u>  Z ı	מאט (	20191	$\Im  \mathcal{C} $
		(AREA TRACT		TRAIL				APPOINTM	ENT TIME			-10
		I TRACT		TRAIL	EH.			APPOINTIV	ICIAL LUME	:		
stontown New 5	د بر بد ہے	ーしめ	S				i		~~~	•		
CI REP. LOADING (PRINT)	PROCEDU	RF	BOX SPOT	ED	вох	REMOVE	D (	TIME AD	ENPRATO	R (MILIT	ARY TIME ON	LY)
	Live			_				A7	720	7 /	1./6	
d5i	PROCEDU Live Loa	10	911	2	1			4000			PARTURE TIME	<u>)                                    </u>
OMMENTS OF DELAYS AT CENERATOR			1 / * *		i		<del></del>		AL TIME	UEI	ARTURE TIME	
OMMENTS OR DELAYS AT GENERATOR								EQUIPMEN	I. USED			•
Acutual Armore 07	3047	LS.					1					
BROKER:									_		~~~	
PO#:	WO#:			STAT	EM	ANIF	EST	NO.: /(	)YB8	36-30	1773	•
X) PROPER U.S. D.O.T. SHIPPING NA	ME HA	U.S. D.O.T. ZARDOUS CLASS	NA/UN/NO.		KING OUP	NO, CONT.	CONT. TYPE		NET NTITY	UNIT	WASTE NO.	FORM
JPQ Polychtoring	+ <del>c</del> l	9	- 5				001	11				
MI ISIDHENYL MY	<b>x</b> .	(	2315	170	_	01	CYM	1 43	840	1	13007	12
	•								(			
2	}			ł		]						
							<u>†                                      </u>	<b></b>		-	†	+
3							i	-				1
PECIAL HANDLING INSTRUCTIONS INCLUI	OINIC CONTAIN	ICO EVELIOTI	ON HE IDENT	ICICATION	CUDI	ACAIT OF	A NON I	14740001	IS MATLINE	- MUICH D	DEC NOT H	VE TO
dE MANIFESTED).  **SNERATOR'S CERTIFICATION: This is to ce portation according to the applicable regula reatment, Storage or Disposal Facility can	tions of the Dep	artment of Tran	rsportation, U.S	EPA and	he Stat	e. The wa	stes desc	ribed above	e were consi	gned to the	Transported	named.
my knowledge.	and win accept	the shipment o	n nazaruous wa	iste, and na	is a van	а ретпи	0 00 50.11	Jeruly mace	ne loregoin	y is title and	·	e DeSi Oi
ayment to the contractor for waste removal doe the contractor.	s not constitute	payment to the	carrier and if th	e contracto	or does	not pay th	e carrier,	the general	tor is obligat	ed to pay th	e agreed rate	offered
L'LEASE PRINT NAME/TITLE		GEI	NERATOR'S S	IGNATURE	_				D	ATE LOAD	ED	
	1 -	1	0.	- 2	-100	7	-//	In		11/	18/	97
Joseph M. Fal	<u>ωα.</u>	Х	I HAY READ THE	AMBOVE AND	UNDERS	FAND AND A	AGREE TO A	L OF ITS CON	ITENT.	MO.	DAY	YR.
SOF NAME/ADDRESS		PHONE						rsof epa	ID NO.			
C.M.M			٠.					WALK	12/1/1	98	2/2/2	フト
		(AREA	<u> </u>					Y Y VO		(DF	اماماد	
(		TRACT	OR	TRAILI	≣R		- 14	APPØINTM	ENT TIME			
model City,	$\alpha + \nabla C$									<b>:</b>		
CI REP. UNLOADING (PRINT)	PROCEDU	:1	BOX SPOTT	ED	BOV	REMOVE	<u></u>	TIME	AT TSDF	/A/II 17	ARY TIME ONL	vs.
Grief : Sheoroling (Filler)	Tr Hoyecool	nı.	BOX SFOTT	LD	BUA	NEWOVE	. [	1 ((4) (2.7	11 1301	(sure)	VIII TIME OUR	-'',
	1		1		1		- [		:	<del></del>	:	
COLUMN TO COLUMN AT TOOK		<del></del>	1		L	·			AL TIME	OEF	PARTURE TIME	
COMMENTS OR DELAYS AT TSDF								EQUIPMEN	II USED			
DI CAOC DOWN HAVE CITY O	<del></del>											
PLEASE PRINT NAME/TITLE		TSC	OF SIGNATUR	Ē					D.	ATE UNLO	ADED .	
		X							·	· /	/	
		^``								MO.	DAY	YR.
AR H-0257 ME ME-HWT PC 944 ME-WOT		MO H-1490 ND WH-429		NOVA S		, CANAD	A NSC	000 147	QUEB RI RI		DA QC-6ML-	047
CT CT-HW-307 MD HWH-167	•	NH TNH-00-		OK 335					TX 40			
DE DE-HW-203 96-OP-17	65	NJ S-2265				NADA A	840943		WI 11			
DE-SW-203 MA MA-294		15939		PA PA	-AH-00	67						

....te - FCI Original Yellow - FCI Billing

SWH-1540

MN 61572

NY JA-113

Blue - FCI Office/Customer Green - Retained by TSDF Gold - Retained by Generator I38717

#### Clean Earth of New Castle, Inc.

#### 94 Pyles Lane New Castle, DE 19720 (302) 427-6633

## Certificate of Destruction and Recycling

This is to certify that the soil delivered to Clean Earth of New Castle, Inc. from the site described in the contaminated soil profile sheet that was issued the Approval Number listed below and represented by the attached treatment report, has been duly treated and rendered safe for beneficial reuse in accordance with the permit to operate issued to Clean Earth of New Castle, Inc. by the Delaware Department of Natural Resources.

Authorized Signature

Paul A. Lane, Operations Manager June 16, 1998

Approval# Generator Site Location 980139

U.S. ARMY, FORT MONMOUTH CHARLES WOOD AREA

FORT MONMOUTH, NJ 08057

Total Tons This Certificate:

33.44

Total Tickets This Certificate:

į.

Treatment Date or Dates:

6/4/98-6/4/98

Dage# 1

Treatment Report

CDR#

9015

Generator

U.S. ARMY, FORT MONMOUTH

Site Location

CHARLES WOOD AREA

FORT MONMOUTH, NJ 08057

Total Tickets 1

Total Tons 33.44

(ppm) (ppb)

X Post TPH I Approval# Ē **Net Tons** 8 Ticket # Rec. Date <10 980139 33.44 ₹5 ⟨5 (15 39960 6/4/98

CENC Delivery Report - DR & Approval\* 6/10/98

From: 6/3/98 Te: Approval 980139 U.S. ARMY, FORT MONMOUTH Generator

CHARLES WOOD AREA FORT MONIMOUTH, NJ. 08057 Origin

\*Loads 415.44 TOTAL

"ats	Ticket*	Approval 8	Truck*	Loc.	Manifest#s.	Net Tons
V98	39898	980139	206	B4	001	24.90
4 J/98	39899	980139	1565	84	002	24.61
3/3/98	39904	980139	2	B4	003	26.32
/3/98	39905	980139	12	B4	004	20,53
6/3/98	39906	980139	04	84	005	24.57
./3/98	39907	980139	1	B4	006	20.06
74798	39919	980139	31	B4	007	25.11
6/4/98	39920	980139	388	B4	008	28.04
, /4/98	39938 -	980139	17	84	009	32.57
74/98	39946	980139	403	B4	010	23.27
6/4/98	39947	980139	400	84	011	25.72
: 1/4/98	<b>3</b> 9950	98Ú 139	6260	B4	012	25.46
jo/4/98	39960	980139	6393	84	013	33.44
6/5/98	39969	980139	401	B4	014	28.63
75/98	39970	980139	400	64	015	26.79
#6/5/98 °	39981	980139	403	B4	016	25.42

415.44 tons



# CLEAN EARTH OF NEW CASTLE, INC. INVOICE DATE

6/4/90

94 Pyles Lane P.O. Box 1049 New Castle, DE 19720-1049 (302) 427-6633

## TREATMENT INVOICE LOAD LIST

Inveice # A-4893
Approval # 980139

Generator U.S. ARMY, FORT MONMOUTH

Load#	Rec. Date	B/L	Manifest#	Net Tons Su	rcharge
39898	6/3/98		001	24.90	N/A
39899	6/3/98		002	24.61	N/A
39904	6/3/98		003	26.32	N/A
39905	6/3/98		004	20.53	N/A
39906	6/3/98		005	24.57	N/A
39907	6/3/98		006	20.06	N/A
39919	6/4/98		007	25.11	N/A
39920	6/4/98 ′	<b>.</b>	008	28.04	N/A

194.14 Jono



# CLEAN EARTH OF NEW CASTLE, INC. INVOICE DATE

6/10/9€

94 Pyles Lane P.O. Box 1049 New Castle, DE 19720-1049 (302) 427-6633

#### TREATMENT INVOICE LOAD LIST

Generator U.S. ARMY, FORT MONMOUTH

Load#	Rec. Date	B/L	Manifest#	Met Tons Su	rcharge
39938	6/4/98		009	<b>32.57</b>	N/A
39946	6/4/98		010	23.27	N/A
39947	6/4/98		011	25.72	N/A
39950	6/4/98		012	25.46	N/A
39960	6/4/98		013	33.44	N/A
39969	6/5/98		014	28.63	N/A
39970	6/5/98	•	015	26.79	N/A
39981	6/5/98 *		016	25.42	N/A

721,3 tons

94 Pyles Lane New Castle, DE 19720 (302) 427-6633 INCOMING LOAD TICKET

24.90

ite	6/3/98			A	(302):42 <b>NCOMING</b> LO
Tirne	11:31 AM	Ī			•
Ticket#	39898			•	
<b>ubbrox</b> a	980139				
The of	Material		Gross	Tare	Het Tons

ON PCB MINERAL OIL

OTES 1:

TES 2:

· ·		
"WM ID#	\$18 JANET W. ELLIOTT	Signature water Electe
"I of Lading#		
anifest#	001	
St. Manifest#		
ans. ID*	157	
ransporter	R.J. I. TRANSPORT	DE-SW Permit# 813
Trans. Addr.	72 ROWLÂND ROAD	
,	CRANBURY, NJ 08512	<u> </u>
iver	HEMINOWAY Tru	ck <sup>#</sup> 206
Sustomer	ECO-TRON NEW JERSEY, INC.	
nerator	U.S. ARMY, FORT MONMOUTH	
merator Site	CHARLES WOOD AREA	
	FORT MONMOUTH, NJ 08057	
Contact 1	TAHER GINWALA	609-893-7873
Contact 2		

94 Pyles Lane New Castle, DE 19720 (302) 427-6633 INCOMING LOAD TICKET

 Oate
 6/5/98

 Time
 8.03 AM

 Tioket#
 39981

, Approval \* 980139

Type of Material	Gross	Tare	Net Tons	Drums
NON PCB MINERAL OIL	77,560	26,720	25.42	

· •		$\wedge$		
			111 6 11 4	_·
WM ID#	618 JANET W. ELLIOTT	Signature MIL	aw din	]
Bill of Lading:	#			
ifest#	016	<b>,</b>		
or Manifest	#	ت		
Trans. ID*	<b>1</b> 19			-
Transporter	THE RESIDENCE AND PARTY OF THE	DE-SW Peri	nit# 077	
Trans_Addr.	3482 WRANGLE HILL ROAD			
	BEAR, DE 19701			
Ÿ	र्वेद्ध विकास ("इस्टेंडन विकास प्रतिकास (इस्टेंडन) विकास विकास (इस्टेंडन)	Service Committee		
Driver	HOWLAND - Truck	<b>4</b> 03		
Customer	ECO-TRON NEW JERSEY, INC.		• •	
Generator	U.S. ARMY, FORT MONMOUTH			
Generator Si	ite CHARLES WOOD AREA			
·	ORT MONMOUTH, NJ 08057			
			å	
	2 1121 (1122)	609-893-7873	- 1	
Contact 1	TAHER GINVALA	B09-093 1013		
Contact 2		经经验的 医多种性		
NOTES 1:			I	
NOTES 2:			I	
marted L.	E			

CLEAN EARTH OF NEW CASTLE, INC. 94 Pyles Lane New Castel, DE. 19720 Tele#(302) 427-6633/800-30EARTH Fax#(302) 427-6634

NON-HAZARDOUS MATER	HALS MANIFEST
The same sent of many and sent section in the	
	NIFEST #_66/
CE	NC TICKET # 39898
GENERATOR'S NAME & ADDRESS	Site Address
HEADMY FORT MONMOUTH	SAME SITE ID #NJ2210020978
DIRECTORATE OF PUBLIC WORKS BLD. 173 SELFA	HOHARLES WOOD AREA
FORT MONMOUTH NJ 07703 PW- EV	SAME
GENERATOR'S PHONE #:732-532-6223	Est. Quanity: 2 2
DESCRIPTION OF MATERIAL:	
NON DOT REGULATED/RCRA NON-HAZARDOUS PETRO	LEUM HYDROCARBON CONT MATERIAL
I harship pertificities the above described materials is not a hazal	dous waste as defined by 40 CFR Part 261 nor is it
contaminated by PCB as defined by 40 CFR part 761. Additional described in the application for treatment provided to Clean Eart	lly it is the same material which was analyzed and
number listed above. It is properly classified and packaged	for transportation in accordance with applicable
regulations	
the mo Clina	TITIO: Drungmente Secontest
Name Joseph H. Fallot	17700401
Signature: MORAN M. Fallon	Date: 6/3/98
TRANSPORTER	
Company RUT TRANSPORT	Phone #
	Gross Weight: 80480 16 11:44 8649/8/89
Address:72 ROWLAND RD, CRANBURY, NJ 08512	
DE SW HAULERS PERMIT#B13	
	Net Weight: 24,90 TO
Driver: GOOGY HEMINWOY (TYPE OR PRINT CLEARLY)	9,000
I hereby certify the above described materials were picked up a	t the above described generator address without
incident and will be delivered without tampering of any kind.	1 600
La L	Date: 6/3/98
Driver Signature	
DESTINATION (	
I hereby certify that the above described materials was delivere	d to Clean Earth of New Castle, Inc. at 94 Pyles
Lane, New Castle, Delaware.	TOWARD TO THE
have been a comment of the comment o	Delta 198
Therein certify that the almost territed material has been acceded.  Lane, New Castle, Delaward.	THE AF HIMM WATTY AT THE WE HATTE IN THE AF THE PA

Authorized Signature

CLEAN EARTH OF NEW CASTLE, INC. 94 Pyles Lane New Castel, DE. 19720 Tele#(302) 427-6633/800-30EARTH Fax#(302) 427-0034

NON-HAZARDOUS MATER	
I I LE OU LUGIT CEMBUCIA	K HUMBER 1363
APPROVAL #980139 MA	WIFEST # 062
CE	NC TICKET # 39899
GENERATOR'S NAME & ADDRESS:	Site Address
IS ARMY FORT MONMOUTH	SAME SITE ID #NJ221002097B
DIRECTORATE OF DIRLIC WORKS BLD 173 SELFM	CHARLES WOOD AREA
FORT MONMOUTH, NJ 07703	
ENERATOR'S PHONE #: 732-532-6223	Est. Quanity: 2 2
DESCRIPTION OF MATERIAL:	
ION DOT REGULATED/RCRA NON-HAZARDOUS PETRO	CLEUM HYDROCARBON CONT. MATERIAL
hereby certify that the above described materials is not a haza contaminated by PCB as defined by 40 CFR part 761. Additional	rdous waste as defined by 4U CFR Part 261 nor is it.
rescribed in the application for treatment provided to Clean Earl	th of New Castle, ho, which resulted in the approval
umber listed above. It is property classified and packaged	for transportation in accordance with applicable
regulations	$\alpha \longrightarrow \beta \rightarrow \gamma$
Jasaph D. Fg. 1997	Title Mulle primer science
Jature Joseph M. Fallay	Title Churco priente Becentral  Date: 6/3/98
<b>TRANSPORTER</b>	
Company RUT TRANSPORT	Phone #
	82820 1b 11:49 AM 06/03/38
Address: 72 ROWLAND RD., CRANBURY, NJ. 08512	_ Gross Weight:
DE SW HAULERS PERMITTEELS	1 61 6 110 6116
Driver EAN HOVERTING	_Net Weight
(TYPE OR PRINT CLEAPCY)	
I hereby certify the above described materials were picked up a neident and will be delivered without tampering of any kind.	t the above described generator address without
Heidelf and All in deliter of Author tartebuilds, and tare	nu 6-3-98
Driver Signature: Coan Denauled	Date: 0 3 / 0
DESTINATION	Jan Crant of Man Cadle has at Q4 Dube
I hereby certify that the above described materials was delivere and, New Castle, Delayare.	
System Stanature: Low Nothing	Xante 6-3-98
I hereby certify that the above described material has been acce	oted at Clean Earth of New Castle, Inc. at 94 Pyles
tane, New Castle, Delayare.	Dete: 6-3-98
Authorized Signature day that the state of t	LANG. GET J. S.

94 Pyles Lane New Castle, DE 19720 (302) 427-6633 INCOMING LOAD TICKET

te 6/3/98 Time 11:43 AM cket# 39899

Approval # 980139

pe of Material	Gross	Tare	Met Tons	<b>≢</b> Di
NON PCB MINERAL OIL	82,820	33,600	24.61	

/			()	41 NC	1 1	
WM ID#	619 JANET W. ELLIOTT	Sig	gnature 42	utu) EE	self	_ }
of Lading#			U			
janifest#	002					
St. Manifest#		<b>5</b> 7	•			
ans. ID#	157			•		
íransporter	R.J.T. TRANSPORT		DE-SW Per	mit# 813		tern get, r terpestyreterisk, my
ans. Addr.	72 ROWLAND ROAD					
	CRANBURY, NJ 06512				j.	
iver	FIORENTINO Truck	# 1565			٠.	
Customer	ECO-TRON NEW JERSEY, INC.		•		•	
nerator	U.S. ARMY, FORT MONMOUTH	1.425				
enerator Site	CHARLES WOOD AREA FORT MONMOUTH, NJ. 08057				·	
Centact 1	TAHER GINWALA	609-89	3-7873	1		
ntact 2						
JOTES 1:	L	laute seasonists		J		
HES 2:		A7-25-0-4-0-0-5-10-0-2-150				

94 Pyles Lane New Castel, DE. 19720 Tele#(302) 427-6633/800-30EARTH Fax#(302) 427-6634

NOM-DAZARDOUS MATER	
#*	K NUMBER
APPROVAL #980139 M/	ANIFEST # 003
	NC TICKET #39904
GENERATOR'S NAME & ADDRESS	Site Address
SARMY FORT MONMOUTH	SAME SITE ID #NJ2210020978
DIRECTORATE OF PUBLIC WORKS BLD. 173 SELF	A- CHARLES WOOD AREA
FORT MONMOUTH, NJ 07703 PW-BV	SAME
ENERATOR'S PHONE #:732-532-6223	Est. Quanity: 2 2
DESCRIPTION OF MATERIAL:	
"ON DOT REGULATED/RCRA NON-HAZARDOUS PETRO	OLEUM HYDROCARBON CONT.MATERIAL
contaminated by PCB as defined by 40 CFR part 761. Additional described in the application for treatment provided to Clean fair imber listed above. It is property classified and packaged equilations.	th of New Castle, how which resulted in the approval
ame: Tosoph M. Falbn	Title Covernmental Scientist
in sture Joseph M. Follon	Date: 4/3/98
RANSPORTER	
Company RUT TRANSPORT	Phone #
	78860 to 12:42 PM 06/03/3
ddress: 72 ROW, AND RD., CRANBURY, NJ. 08512	Gross Weight:
DE SW HAULERS PERMIT#813	Tare Weight: 26020 16 12:59 PM 06/03/9
Irwer: Keun Markay	Net Weight: 26,32
(TYPE OR PRINT CLEARLY)	
I hereby certify the above described materials were picked up a cident and will be delivered without tampering of any kind:	t the above described generator address without
Driver Signature 2 hope has	Dete: 6/3/98
IESTINATION	
I hereby certify that the above described materials was delivere 'ane, New Castle, Delaware // /	7/210Z
Niver Signature	Date: 4 Jao
Thereby certify that the above described material has been accept ane, New Castle, Delaware.	pted at Clean Earth of New Castle, Inc. at 94 Pyles  Date: 6 3-98

94 Pyles Lane New Castle, DE 19720 (302) 427-6633 INCOMING LOAD TICKET

\*Drums

Approval • 360139

ype of Material	<u>Gross</u>	Tare	Net Tons
NON PCB MINERAL OIL	78,660	26,020	26.32

				$A \setminus C$	1111	1
WM ID#	518 JANET W. ELLIOTT	Sig	nature 42	F. (1) . C	SKAN	
!! of Lading#						
Manifest#	003		. •			
IST. Manifest#		rige.				
ans. ID#	157					
Transporter	R.J. I. TRANSPORT		DE-SW Permit	# 813		····
ans. Addr.	72 ROWLAND ROAD CRANBURY, NJ 08512					
					•	
river	MARKEY	uck # 2		* *		
rustomer	ECO-TRON NEW JERSEY, INC.					
enerator	U.S. ARMY, FORT MONMOUTH		,			
Benerator Site	CHARLES WOOD AREA FORT MONMOUTH, NJ. 08057	:				
						•
Contact-1	TAHER GINWALA	609-89	3-7873			
intact 2						
NOTES 1:			-		-	•
OTES 2:						

How 10.40 BM

CLEAN EARTH OF NEW CASTLE, INC. 94 Pyles Lane New Castel, DE. 19720 Tele#(302) 427-6633/800-30EARTH Fax#(302) 427-6634

NON-HAZARDOUS MATE	RIALS MANIFEST
TRUE OR PRINT CLEARLY)	CK HUMBER / / -
APPROVAL # <u>980139</u> MA	ANIFEST # 004
CE	NC TICKET #39905
GENERATOR'S NAME & ADDRESS:	Site Address
SARMY FORT MONMOUTH	SAME SITE ID #NJ2210020978
DIRECTORATE OF PUBLIC WORKS BLD. 173 SELF	
CORT MONMOUTH, NJ. 07703 PW-€V	SAME
IENERATOR'S PHONE #:732-532-6223	Est. Quanity: 2 2
DESCRIPTION OF MATERIAL:	
ION DOT REGULATED/RCRA NON-HAZARDOUS PETR	
hereby certify that the above described materials is not a haza	rdous waste as defined by 40 CFR Part 261 nor is it
contaminated by FCB as defined by 40 CFR part 761. Additional described in the application for treatment provided to Clean Ear	ally It is the same material which was analyzed and thiof New Castle - bo which resulted in the approval
umber listed above. It is property classified and packaged	for transportation in accordance with applicable
regulations:	A Comment of the comm
ame Slasaph M. Fallon	Title: Convergmente Decentest
10m -101-	1/2/20
ature: Specifill. falls	Date: 0/3/48
RANSPORTER	
■ 14.1. A 2. A	PM 3-3-3-122
Company RUT TRANSPORT	Phone #
Address: 72 ROWLAND RD., CRANBURY, NJ 08512	Gross Weight: 76480 lb 12:48 PM 06/03/9
DE SW HAULERS PERMIT#813	I all C Melalic
TYPE OR PRINT CLEARLY)	Net Weight: & 0.53
I hereby certify the above described praterials were picked up a	
i oldent and will be delivered without tampering of any kind.	A the store described generator address without
	1/5/21
Driver Signature	Date 6/5/8
JESTINATION	
I hereby certify that the above described materials was delivere	d to Clean Earth of New Castle, ho, at 94 Pules
ane, New Castle, Delaware	15/01
itiver Signature:	April 0/5/16
Lane, New Castle, Delamare.	
sutherized Signature XXXIII Tolk I -	Date: 6-3-95

ARRIVETOB 7,00 CLEAN EARTH OF NEW CASTLE, INC.

94 Pyles Lane New Castel, DE. 19720 Tele#(302) 427-6633/800-30EARTH Fax#(302) 427-6634

NON-HAZARDOUS MATE	RIALS MANIFEST A //
	CK NUMBER 04
_APPROVAL # <u>980139</u> M/	ANIFEST # 605
Cf	NC TICKET # 39906
GENERATOR'S NAME & ADDRESS	Site Address
'S ARMY FORT NONMOUTH	SAME SITE ID #NJ2210020978
DIRECTORATE OF PUBLIC WORKS BLD. 179 SELF	4- CHARLES WOOD AREA
FORT MONMOUTH NJ 07703 PU-EN	SAME
ENERATOR'S PHONE #:732-532-6223	Est. Quanity: 2 2
DESCRIPTION OF MATERIAL: "YOU DOT REGULATED/RORA NON-HAZARDOUS PETR	
hereby certify that the above described materials is not a haz	
contaminated by PCB as defined by 40 CFR part 761. Addition	
described in the application for treatment provided to Clean Ear umber listed above. It is property classified and packaged	thor hew Castle, ho, which resulted in the approval
agulations.	
ame: Josaph M. Fallun	Title: Churconnatal Scientist
Signature: Spooph M. Follow	Date: 6/3/98
TRANSPORTER	
Company RJT TRANSPORT	Phone #
ddress: 72 ROWLAND RD., CRANBURY, NJ 08512	Gross Weight: 75820 in 12:56 PM 06/09 to
DE SW HAULERS PERMIT#813	Tare Weight: 26690 15 01 23 PM 06/03/9
'river' 720	Net Weight: 24,57
(TYPE OR PRINT CLEARLY)	
I hereby certify the above described materials were picked up a	t the above described generator address without
icident and will be delivered without tampering of any kind.	
Driver Signature: De Partie	Date: 6-3-96
PESTINATION	- 첫 No. N. 유럽지는 기급 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 -
I hereby certify that the above described materials was delivere I and New Castle, Delaware	d to Clean Earth of New Castle, Inc. at 94 Pyles
river Signature()	✓ Date
Thereby certify that the above described material has been access	A The state of the
of the Mew Castle, Delaward Withorized Signature:	Date: 6-3-9 #

94 Pyles Lane New Castle, DE 19720 (302) 427-6633 INCOMING LOAD TICKET

ite 673798
Time 12:46.PM
-- icket# 39906

Approval # 980139

rpe of Material	Gross	Tare	Met Tons	*Drums
NON PCB MINERAL OIL	75,820	26,680	24.57	

. *		•	4	V Q/	1.1
WM ID#	618 JANET W. ELLIOTT	Si	gnature Mand	W. St.	ulf
I of Lading#					
est#	905				
St. Manifest#					
rans. ID#	157				
Transporter	R.L. TRAISPORT		DE-SW Permit#	813	
ans. Addr.	72 ROWLAND ROAD				
	CRANBURY, NJ 08512				
\$** :					
"rtver ;	BATON Truck	k <sup>#</sup> 04			
Customer	ECO-TRON NEW JERSEY, INC.		•		
enerator	U.S. ARMY, FORT MONMOUTH				
Jenerator Site	CHARLES WOOD AREA				
	FORT MONMOUTH, NJ 08057	San Stress (S. 1507) (Astrolo		•	
Contact I	TAHER GINWALA	609-89	3-7873	-	
ontact 2					
NOTES 1:					
OTES 2:					

CLEAN EARTH OF NEW CASTLE, INC. 94 Pyles Lane New Castel, DE. 19720

Tele#(302) 427-6633/800-30EARTH Fax#(302) 427-6634

NON-HAZARDOUS MATERIALS MANIFEST TYPE OR PRINT CLEARLY) TRUCK NUMBER MANIFEST # 4PPROVAL #980139 Site Address GENERATOR'S NAME & ADDRESS: SAME SITE ID #NJ22140020978 IS ARMY FORT MONMOUTH DIRECTORATE OF PUBLIC WORKS BLD. 173 SELEM - CHARLES WOOD AREA ORT MONMOUTH NJ 07703 ENERATOR'S PHONE #:732-532-6223 Est. Quanity: DESCRIPTION OF MATERIAL NON DOT REGULATED/RCRA NON-HAZARDOUS PETROLEUM HYDROCARBON CONT.MATERIAL hereby certify that the above described materials is not a hazardous waste as defined by 40 CFR Part 261 nor is it contaminated by PCB as defined by 40 CFR part 781. Additionally It is the same material which was analyzed and described in the application for treatment provided to Clean Earth of New Castle, he, which resulted in the approval. umber listed above. It is property classified and packaged for transportation in accordance with applicable equiations. **TRANSPORTER** Company RUT TRANSPORT Phone # 65980 16 01:03 PM 06/03/98 Gross Weight: Address: 72 ROWLAND RD., CRANBURY, NJ 08512 06/03/93 25860 16 01·29 PM Tare Weight: DE SW HAULERS PERMIT#813 Net Weight: I hereby certify the above described materials were picked up at the above described generator address without neident and will be delivered without tampering of any kind. priver Signature: willie S DESTINATION Il hereby certify that the above described materials was delivered to Clean Earth of New Castle, Inc. at 94 Pules lane, New Castle, Delaware. Date: 6-5 Priver Signature Date Date Date of Strate of S w Castle, Inc. at 94 Pules Lane, Mew Castle, Delamare. Authorized Signature:

94 Pyles Lane New Castle, DE 19720 (302) 427-6633 INCOMING LOAD TICKET

Int Lating#   est #   206     St. Manifest #		•		C 61 14
est* 006 St. Manifest*  Tans. ID* 157 Fransporter K.I.I. TRANSPORT DE-SW Permit* 813  ans. Addr. 72 ROWLAND ROAD CRANBURY, NJ. 08512  Tiver SRIKES Truck* 1  Customer ECO-TRON NEW JERSEY, INC. Herator U.S. ARMY, FORT MONMOUTH Jenerator Site CHARLES WOOD AREA FORT MONMOUTH, NJ. 08057  Contact 1 TAHER GINWALA 609-893-7873	WM ID#	618 JANET W. ELLIOTT	Signature fills	J. Clark
St. Manifest*  cans. ID* 1.57  Iransporter				54
rans. ID* 157  Iransporter K.J.I. TKANSPOKT DE-SW Permit* 813  aris. Addr. 72 ROWLAND ROAD DRAMBURY, N.J. 08512  river SRIKES Truck * 1  Customer ECO-TRON NEW JERSEY, INC. Herator J.S. ARMY, FORT MONMOUTH Jenerator Site CHARLES WOOD AREA FORT MONMOUTH, N.J. 08057  Contact 1 TAHER BIRWALA 609-893-7873  INTact 2	est#	006		i .
rans. ID* 157  Transporter R.J.I. TRANSPORT  ans. Addr. 72 ROWLAND ROAD  CRANBURY, NJ. 08512  Tiver SRIKES Truck * 1  Customer ECO-TRON NEW JERSEY, INC.  Inerator J.S. ARMY, FORT MONIMOUTH  Jenerator Site CHARLES WOOD AREA FORT MONIMOUTH, NJ. 08057  Contact 1 TAHER GRIVWALA 609-893-7873  INTact 2  MOTES 1:	St. Manifest#		٤	
ransporter R.J. I RANSPORT DE-SW Permit* 813  aris. Addr. 72 ROWL AND ROAD CRANBURY, N.J. 08512  river SRIKES Truck * 1  Customer ECO-TRON NEW JERSEY, INC. enerator U.S. ARMY, FORT MONMOUTH penerator Site CHARLES WOOD AREA FORT MONMOUTH, N.J. 08057  Contact 1 TAHER GRIWALA 609-893-7873  intact 2  AOTES 1:	rans ID#	1157	1	
craneury NJ 08512  river SPIKES Truck * 1  Customer ECO-TRON NEW JERSEY, INC. merator U.S. ARMY, FORT MONMOUTH penerator Site CHARLES WOOD AREA FORT MONMOUTH, NJ 08057  Contact 1 TAHER BINWALA 609-893-7873  intact 2  AOTES 1:			DE-SW Permit	813
Customer ECO-TRON NEW JERSEY, INC. PREPARED U.S. ARMY, FORT MONIMOUTH PREPARED CHARLES WOOD AREA FORT MONIMOUTH, NJ 08057  Contact 1 TAHER GRWALA 609-893-7873  Intact 2  MOTES 1:	aris. Addr.	72 ROYLAND ROAD		
Customer ECO-TRON NEW JERSEY, INC.  enerator U.S. ARMY, FORT MONIMOUTH penerator Site CHARLES WOOD AREA FORT MONIMOUTH, NJ 08057  Contact 1 TAHER BINWALA 609-893-7873  intact 2  AOTES 1:		CRANBURY, NJ 08512		
Customer ECO-TRON NEW JERSEY, INC.  enerator U.S. ARMY, FORT MONIMOUTH penerator Site CHARLES WOOD AREA FORT MONIMOUTH, NJ 08057  Contact 1 TAHER BINWALA 609-893-7873  intact 2  AOTES 1:				
enerator U.S. ARMY, FORT MONIMOUTH penerator Site CHARLES WOOD AREA FORT MONIMOUTH, NJ 08057  Contact 1 TAHER GRIWALA 609-893-7873  Intact 2  AOTES 1:	river	SPIKES Truck	*	
Contact 1 TAHER GINWALA 609-893-7873  AOTES 1:	Customer	ECO-TRON NEW JERSEY, INC.		
FORT MONMOUTH, NJ 08057  Contact 1 TAHER GINWALA 609-893-7873  INTACT 2  AOTES 1:	enerator	U.S. ARMY, FORT MONMOUTH		
Contact 1 TAHER GIWALA 609-893-7873 INTES 1:	penerator Site	CHARLES WOOD AREA		•
intact 2	(	FORT MONMOUTH, NJ 08057		•
intact 2				
AÖTES 1:	Contact 1	TAHER GINWALA	609-893-7873	
	intact 2			
OTES 2:	AOTES 1:			
	OTES 2:			

CLEAN EARTH OF NEW CASTLE, INC. 94 Pyles Lane New Castel, DE. 19720 Tele#(302) 427-6633/800-30EARTH Fax#(302) 427-6634

NON-HAZARDOUS MATER	KIALS MANIFEST 3/
	ANIFEST # (4)
	NC TICKET # 399 19
그는 하시다. 하는 사람들은 사람들은 그는 하는 그 살아 보는 사람들이 되었다. 그는 사람들이 없는 것이 없는 것이다.	Site Address
GENERATOR'S NAME & ADDRESS	SAME SITE ID #NJ2210020978
	-CHARLES WOOD AREA
FORT MONMOUTH, NJ 07703 PW-EV	SAME
ENERATOR'S PHONE #:732-532-6223	Est. Quanity: 2 2
DESCRIPTION OF MATERIAL	
NON DOT REGULATED/RCRA NON-HAZARDOUS PETRO	LEUM HYDROCARBON CONT.MATERIAL
hereby certify that the above described materials is not a haza optaminated by PCB as defined by 40 CFR part 761. Additional described in the application for treatment provided to Clean Early	rdous waste as defined by 40 CFR Part 261 nor is it. Illy it is the same material which was analyzed and
umber listed above. It is property classified and packaged equiations	for transportation in accordance with applicable
Name: Joseph M. Falbo	Title: (mulynmental Scientis)
ignature geogram. Follon	Date: 0/3/98/
RANSPORTER	
ompany <u>RJTTRANSPORT</u>	Phone #
vddress: 72 ROWLAND RD., CRANBURY, NJ. 08512	Gross Weight: 85000 15 06:44 87 0620
DE SW HAULERS PERMIT#B13	_ Gross Weight:85000_16_06144_AM0670 Tare Weight:34780_16_07108_AM06704738
Driver SCOTT GAYARADO	Net Weight: 25.7
(TYPE OR PRINCILEARLY)	Net weight: A CATT
I hereby certify the above described materials were picked up a	t the alrive described generator address without
noident and will be delivered without tampering of any kind.	1-100
Priver Signature: DOW JMHO	Date: 6/3/78
DESTINATION	
hereby certify that the above described materials was delivere	d to Clean Earth of New Castle, hc. at 94 Pyles
Lane, New Castle, Delaware 1	DMC 6/4/98

Nereby certify that the above described material has been accepted at Clean Earth of New Castle, Inc. at 94 Pyles

Lare, New Castle, Delaware authorized Signature:

94 Pyles Lane New Castle, DE 19720 (302) 427-6633 INCOMING LOAD TICKET

Time 628 AM 39919

Approval # 980139

ype of Material	<u>Gro55</u>	Tare	Met Tons	*Drums
NON PCB MINERAL OIL	85,000	34,780	25.11	

7					4 1 0 1	11 5.4
MM ID#	48 JOSH LEON ARD		Signati.	ry Takan	TW CL	LI
Lading#				0		
fest#	007		• 1			
t. Manifest#			بخ			
;rans. ID#	157					
Transporter	R.J.T. TRANSPORT		DE	-SW Permit	# 813	
ans: Addr.	72 ROWLAND ROAD					
	CRANBURY, NJ 08512					\$ 2
river	GARGANO	Truck *	31			
in ustomer	ECO-TRON NEW JERSEY,	INC.	1			
enerator	U.S. ARMY, FORT MONMO	UTH		•		
Generator Site	CHARLES WOOD AREA FORT MONMOUTH, NJ. 01	8057				
Contact 1	TAHER GINWALA	60	09-893-78	373		
ontact 2						
NOTES 1:						
OTES 2						

CLEAN EARTH OF NEW CASTLE, INC. 94 Pyles Lane New Castel, DE. 19720 Tele#(302) 427-6633/800-30EARTH Fax#(302) 427-6634

NON-HAZARDOUS MATERIALS MANIFEST

TRUE OR PRINT CLEARLY)	CK NUMBER 2004
APPROVAL #980139 M/	ANIFEST POOP
- CE	NC TICKET #3990
GENERATOR'S NAME & ADDRESS:	Site Address
A'S ARMY FORT MONMOUTH	SAME SITE ID #NJ2210020978
RECTORATE OF PUBLIC WORKS BLD. 173 SELF	CHARLES WOOD AREA
FORT MONMOUTH NJ 07703 PW-E	SAME
"ENERATOR'S PHONE #:792-532-6223	Est. Quanity: 2 2
ESCRIPTION OF MATERIAL:	
NON DOT REGULATED/RCRA NON-HAZARDOUS PETR	CLEUM HYDROCARBON CONT MATERIAL
rereby certify that the above described materials is not a haza	
intarninated by PCB as defined by 40 CFR part 761. Addition	ally it is the same material which was analyzed and
described in the application for treatment provided to Clean Ear - imber listed above. It is property classified and packaged	th of New Castle, he: which resulted in the approval
igulations.	The reservoir ation in accordance with applicable
	00
Name: 405000 M. Fallin	Title: ( My 10 ments Accorded
mature: Spach M. 7500m	Date: 12/08/
	0/5/76
TRANSPORTER	
ompanyRUTTRANSPORT	Phone #
	86D40 15 06:53 RM 06/04/5
ddress 72 ROWLAND RD, CRANBURY, NJ 08512	in the second of
JE SW HAULERS PERMITAELS	Tare Weight: 29360 10 67+18 AM 06/04/9
TIMER WIN A GOLUMN	
CLASE OR PRINT CLEARLY)	Net Weight: Q 0 0 4
hereby certify the above described materials were picked up a	t the shows described commuter address tillbut
incident and will be delivered without tampering of any kind.	A day are days and days and
	Alala /
· iver Signature	Date (2) 5/5 3
ESTINATION	
ereby certify that the above described materials was delivered	den Bleen Forth of Nov. Cartle ha at GA Dube
sane, New Castle, Oppayare	/1.6/
Tyer Signature: A P	Detre: O/Y/X
ereby certify that the above described material has been accep	ited at Clean Earth of New Castle, Inc. at 94 Pyles
are, New Castle, Delaware.  Authorized Signature:	Date: 6-4-98
The same of the sa	tura (sa)

94 Pyles Lane New Castle, DE 19720 (302) 427-6633 INCOMING LOAD TICKET

ite 6/4/98 Time 6.41 AM 39920

Approval \* 980139

rpe of Material	Gross	Tare	Net Tons	*Drums
NON PCB MINERAL OIL	86,040	29,960	28.04	

4			<u>\</u>	611 816 3	rt.
WHID#	61.6 JANET W. ELLIOTT	Sig	nature Ar And	W. Celul	
of Lading#			- 6		
)st#	008	•			
St. Manifest*		٠			
ans, ID#	157				
ransporter	RESET TRANSPORT		DE-SW Permit	# 813	
ans. Addr.	72 ROWLAND ROAD				
<del></del>	CRANBURY, NJ 08512			· ·	
7					
iver	BOEKHOUT Tru	ck <b>*</b> 398			
Customer	ECO-TRON NEW JERSEY, INC.				
enerator	U.S. ARMY, FORT MONMOUTH				
enerator Site	CHARLES WOOD AREA		1	•	
<del></del>	FORT MONMOUTH, NJ 08057				
Contact 1	TAHER BINWALA	609-89	2-7873	ē.	
ntact 2					
JOTES 1:				•	÷
ITES Z:					

CLEAN EARTH OF NEW CASTLE, INC. 94 Pyles Lane New Castel, DE. 19720 Tele#(302) 427-6633/800-30EARTH Fax#(302) 427-6634

, NON-HAZARDOUS MATER	IIALS MANIFEST
A P A A THE COURSE A SECULAR AND ADDRESS OF THE PARTY OF	K NUMBER
APPROVAL #980139 MA	ANIFEST # 069
	NC TICKET #39938
GENERATOR'S NAME & ADDRESS	Site Address
IS ARMY FORT MONMOUTH	SAME SITE ID #NJ2210020978
MRECT OP ATE OF PUBLIC WORKS BLD 173 SELFM	CHARLES WOOD AREA
FORT MONMOUTH NJ 07703	SAME
SENERATOR'S PHONE #:792-532-6223	Est. Quanity: 2 2
DESCRIPTION OF MATERIAL:	
YON DOT REGULATED/RCRA NON-HAZARDOUS-PETRO	LEUM HYDROCARBON CONT.MATERIAL
hereby certify that the above described materials is not a haza	
pontaminated by PCB as defined by 40 CFR part 761. Additional	By it is the same material which was analyzed and
described in the application for treatment provided to Clean Earl number listed above. It is property classified and packaged	
egulations	
jame: Joe Fallon	Title: Chusionmente Guentest
CALL THE STATE OF	Title: Create for Flow
Signature: Al Fallon	Date: 6/4/98
TRANSPORTED TAT HOW NOW	
Company RdTTRANSPORT	Phone #
Vidress 72 ROWLAND RD, CRANBURY NJ 08512	Gross Weight: 91300 lb 10:00 AM 06/04/9
DE SW HAULERS PERMIT#813)	Tare Weight: 26160 16 10:11 8M 06/04/5
Iriver: Voir Kamon Karama-	Net Weight: 32.57
(TYPE OR PRINT CLEARLY)	_ Net west in
I hereby certify the above described materials were picked up a	the above described generator address without
acident and will be delivered without tampering of any kind.	
100/1/10	4.7.7.48
Driver Signature	Date
DESTINATION	
Thereby certify that the above described materials was delivered	to Clean Earth of New Castle, ho, at 94 Pules
lane, New Costle, Delayare, (1)	
river Signature: Von	XDate: 6-11-92
hereby certify that the above described material has been accep	ted at Clean Earth of New Castle, Inc. at 94 Pyles

Lane, New Castle, Delaware.

94 Pyles Lane New Castle, DE 19720 (302) 427-6633 INCOMING LOAD TICKET

te 6/4/98
Time 9.53 AM
cket# 39938

approval • 980139

| tpe of Material | Gross | Tare | Met Tons | Drums | ON PCB MINERAL OIL | 91,300 | 26,160 | 32.57

·· •		
₩M ID#	618 JUANET W. ELLIOTT	Signature (KILL)
of Lading#		
st#	009	
St. Manifest#		
ans. ID#	32	
ransporter	HAB NAB TRUCKING, INC.	DE-SW Permit# 070
ans. Addr.	P.O.BOX 420	
¥ .	1129A BRICKY ARD ROAD SEAFORD, DE 19973	
iver	RCSARIO Truck	* <u>117</u>
Customer	ECO-TRON NEW JERSEY, INC.	
nerator	U.S. ARMY, FORT MONMOUTH	
jenerator Site	CHARLES WOOD AREA FORT MONMOUTH, NJ. 08057	
Contact 1	TAHER GINWALA	609-893-7873
ntact 2		
JOTES 1:		
STES 1:		

CLEAN EARTH OF NEW CASTLE, INC. 94 Pyles Lane New Castel, DE. 19720 Tele#(302) 427-6633/800-30EARTH Fax#(302) 427-6634

NON-HAZARDOUS MAT	TERIALS MANIFEST ノムク
	RUCK NUMBER PS
APPROVAL #980139	MANIFEST # 6/6
	CENC TICKET-# 399 46
GENERATOR'S NAME & ADDRESS	Site Address
IS ARMY FORT MONMOUTH	SAME SITE ID #NJ2210020978
DIRECTORATE OF PUBLIC WORKS BLD. 173 SEL	
CORT. MONMOUTH, NJ. 07703	SAME
- SENERATOR'S PHONE #:732-532-6223	Est. Quanity: 2 2
DESCRIPTION OF MATERIAL:	
"ION DOT REGULATED/RCRA NON-HAZARDOUS PE	
hereby certify that the above described materials is not a hontaminated by PCB as defined by 40 CFR part 761. Additional described in the application for treatment provided to Clean Eumber listed above. It is property classified and packagulations.	lonally it is the same material which was analyzed and tarth of New Castle, ho, which resulted in the approval ged for transportation in accordance with applicable
iame: Jac Fallon	Title: awaynmental feartest
Signature: W. F. U.M.	Date: 6/4/98
TRANSPORTER TAT	
Company RUTTERANSPUR POR OC	Phone #
Address: Fa ROWVAND RD. GRANBURY NJ DESTE	Gross Weight: 73600 19 11:14 AM 06/04/9
DE SW HAUKERS PROMITOR DI 3 /	Tare Weight: 27060 16 11-98 AM 06/04/96
Silver: 1/Matthe Jawan	Net Weight 23.27
1/1 AGABBARKIT CLEARLY)	
I hereby certify the above described materials described uncident and will be delivered with full tamper in an any kind.	하면 되었다. 말하네네. 어느 그 그 그 그 때문에 살아 나는 것이 되었다.
Driver Signature	Date: 6-9-98
DESTINATION AND AND AND AND AND AND AND AND AND AN	
hereby certify that the above restribed thaterials was delived the lew Castle, belaying a first the second of the	red to Clean Earth of New Castle, Inc. at 94 Pyles
river Signature	X Date 2 4 90
hereby certify that the above described material has been ac	ceited at Cean Earth of New Castle, Inc. at 94 Pules
Lane, New Castle, Delaware.	6-4-98
	The state of the s

94 Pyles Lane New Castle, DE 19720 (302) 427-6633 INCOMING LOAD TICKET

ite 6/4/98 Time 11:05 AM oket# 39946

Approval \* 980139

pe of Material	Gross.	Tare	Net Tons	*Drums
NON PCB MINERAL OIL	73,600	27,060	23.27	

		A = A + A + A + A + A + A + A + A + A +	11. 44.
ÿM ID#	518 JANET W. ELLIOTT	Signature (ACC)	ttul
I of Lading#			
)st#	010		
St. rianifest#			
rans. 10#	119		
ransporter	TAT TRUCKING, INC.	DE-SW Permit# 077	
ans. Addr.	3482 WRANGLE HILL ROAD		
	BEAR, DE 19701		
iver	HOWLAND Truck #	403	
Customer	ECO-TRON NEW JERSEY, INC.	·	
nerator	U.S. ARMY, FORT MONMOUTH		
jenerator Site	CHARLES WOOD AREA FORT MONMOUTH, NJ. 08057		
,			
Contact 1	TAHER GINWALA	609-893-7873	
ntact 2			
NOTES 1:			
OTES 2:			

CLEAN EARTH OF NEW CASTLE, INC. 94 Pyles Lane New Castel, DE. 19720 Tele#(302) 427-6633/800-30EARTH Fax#(302) 427-6634

	S MATERIALS MANIFEST
APPROVAL #980139	MANIFEST # 0//
-4LLIOANE #300133	· · · · · · · · · · · · · · · · · · ·
	CENC TICKET # 39947
GENERATOR'S NAME & ADDRESS	Site Address
NECTORATE OF BURNEY WORKS BLD. 173	SELFM CHARLES WOOD AREA
DIRECT ORATE OF PUBLIC WORKS BLD. 173 PORT MONMOUTH, NJ 07703	PW-EY SAME
- JENERATOR'S PHONE #:732-532-6223	
DESCRIPTION OF MATERIAL	
	OUS PETROLEUM HYDROCARBON CONT. MATERIAL
	s not a hazardous waste as defined by 40 CFR Part 261 nor is it
contaminated by PCB as defined by 40 CFR part 761	Additionally it is the same material which was analyzed and
	o Clean Earth of New Castle, ho, which resulted in the approval d packaged for transportation in accordance with applicable
. egulations	$\alpha$ . $\iota$
larne Itoo Fallon	Title: Oweronmental perante
	1 labo
Signature	Date: 6/4/90
[RANSPORTER	elking
Company EJETRANS PURT BEACO	Phone #
Was a series of the series of	
Address: 72 ROWLAND RU, CRANBURY, NJ	19512 Gross Weight: 62280 15 17-23 AM 06/04/9
DE SW HAULERS PERMIZMETS 377	Tare Weight: 30840 15 11445 81 06/04/9
Driver: James Lotte	Net Weight: 2 5. 72
(TYPE OR PRINT CLEARLY)	
I hereby certify the above described materials were notions and will be delivered without tampering of a	picked up at the above described generator address without ing kind
Oriver Signature: 54mes KOLLER	Date: 6-4-98
DESTINATION	
lane, New Castle Delayare.	as delivered to Clean Earth of New Castle, Inc. at 94 Pyles
river signature 1000 House described potential has	Date: 4-4-4 sheen accepted at Clean Earth of New Castle, Inc. at 94 Pyles
Lane, New Castle, Delaware	Date: 6-4-98

94 Pyles Lane New Castle, DE 19720 (302) 427-6633 INCOMING LOAD TICKET

ute 6/4/98
Time 11:05 AM
approval • 980139

pe of Material	Gross	Tare	Net Tons	*Drums
NON PCB MINERAL OFL	73,600	27,060	23.27	

			(1)	11 / A
WM ID#	518 JANET W. ELLIOTT	[5	signatur Will ()	that
I of Lading#				
)st#	010	•		
Št., jánifest#		٠.		
rans ID#	19			
iransporter	TAT TRUCKING, INC.		DE-SW Permit# 077	<del></del>
ans. Addr.	3482 WRANGLE HILL ROAD			
ਭ	BEAR, DE 19701			
iver	HOYLAND True	sk <b>#  </b> 403		•
1701	Director	- 1003		
Customer	ECO-TRON NEW JERSEY, INC.		-	
enerator	U.S. ARMY, FORT MONMOUTH			
jenerator Site	CHARLES WOOD AREA			
	FORT MONMOUTH, NJ 08057			•
,				
Contact 1	TAHER GINVALA	609-8	93-7873	
ntact 2				
NOTES 1:				
	<u> Доментичности передоличностичности</u>			
OTES 2:				

NON-HAZARDOU	S MATERIALS MANIFEST
(TYPE OR PRINT CLEARLY)	TRUCK NUMBER
APPROVAL #980139	MANIFEST # 0/1
	CENC TICKET # 39947
GENERATOR'S NAME & ADDRESS	Site Address
IS ARMY FORT MONMOUTH	SAME SITE ID #NJ2210020978
DIRECTORATE OF PUBLIC WORKS BLD. 173	SELFM CHARLES WOOD AREA
PORT MONMOUTH, NJ 07703	PU-EY SAME
- <b>SENERATOR'S PHONE #:</b> <u>732-532-6223</u>	Est Quanty: 2 2
DESCRIPTION OF MATERIAL:	
	OUS PETROLEUM HYDROCARBON CONT. MATERIAL
	s not a hazardous waste as defined by 40 CFR Part 261 nor is it
contaminated by PCB as defined by 40 CFR part (b) described in the application for treatment provided to	Additionally it is the same material which was analyzed and o Clean Earth of New Castle, ho, which resulted in the approval
	d packaged for transportation in accordance with applicable
egulations.	$\sim$ $\sim$ $\sim$ $\sim$ $\sim$
lame: Stop Faller	Title: Chocomparts peranted
Signature: W. Fallm	Date: 6/4/98
1 /TH-T-TOW	elking
TRANSPORTER 2 X	
Company to real RANS PURI PT	C Phone #
	82280 1b 11:23 AN 06/04/3
Address 72 NOWLAND RD., CRANBURY, NJ	US512 Gross Weight:
DE SW HAULERS PERMITTED STOP	Tare Weight: 30840 16 11745 AM 06/04/S
Irwer Jamo dotter	Net Weight: 2 5, 72
J (TYPE OR PRINT CLEARLY)	
I hereby certify the above described materials were neldent and will be delivered without tampering of a	picked up at the above described generator address without my kind.
Driver Signature 5 Ames hollER	Date: 6-4-98
DESTINATION	
	as delivered to Clean Earth of New Castle, hc. at 94 Pyles
ane, New Castle, Delaware.	VDate: 6-4-98
thereby certify that the above described material has	s been accepted at Clean Earth of New Castle, Inc. at 94 Pyles
Lane, New Castle, Delayare ( 1/ / #	1-11-00
Luthardrad Complying Med III CV Late	Date: 6 7 7

## CLEAN EARTH OF NEW CASTLE, INC. 94 Pyles Lane New Castle, DE 19720

itė	6/4/98		ti	(302) 42 <b>NCOMING</b> LO	7-6633 DAD TICKET
- √irne	11:13 AM	•			
_ = cket#	39947	1			
Approva	980139				
pe of	Material .	Gross	Tare	<b>Net Tons</b>	*Drums
MON PCB	MINERAL OIL	82,280	30,840	25.72	
					NO PERSONAL PROPERTY AND PROPERTY OF THE

		1 1 0/1 4
i <sup>#</sup> MTD#	618 JANET W. ELLIOTT Si	gnature Will W. Cliff
l of Lading#		
*est#	011	
anifest#		
ans: ID#	19	
ransporter	TAT TRUCKING, INC.	DE-SW Permit# 077
ans. Addr.	3482 WRANGLE HILL ROAD	
÷ .	SEAR, DE 19701	
i iver	LOLLER Truck # 400	
ਰੰ <b>ustomer</b>	ECO-TRON NEW JERSEY, INC.	•
nerator	U.S. ARMY, FORT MONMOUTH	
enerator Site	CHARLES WOOD AREA FORT MONMOUTH, NJ 08057	
≾ontact 1	TAHER GINWALA 609-89	3-7873
ntact 2		
ØTC5 1:		
ITES 2:		

NON-HAZARDOUS MA	
	TRUCK NUMBER 6260
APPROVAL # <u>980139</u>	MANIFEST # 0/2
	CENC TICKET-#39956
GENERATOR'S NAME & ADDRESS	Site Address
IS ARMY FORT MONMOUTH	SAME SITE ID #NJ2210020978
	FM-GHARLES WOOD AREA
FORT MONMOUTH, NJ 07703 (W-1	
#NERATOR'S, PHONE #:732-532-6223	Est. Quanity: 2 2
DESCRIPTION OF MATERIAL:	
'ION DOT REGULATED/RCRA NON-HAZARDOUS PE	
hereby certify that the above described materials is not a contaminated by PCB as defined by 40 CFR part 761. Additionally 10 per 10 pe	
described in the application for treatment provided to Clean	Earth of New Castle, ho. which resulted in the approval
number listed above. It is property classified and pack	aged for transportation in accordance with applicable
. egulations.	A. 100 + +
tame: Sox Fallon	Title: (muly namental sciences
Signature: W Foun	Date: 6 4 98
A III I MAY.	
FRANSPORTER //TAD	
Company DJF-FRANSPORT H	Phone #
	81520 1b 11:48 AM 06/04/9
Address 72 ROM AND RD. CRANBURY NL 0551	
DE SW HAULERS PERMITHELS 0 70	lais negit.
Driver: William HAUES	Net Weight: 25,46
CTYPE OR PRINT CLEARY)	
I hereby certify the above described materials were picked notident and will be delivered without Simperipage Lany kink	
	1 11 00
Oriver Signature:	Date: 6-7-78
DESTINATION	
I hereby certify that the above described materials was deli-	vered to Clean Earth of New Castle, Inc. at 94 Pyles
lane, New Castle, Delaware	1 4 90
river Signature: Thereby certify that the above described material has been a	Date:
Lane, New Castle, Delaware.	
Authorized Signature: Janua Litt	Date: 6-4-98

### CLEAN EARTH OF NEW CASTLE, INC. 94 Pyles Lane

94 Pyles Lane
New Castle, DE 19720
(302) 427-6633

· ·	(002) 723 0000
Section 1	74/98 INCOMING LOAD TICKET
rime . T	1:39 AM
_cket# 3	9950
pproval *	980139
ann an Mal	Tarini Ta
pe of Mat	
ON PCB MINE	RAL OIL 81,520 30,600 25.46
*	
M ID#	\$18 JANET W. ELLIOTT Signature Phrasis Wash
l of Lading#	
st#	012
ot. ranifest#	
and the second second	32
ansporter	HAB NAB TRUCKING, INC. DE-SW Permit# 070
ans. Addi.	P.0.80X 420
	1129A BRICKY ARD ROAD
·	SEAFORD, DE 19973
iver	#AYES 6260
.ustomer	ECO-TRON NEW JERSEY, INC.
rerator	U.S. ARMY, FORT MONMOUTH
nerator Site	CHARLES WOOD AREA
, — — — — — — — — — — — — — — — — — — —	FORT MONMOUTH, NJ 08057
-	
entact 1	TAHER GINWALA 609-893-7873
ntact 2	
*	
STES 1:	
ITES 2:	

	MATERIALS MANIFEST 1297
YPE OR PRINT CLEARLY)	TRUCK NUMBER
APPRØVAL #980139	MANIFEST # 0/3
	CENC TICKET #39960
SENERATOR'S NAME & ADDRESS	Site Address
"SARMY FORT MONMOUTH	SAME SITE ID #NJ2210020978
	ELFM- CHARLES WOOD AREA
LOW! MONROOTH HANDLAND	
ENERATOR'S PHONE #:732-532-6223	Est, Quanity: 2 2
ESCRIPTION OF MATERIAL:  AON DOT REGULATED/RCRA NON-HAZARDOUS	DETROLEUM HYDROCARBON CONT MATERIAL
prehi partificities the above described materials is se	tha hazardous waste as defined by 40 CFR Part 261 nor is it
atamisated by PCB as defined by 40 CFR part 761. T	dufficially it is the same material which was analyzed and
described in the application for treatment provided to C	lean Earth of New Castle, he which resulted in the approval ackaged for transportation in accordance with applicable
quistions	(2) And Park - Table 2000 Community Communit
Hame Job Fallon 1	Title Meyerpagenta Scientist
grature Ste Follow	Date: 6/4/98
TRANSPORTER 1	
ompany PUT JPANSPORT LAS MA	4 TATPhone #
	學說 기업 학생 가입으로 많은 그 가장 가 먹었다. 그 가는 그는 그 가장 말한 음식적인 하고 그렇지 않는 목사실학 다시다. 그
deress: 72 ROWLAND RD CRANBURY, NJ. OF	新2 Gross Weight: 98380 15 好:48 附 %74/88
JE SW HAVLERS PERMIT#813 0 70	Tare Weight: 22 1/14
Kniver Keuli J 24 S/2	Net Weight
(TYPE OR PRINT CLEARLY)	
	ked up at the above described generator address without
roident and will be delivered without tampering of any	
river Signature	Date:
. OTHER TIME	
ESTINATION	delivered to Clean Earth of New Castle, ho. at 94 Pyles
cane, New Castle, Delayare	6-472
(Iver Signature Selfond	A Class Could be at 91 Bulbs
are New Castle, Delawage + D A H	een accepted at Clean Earth of New Castle, Inc. at 94 Pyles
Authorized Signature	Cate:

94 Pyles Lane New Castle, DE 19720 (302) 427-6633 INCOMING LOAD TICKET

ate 6/4/98
fime 1:40 PM
isket# 39960
Approval # 980139

ype of Raterial	Gro55	Tare	Net Tons	*Drums
HON PCB MINERAL OIL	98,380	31,500	33.44	

		A CA H
WM ID#	STB JANET W. ELLIOTT	Signature Will William
il of Lading#		<del></del>
est#	013	
डिर. √anifest#		ž.
rans. ID#	32	
Fansporter	HAB NAB TRUCKING, INC.	DE-SW Permit# 070
rans: Addr.	P.O.BOX 420 1129A BRICKY ARD ROAD SEAFORD, DE 19973	
² river	HASSLER Truck #	6393
Customer	ECO-TRON NEW JERSEY, INC.	
enerator	U.S. ARMY, FORT MONMOUTH	
enerator Site	CHARLES WOOD AREA FORT MONMOUTH, NJ. 08057	
	CRITICAL CONT. NO COSST	
Contact 1	TAHER GIMMALA	609-893-7873
ontact 2		
NOTES 1:		
710TES 2:		

94 Pyles Lane New Castel, DE. 19720 Tele#(302) 427-6633/800-30EARTH Fax#(302) 427-6634

NON-HAZARDOUS MA	HERIALS MANIFEST
S. t. tie, W. date, at the state of supplemental and the	TRUCK NUMBER 401
APPROVAL #980139	MANIFEST # 614
	CENC TICKET # 39969
GENERATOR'S NAME & ADDRESS	Site Address
"S ARMY FORT MONMOUTH	SAME SITE ID #NJ2210020978
IRECTORATE OF PUBLIC WORKS BLD. 173 SEL	FM- CHARLES WOOD AREA
VIII III VIII VIII VIII VIII VIII VIII	- BV SAME
ENERATOR'S PHONE #:732-532-6223	Est: Quanity: 2 2
DESCRIPTION OF MATERIAL:	
NON DOT REGULATED/BCRA NON-HAZARDOUS PI	
, hereby certify that the above described materials is not a ontaminated by PCB as defined by 40 CFR part 761/2. Additionally 100 CFR part 761/2.	
described in the application for treatment provided to Clean	
umber listed above. It is property classified and pack	aged for transportation in accordance with applicable
equiations	1 1 1 to
Name Jos Fallan	Title Christophique felous
ignature Ope Fallon	Title Convergemental Secontest
ignature 92 70 94	Lides 917119
RANSPORTER	
Jompany RJT TRAMSPORT TAT	Phone #
Bear DE	
ddress 72 ROWLAND RD. CRANBURY, NJ-0851	2 Gross Weight: 87140 15 03:33 PM (
DE SW HAULERS PERMIT#813	Tare Weight:
Driver: Wil charl Howland	Net Weight: 29880 15 03:44 PM
- (TYPE OR PRINT CLEARLY)	
hereby certify the above described materials were picked	
incident and will be delivered without tampering of any king	[월] 이 이 선생님은 살아 가장 하는 것이 하는 그 그가 되었다면 하는 그 모든 가장 그렇게
river Signature: Thehard & Hodian	Deta June 4/1998
DESTINATION	
hereby certify that the above described materials was deli-	vereg to Clean Earth of New Castle, ho. at 94 Pyles
river Signature	Date: 2/4/98
hereby certify that the above desprited material has been	
Star Carta Frankling	and the state of t

**Authorized Signature** 

94 Pyles Lane New Castle, DE 19720 (**3**02) 427-6633

ite 6	15/98 INCOMING LOAD TICKET
37.7	55 AM
Ticket# 35	9969
ipproval *	980139
Tipe of Mat	erial Gross Tare Net Tons *Drums
ON PCB-FIINE	RAL OIL 87,140 29,880 28.63
, /M ID#	S18 JANET W. ELLIOTT Signature Will (1)
"I of Lading#	
	014
ો. anifest#	
ans. ID#	19
ransporter	TAT. TRUCKING, INC. DE-SW Permit* 077
Trans. Addr.	3482 WRANGLE HILL ROAD
	BEAR, DE 19701
ÿ	
iver	HOWLAND Truck # 401
ustomer	ECO-TRON NEW JERSEY, INC.
	U.S. ARMY, FORT MONIMOUTH
nerator Site	CHARLES WOOD AREA
	FORT MONMOUTH, NJ 08057
ontact 1	TAHER GINWALA 609-893-7873
ntact 2	
otes 1:	
TES 2:	

NON-HAZARDOUS MATI	ERIALS MANIFEST / //V
그 불리하는 그 씨는 사이램은 사이램, 역사에서 사이를 보는 사람들이 되었다.	UCK HUMBER 700
APPROVAL #980139 M	ANIFEST # 0/5
Ċ	ENC TICKEF# 39976
GENERATOR'S NAME & ADDRESS	Site Address
SARMY FORT MONMOUTH	SAME SITE ID #NJ2210020978
DIRECTORATE OF PUBLIC WORKS BLD. 173 SELFA	
FORT MONMOUTH, NJ 07703 PN-E	
ENERATOR'S PHONE #:732-532-6223	Est. Quanity: 2 2
DESCRIPTION OF MATERIAL:	DOLEHIA HIYO DOCADDOM OOME MATEDIAL
ION DOT REGULATED/RCRA NON-HAZARDOUS PET	
contaminated by PCB as defined by 40 CFR part 761. Addition	
described in the application for treatment provided to Clean Ea	
umber listed above. It is property classified and package equiations	
	Title Charinmental Scientist
"ame: JAL TG [101]	little: Ortogram Ortogram
Fignature: MC + CUSY)	Date 6/4/48
RANSPORTER - TRUCKING	
- "你只能都是我们就是可能没有理论的。""你说,你没有一个人,不是不是什么。""一人,我们也是不是一个人。""你是一个人,我们也是一个人,我们也是一个人,我们	
iompany Ref Tables and BEAR, D.W.	Rhone #
vddress: 72 ROWLAND RD, CRANBURY, NJ 08512	6#080 1b_07:04 AM 06/05/9 Gross Weight:
DE SW HAULERS PERMIT#813	Tare Weight: 30500 16 07:30 AM 06/05/98
. Iriver:	Net Weight 26.79
(TYPEORPRINT CLEARLY)	No. Visit
I hereby certify the above described materials were picked up	at the above described generator address without
wident and will be delivered without tampering of any kind	
Driver Signature: La me La Clair	Date: 6-4-98
<b>JESTINATION</b>	
hereby certify that the shove described materials was deliver tane, New Castle, Delaware	
river Signature: Comes Faller	Deta 4-4-98
hereby certify that the above described material has been acc	
Lane, New Castle, Delaware	Tate 6-5-98

94 Pyles Lane New Castle, DE 19720 (302) 427-6633

\*Drums

6/5/98 INCOMING LOAD TICKET 6.58 AM me 39970 Finket# proval # 980139 pe of Material Grass Tare Net Tons

ON PCB MIN	ERAL OIL 84,080 3	0,500 . 26.79
		O Marilla
MID#	618 JANET W. ELLIOTT	Signature Will College
of Lading #	015	
iffest*		
ans. ID#	19 TAT TRUCKING, INC.	DE-SW Permit# 077
Trans. Addr.	3482 WRANGLE HILL ROAD	
= <del>;</del>	BEAR, DE 19701	
iver	LOLLER Truck	* 400
stomer	ECO-TRON NEW JERSEY, INC.	
nerator	U.S. ARMY, FORT MONMOUTH	
nerator Sit	e CHARLESWOOD AREA FORT MONMOUTH, NJ 08057	
intact 1	TAHER GINWALA	609-893-7873
mtact 2		
ग्रह्य ।:		
MOTES 2:	*-	

4

NON-HAZARDOUS	S MATERIALS MANIFEST
TYPE OR PRINT CLEARLY)	TRUCK NUMBER
APPROVAL #980139	MANIFEST # 0/6
	CENC TICKET # 39981
GENERATOR'S NAME & ADDRESS	Site Address
IS ARMY FORT MONMOUTH	SAME SITE ID #NJ2210020978
JIRECTORATE OF PUBLIC WORKS BLD. 173	CHARLES WOOD AREA
FORT MONMOUNH, NJ. 07/03	3 A M L
JENERATOR'S PHONE #:732-532-6223	Est. Quanity: 2 2
JESCRIPTION OF MATERIAL:	
	NIS PETROLEUM HYDROCARBON CONT.MATERIAL
hereby certify that the above described materials is	not a hazardous waste as defined by 40 CFR Part 261 nor is it
unitaminated by PCH as defined by 4U CFR part (b)	. Additionally it is the same material which was analyzed and Clean Earth of New Castle, how which resulted in the approval
	d packaged for transportation in accordance with applicable
equiations	$\sim 10^{\circ}$
Name Joe Fallon.	INIO Convergence to Scientist
6 7 11	·墨克尔·墨尔斯·马·塞莱马克·戈尔·艾尔·艾尔·马克·艾尔·马克·斯萨斯
ignature: At fallon	7 Date: 0/9/18
FRANSPORTER THE TREKING	DAM
Zumpany R LESS PANS PORT	Phone #
Address 72 ROWLAND RD., CRANBURY, NJ	06512 Gross Weight: 77560 16 08:12 AM 06/05/
一个人的现在分词 人名英格兰人姓氏格兰 化二氯甲基磺基酚 网络紫色的 医皮肤 化基层的 化二氯酸 化二二二氯 医二氯磺胺 化二氯甲基酚 化二氯甲基酚 医二氯甲基酚 医二氯甲基酚 化二氯甲基酚 化氯甲基酚 化二氯甲基酚 化二氯甲基酚 化氯甲基酚 化二氯甲基酚 化二氯甲基酚 化二氯甲基酚 化二氯甲基酚 化二氯甲基酚 化氯甲基酚 化氯甲基酚 化氯甲基酚 化二氯甲基酚 化氯甲基甲基酚 化二氯甲基酚 化二氯甲基酚 化氯甲基甲基酚 化氯甲基甲基酚 化氯甲基酚 化氯甲基甲基酚 化氯甲基甲基酚 化氯甲基酚 化氯甲基酚 化氯甲基酚 化二氯甲基甲基酚 化氯甲基甲基酚 化氯甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基	Tare Weight: 26720 15 08:30 8M 06/05/
DE SW HAULERS PERMITABETS 077	
Oriver (TYPE OR MRINT CLEARLY)	Net Weight: × 7 7
	nicked up at the above described generator address without
noident and will be delivered. Amout supering of a	picked up at the above described generator address without my kind.
Driver Signature	Date: (2-4-70)
DECTIBLATION	
DESTINATION hereby certify that the polyellescript hererials w	as delivered to Clean Earth of New Castle, Inc. at 94 Pyles
Land, New Castle, Delayay	海内的基础上标识别的 化自动流流 化异丙烯环烷 电影 化二甲基乙二甲基乙二甲基乙二甲基乙二甲基乙二甲基乙二甲基乙二甲基乙二甲基乙二甲基乙
river Signature: ////////////////////////////////////	Date: 6-5-98
hareby certify that the above described material has	been accepted at Clean Earth of New Castle, Inc. at 94 Pyles
Lane, New Castle, Delaware	10-5-98

of New Castle, Inc.	94 Pyles Lane • P.O. Box 1049 • New Castle, DE 19720-1049
PROVAL NUMBER:	Telephone: (302) 427-6633 ♥ Fax: (302) 427-6634
CONTAMINATED	SOIL PROFILE SHEET
Name: U.S. Arm	y Fort Monmouth
17 17 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0	Public Works, Bldg. 173, SELFM
	State: NJ zip Code: 07703
· · · · · · · · · · · · · · · · · · ·	Fallon Telephone: 732-532-
	1911011 1elephone. 192 USE
Company Name:	w Jarsay, Inc Telephone: \$ 609-727-
Address: P.O. Box 67, A	Jarsay Inc Telephone: 3009-121
1	_ :
	State:
	+ Monmouth, Charles Wood Gr
•	State: NJ Zip Code: 07703
Existing Site Land Use: /////	ary Installation How Many Years: 56
Previous Site Land Uses And Years	Each: Farm land
is this Site a State or Federal Superfu	und Site: Yes No
il Description Source of Contamination (UST or O	ther): Non-PCB Isanoformers
Estimated Volume of Soil:	Tons 250 Cubic Yards
Type of Contamination (Gas, Kero, #2	. #4. #6 Oil, Etc.): Clertrical Oil
If Contamination is Other Than Above	
Is a Soil Analysis Attached to this I	INCO
ste Composition (identify all components	
C = 0.36 5 Soul	<u>99.63</u> = <u>*</u>
OCB =0.014%	= <u>%</u> <u>%</u>
Cert	tification
sereby certify that the above information is	a true and accurate description to the best of
knowledge of the material we intend to sh	nip to Clean Earth of New Castle Inc.
ned: Sceph 11. Fallor	Date: 4/16/98



94 Pyles Lane • P.O. Box 1049 • New Castle, DE 19720-1049 Telephone: (302) 427-6633 • Fax: (302) 427-6634

APPROVAL NUMBER:

### NON-HAZARDOUS WASTE CERTIFICATION SHEET

### PCB Certification

I, the undersigned, under penalty of law, do hereby certify that the material to be submitted for thermal treatment at Clean Earth of New Castle, Incs facility does not contain polychlorinated biphenols (PCBs) at concontration greater than 40 ppm and was not derived from a source containing PCB's at a concentration greater than 50 ppm as derined in 40 CFR 761.

### Herbicide/Pesticide Certification

I, the undersigned, under ponalty of law , do hereby certify that the material to be submitted for thermal treatment at Clean Earth of New Castle, Inc.'s facility does no contain Herbicides or Pesticides at concentrations that would render It a hazardous waste as defined in 40 CFR 261.

#### Non-Hazardous Waste Certification

I, the undersigned under penalty of law, do hereby certify that the material to be submitted for thermal treatment at Clean Earth of New Castle. Inc.'s facility is not a listed hazardous waste, nor does it contain a listed hazardous waste, nor does it exhibit any of the characteristics of a hazardous waste as defined in 40 CFR 261.

The undersigned also acknowledges they have used dud alligence in determining the Non-Hazardous status. of the said material, as defined in 40 CFR. Should at any time after delivery, the material accepted by Closn Earth of New Castle, Inc. he found nonconforming to the above, it becomes the responsibility of the Generator/Agent to remove the waste from Clean Earth of New Castle, Inc.'s property within five (5) days of notification (notification is to be verbal followed by written notification, overnight receipted). It is the Generator/Agent's responsibility to acide by all Federal, State, and Local regulations associated with the removal of their waste. If the waste is not removed within the specified time period, said disposal shall be arranged by a Clean Earth of New Castle. Inc. representative and billed to the Generator/Agent at cost plus basis. Furthermore the Generator/Agent will be responsible for any and all costs for decontamination required at Clean Earth of New Castle, Inc.'s facility, that is related to the Generator/Agents's material and all liability for such nonconforming waste shall revert to the Generator/Agent.

US A my Fort Mo	on behalf of:
Joseph M. Fallon GENERATOR NAME	Environmenta Scientis
print name people m. Fallon	TITLE 4/16/98
AUTHORIZED SIGNATURE	DATE
MGP Certification	
sites that contain MGP waste, the undersigned further certifies that characterized with the oversight of the appropriate regulatory agen	cy and that Clean Earth of New Castle is an

acceptable form of treatment for the MGP coal distillate contaminated soil. For sites that are NPL sites, this section must be completed by the appropriate regulatory agent.

PRINT NAME	COMPANY(AGENCY)	TITLE
AUTHORIZED SIGNATURE		DATE
REGULATOR	(check one) GENERATOR	DESIGNATED AGENT

An Equal Opportunity Employer

94 Pyles Lane New Castle, DE 19720 (302) 427-6633

INCOMING LOAD TICKET

8.03 AM ne 39981 ficket# proval # 980139 Net Tons Type of Material Gross Tare 26,720 25.42 IN PCB MINERAL OIL 77,560 4 1 ID# 618 JANET W. ELLIOTT Signature # of Lading# ÷ŧ# 016 ifest\* ans. ID\* TAT TRUCKING, INC. DE-SW Permit# 077 ansporter frans. Addr. 3482 WRANGLE HILL ROAD BEAR, DE 19701 HOWLAND Truck # )river stomer eco-tron new Jersey, inc. U.S. ARMY, FORT MONMOUTH **Jenerator** nerator Site CHARLES WOOD AREA FORT MONMOUTH, NJ 09057 TAHER GINWALA 609-893-7873 ntact 1

675798

Contact 2

HOTES 2: